Adjuster Report Page 1 of 5

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20006838/AGS3Q2

Date: 13/04/2021

**REFERENCE** 

India International Insurance Pte Handling Insurer: Ltd

D19MPC0004171

Claimant

SJY6973C

**Insured Vehicle** No:

**SLR7829T** 

Vehicle No: Date of Loss:

29/06/2020

Nature of Claim: TP Claim No:

L30A26L

MPC2020D0001221

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SJY6973C

Make & Model: PERODUA VIVA, 989cc ELITE GX (A)

Engine No: 24/09/2010 (Man. Year: 2010) Chassis No: PM2L251S002102531

Colour: Orange 989 cc

Odometer: 176041 km

**Engine Capacity:** Market Value/New Car

Price:

Reg. Date:

N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: No

**CONDITION OF TYRES** 

Front Tyre Size: 165/60 R14 165/60 R14 Rear Tyre Size: Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		1,000.00		
Nett Amount (S\$)	0.00	1,000.00	-1,000.00	

**INSPECTION** 

Date of Assignment: 30/06/2020

Date Inspected: 30/06/2020 Inspected At: Advance Auto Garage

10 Kaki Bukit Road 2, #01-21 First

**East Centre** Singapore 417868

Estimated Period of Repair: 0.0 days

Adjuster: ADRIAN LING Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 5

Adjuster Report Page 3 of 5

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE: \$4,400.00

LTA REIMBURSEMENT VALUE (RV): \$3,400.00

NETT VALUE: \$1,000.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

Adjuster Report Page 4 of 5

## **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Jun 2020)

Parts: 144 PERODUA VIVA 989cc ELITE GX (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJY6973C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >