Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20006841/KGS3Q2

Date: 02/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 1900106137 Policy No: Claimant SHD5596Z Insured Vehicle No: SBT26Y Vehicle No:

Date of Loss: 26/06/2020 Nature of Claim: ΤP Claim No: 7062564682SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHD5596Z Reg No:

Make & Model: TOYOTA PRIUS, 1.8 (A) Engine No: 2ZR2B97855

Chassis No: Reg. Date: 11/01/2019 (Man. Year: 2018) JTDKB3FU003079053

Colour: Metallic Pearl White/Red Odometer: 103288 km

Engine Capacity: 1798 cc Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Sailun 9 mm Rear Left Side: Goodyear 3 mm Front Right Side: Rear Right Side: Goodyear 3 mm Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,598.27	432.22	9,166.05	95.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,950.00	300.00	13,650.00	97.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,548.27	732.22	22,816.05	96.89
+ GST 7.00/7.00% (S\$)	1,648.38	51.26	1,597.12	96.89
Nett Amount (S\$)	25,196.65	783.48	24,413.17	96.89
+ Loss of Use (2.0 x S	\$\$50.00/day) (S\$)	100.00		
+ Car Rental (2.0 x S	\$\$96.30/day) (S\$)	192.60		
+ Doc	/Search Fee (S\$)	7.45		
N	lett Liability (S\$)	1,083.53		

INSPECTION

30/06/2020 Date of Assignment:

Trans-cab Auto Services Pte Ltd Date Inspected: 30/06/2020 Inspected At:

No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG Manager: Chong Pui Lin Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

\sim		٦m	mei	റ	$\Delta \alpha$	$\mathbf{\nu}$	rte
١,	てしし	JIII		пu	CU	1 0	ม เอ

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Serviceable	442.60 FL	*- FL
2	1		*REAR BUMPER RE-INFORCEMENT	Repair	332.70 FL	*-FL
3	1		*REAR BUMPER TOWING COVER	Serviceable	15.40 FL	*- FL
4	1		*GUARD,REAR BUMPER,CENTER	Dented/Cut	576.30 FL	*576.30 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	116.50 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	117.70 FL	*- FL
7	1		*REAR TAILGATE	Repair	1,147.80 FL	*- FL
8	1		*REAR TAILGATE OUTER GARNISH	Serviceable	925.60 FL	*- FL
9	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	372.30 FL	*- FL
10	1		*PANEL SUB-ASSY,BODY LOWER BACK	Repair	650.30 FL	*- FL
11	1		*TAILLAMP LOWER RH	Serviceable	502.00 FL	*- FL
12	1		*TAILLAMP UPPER RH	Serviceable	451.80 FL	*- FL
13	1		*REAR BUMPER SIDE RH	Serviceable	123.70 FL	*- FL
14	1		*REAR BUMPER SIDE LH	Serviceable	123.70 FL	*- FL
15	1		*TAILLAMP LOWER LH	Serviceable	502.00 FL	*- FL
16	1		*TAILLAMP UPPER LH	Serviceable	443.30 FL	*- FL
17	1		*COVER,DECK TRIM,REAR	Serviceable	126.70 FL	*- FL
18	1		*COVER,FLOOR UNDER,NO 1	Serviceable	175.10 FL	*- FL
19	1		*COVER,FLOOR UNDER,NO 2	Serviceable	241.90 FL	*- FL
20	1		*COVER,REAR FLOOR	Serviceable	229.90 FL	*- FL
21	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
22	1		*SET REAR BUMPER CLIP	Not Necessary	69.00 FS	*- FS
23	1		*REAR TAILGATE TOYOTA LOGO	Not Necessary	47.00 FS	*- FS
24	1		*REAR TAILGATE WORDING PRIUS	Not Necessary	52.90 FS	*- FS
25	1		*REAR TAILGATE WORDING HYBRID	Not Necessary	53.50 FS	*- FS
26	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
27	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*-FS
28	1		*REAR BUMPER PROTECTOR	Not Necessary	120.00 FS	*- FS
29	1		*REAR WHEEL RIM	Serviceable	1,879.40 FS	*-FS
30	1		*REAR TYRE 195/65/15	Serviceable	350.00 FS	*- FS
31	1		*REAR WHEEL RIM COVER	Serviceable	211.50 FS	*- FS
32	1		*REAR RH BUMPER RETAINER CLIP	Not Necessary	38.00 FS	*- FS
33	1		*REAR LH BUMPER RETAINER CLIP	Not Necessary	38.00 FS	*- FS
34	1		*SET TAILLAMP LOWER CLIP	Not Necessary	33.00 FS	*- FS
35	1		*SET TAILLAMP UPPER CLIP	Not Necessary	33.00 FS	*-FS
36	1		*REAR LICENCE PLATE WITH MOULDING	Not Necessary	100.00 FS	*- FS
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	11,502.60	576.30
- List Item Discount on L Items 25.00/25.00% (S\$)				1,904.33	144.08	
				Total Parts (S\$)	9,598.27	432.22

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Labour Items 1 TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS New 170.00 AND PERFORM WATER SEEPAGE TEST 2 TO TRANSFER OF REAR BUMPER New 170.00 FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST 3 TO TRANSFER OF REAR END PANEL New 170.00 FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST 4 PANEL BEATING,KNOCKING AND STRAIGHTENING THE New 6,000.00 NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	Amount
AND PERFORM WATER SEEPAGE TEST TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST PANEL BEATING,KNOCKING AND STRAIGHTENING THE New 6,000.00 NECESSARY PORTION,REMOVE AND RENEWAL OF	
FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST 3 TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST 4 PANEL BEATING,KNOCKING AND STRAIGHTENING THE New 6,000.00 NECESSARY PORTION,REMOVE AND RENEWAL OF	0.00
FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST 4 PANEL BEATING,KNOCKING AND STRAIGHTENING THE New 6,000.00 NECESSARY PORTION,REMOVE AND RENEWAL OF	0.00
NECESSARY PORTION, REMOVE AND RENEWAL OF	0.00
	80.00
5 LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE New 380.00 ON JIG BENCH, TO FACILITATE REPAIR	0.00
6 TO RUST-PROOFING OF THE AFFECTED AREAS New 170.00	0.00
7 TO REINSTALL REAR BUMPER PARKING SENSOR New 170.00	0.00
8 TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING New 170.00	0.00
9 TO CHECK ELECTRICAL LIGHTING CONCERNED New 170.00	0.00
10 TO REMOVE AND REFIT INTERIOR New 380.00 FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	0.00
11 PUTTY AND SPRAY PAINTING OF THE AFFECTED New 6,000.00 PORTION	220.00
Gross Labour Cost (S\$) 13,950.00	300.00
Report was unsubmitted during this print-out.	

< END OF ESTIMATES >