

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20006843/QEA3Q2**Date:** 08/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993918
Claimant Vehicle No :	GBJ8941E	Insured Vehicle No :	SLX7766J
Date of Loss:	17/06/2020	Nature of Claim:	TP
		Claim No:	5292754748SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ8941E		
Make & Model:	TOYOTA REGIUSACE DX, 2.8 (A)	Engine No:	1GD8439186
Reg. Date:	25/09/2019 (Man. Year: 2019)	Chassis No:	GDH2011026979
Colour:	Silver	Odometer:	28945 km
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,622.90	2,294.95	327.95	12.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	710.00	470.00	240.00	33.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,332.90	2,764.95	567.95	17.04
+ GST 7.00/7.00% (S\$)	233.30	193.55	39.75	17.04
Nett Amount (S\$)	3,566.20	2,958.50	607.70	17.04
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	30/06/2020	
Date Inspected:	01/07/2020 Inspected At:	Carz Auto Services Pte Ltd - Woodlands (HQ) NO 61, WOODLANDS INDUSTRIAL PARK E9, #04-04 E9 PREMIUM SINGAPORE 757047 Singapore 757047
Estimated Period of Repair:	3.0 days	

Adjuster: OI SUN PIN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Crumpled	495.80 FL	*495.80 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	210.30 FL	*- FL
3	1		*FRONT BUMPER FOG LAMP COVER LH	Serviceable	185.90 FL	*- FL
4	1		*FRONT HEAD LAMP LH	Scratched	2,510.80 FL	*2,510.80 FL
5	10		*FRONT BUMPER CLIP LH	Necessary	55.00 FS	*30.00 FS
6	2		*FRONT HEAD LAMP CLIP LH	Necessary	15.80 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,473.60	3,046.60
- List Item Discount on L Items 25.00/25.00% (\$)	850.70	751.65
Total Parts (\$)	2,622.90	2,294.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRONT DAMAGED PARTS REPLACE REALIGNED ALIGNED ALL PARTS	New	400.00	200.00
2	TO RESPRAY AFFECTED AREAS	New	250.00	250.00
3	TO REMOVE/REFIX WIRING CHECKS	New	60.00	20.00
Gross Labour Cost (\$)			710.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >