

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20006845/ATF3E2

Date: 02/02/2021

REFERENCE

Insured/Claimant:	AU KHENG SHENG	Policy No:	1800039616-01	
Date of Loss:	20/06/2020	Nature of Claim:	OD	Claim No: 6535457997SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS211C	Engine No:	CYG020047
Make & Model:	AUDI A6, 1.8 TMU (A)	Chassis No:	WAUZZZ4G5HN114239
Reg. Date:	16/04/2018 (Man. Year: 2017)	Odometer:	27261 km
Colour:	Bronze		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R19	Rear Tyre Size:	225/40 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,062.64	19,146.56	13,916.08	42.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,792.00	7,112.00	6,680.00	48.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,854.64	26,258.56	20,596.08	43.96
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	46,054.64	25,458.56	20,596.08	44.72
+ GST 7.00/7.00% (S\$)	3,223.82	1,782.10	1,441.72	44.72
Nett Amount (S\$)	49,278.46	27,240.66	22,037.80	44.72

INSPECTION

Date of Assignment:	01/07/2020		
Date Inspected:	07/07/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	9.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	2,877.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	511.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	120.00 FS	*- FS
4	14		*LOCKING CLIP	Not Necessary	52.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Deformed	889.00 FS	*711.20 FS
6	1		*RADIATOR GRILLE COVER	Not Necessary	34.00 FS	*- FS
7	1		*SUPPORT FRAME	Dented	3,660.00 FS	*2,928.00 FS
8	1		*ASSEMBLY CARRIER STRUT BRACE	Not Necessary	182.00 FS	*- FS
9	1		*STEERING GEAR	Damaged	6,388.00 FS	*5,110.40 FS
10	1		*ANTI ROLL BAR	Bent	467.00 FS	*392.00 FS
11	1		*ANTI ROLL BAR RUBBER BUSH	Necessary	13.00 FS	*10.24 FS
12	2		*ENGINE UNDERSHIELD - FRONT / REAR	Torn	1,196.00 FS	*956.80 FS
13	1		*UNDERBODY TRIM - LH	Not Necessary	138.00 FS	*- FS
14	1		*UNDERBODY TRIM - LH / RH	O/S torn	630.00 FS	*302.40 FS
15	2		*UNDERBODY TRIM - LH / RH	Not Necessary	356.00 FS	*- FS
16	1		*REAR SILENCER - LH	Not Necessary	1,216.00 FS	*- FS
17	1		*REAR SILENCER DUAL CLIP	Not Necessary	55.00 FS	*- FS
18	1		*REAR SILENCER BRACKET	Not Necessary	54.00 FS	*- FS
19	1		*REAR SILENCER - RH	Not Necessary	1,216.00 FS	*- FS
20	1		*REAR SILENCER DUAL CLIP	Not Necessary	55.00 FS	*- FS
21	1		*REAR SILENCER BRACKET	Not Necessary	54.00 FS	*- FS
22	1		*CENTRE SILENCER	Dented	920.00 FS	*772.40 FS
23	1		*CENTRE SILENCER DUAL CLIP	Necessary	57.00 FS	*46.32 FS
24	2		*CENTRE SILENCER DUAL CLIP	Necessary	109.00 FS	*89.92 FS
25	1		*FRONT BUMPER CLOSING ELEMENT	Missing	206.00 FS	*172.80 FS
26	1		*FRONT NUMBER PLATE	Not Necessary	60.00 FS	*- FS
27	1		*SUNDRIES	Necessary	400.00 FS	*334.24 FS
28	1		*REAR SUBFRAME	Bent	3,330.00 FS	*2,664.00 FS
29	1		*FUEL TANK ASSY	Cut	5,627.00 FS	*4,501.60 FS
30	1		*SEAL RING FOR FUEL TANK ASSY	Necessary	92.00 FS	*73.60 FS
31	1		*HEAT SHIELD FOR TUNNEL	Not Necessary	198.00 FS	*- FS
32	1		*RADIATOR GRILLE	Not Necessary	1,820.00 FS	*- FS
33	1		*BOLTS FOR REAR SUBFRAME	Necessary	80.64 FS	*80.64 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **33,062.64** **19,146.56**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORN, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
2	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	2,400.00	2,400.00
3	TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
4	TO RESPRAY FRONT BUMPER AND FRONT BUMPER SPOILER	New	2,000.00	300.00
5	TO REMOVE AND RENEW BOTH REAR EXHAUST SILENCER AND CENTRE SILENCE. TO ALIGN POSITION	New	480.00	480.00
6	TO CARRY OUT WHEEL ALIGNMENT	New	240.00	240.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO REMOVE AND REINSTALL EXHAUST SYSTEM AND REAR SUSPENSION ASSY/ RENEW ACCORDINGLY	New	2,400.00	2,400.00
9	TO REMOVE AND RENEW FUEL TANK ASSY	New	600.00	600.00
10	TO REMOVE AND REINSTALL INTERIOR FLOOR CARPET, CENTRE CONSOLE, FRONT SEATS, REAR SEATS, BACK REST AND HAT TRAYS TO FACILITATE REPAIRING OF FLOOR PAN	New	1,800.00	0.00
11	TO WELD AND REPAIR FLOOR PAN	New	1,000.00	0.00
12	TO RESPRAY FLOOR PAN	New	1,000.00	0.00
Gross Labour Cost (\$\$)			13,792.00	7,112.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >