

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20006846/AQF3E2

Date: 15/12/2020

REFERENCE

Insured/Claimant:	PRASHANTH RAO PEJAVAR	Policy No:	1900252286	
Date of Loss:	23/05/2020	Nature of Claim:	OD	Claim No: 1494160389SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGE8116M	Engine No:	CZD886615
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF33L1015705
Reg. Date:	29/11/2019 (Man. Year: 2019)	Odometer:	3541 km
Colour:	Blue		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$135,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,264.00	4,078.40	3,185.60	43.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	4,252.00	2,602.00	1,650.00	38.81
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,516.00	6,680.40	4,835.60	41.99
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	10,716.00	5,880.40	4,835.60	45.13
+ GST 7.00/7.00% (S\$)	750.12	411.63	338.49	45.12
Nett Amount (S\$)	11,466.12	6,292.03	5,174.09	45.13

INSPECTION

Date of Assignment:	01/07/2020		
Date Inspected:	01/07/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LID	Dented	3,305.00 FS	*2,644.00 FS
2	1		*PACKING ADHESIVE	Necessary	18.00 FS	*14.40 FS
3	1		*REAR LID ATTACHMENT PARTS	Not Necessary	354.00 FS	*- FS
4	1		*REAR LID LOCK	Not Necessary	232.00 FS	*- FS
5	1		*REAR LID STRIKER PLATE	Not Necessary	63.00 FS	*- FS
6	1		*LID LOCK PUSH BUTTON	Not Necessary	1,267.00 FS	*- FS
7	1		*AUDI EMBLEM	Necessary	117.00 FS	*93.60 FS
8	1		*Q3 INSCRIPTION	Necessary	90.00 FS	*72.00 FS
9	1		*REAR WINDSCREEN	Necessary	901.00 FS	*720.80 FS
10	1		*PRIMER	Necessary	19.00 FS	*15.20 FS
11	2		*REAR SPOILER - LH / RH	Necessary	398.00 FS	*318.40 FS
12	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
13	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					7,264.00	4,078.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY	New	480.00	480.00
2	TO RENEW REAR WINDSCREEN TO FACILITATE REAR LID RENEWAL	New	480.00	480.00
3	TO INSTALL REAR WINDSCREEN SOLAR FILM	New	400.00	400.00
4	TO DISMANTLE AND RENEW REAR LID. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
5	TO RESPRAY REAR LID	New	1,500.00	550.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,252.00	2,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >