

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006853/QES3Q2

Date: 06/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800067417

Claimant
Vehicle No : SLF7840Y **Insured Vehicle No :** SMA4873L

Date of Loss: 29/06/2020 Nature of Claim: TP Claim No: 3362433943SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF7840Y		
Make & Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6AT (A)	Engine No:	P520375759
Reg. Date:	09/09/2016 (Man. Year: 2016)	Chassis No:	JM6BM42A8G0346674
Colour:	Black	Odometer:	203767 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,863.88	889.20	974.68	52.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	550.00	450.00	45.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,863.88	1,439.20	1,424.68	49.75
Approved Total (Overridden) (S\$)		1,150.00		
(S\$)	2,863.88	1,150.00	1,713.88	59.84
+ GST 7.00/7.00% (S\$)	200.47	80.50	119.97	59.84
Nett Amount (S\$)	3,064.35	1,230.50	1,833.85	59.84
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,417.95		

INSPECTION

Date of Assignment: 01/07/2020

Date Inspected: 02/07/2020 Inspected At:

Lion City Rentals Pte Ltd (HQ)
60 Jalan Lam Huat, #04-01 Carros
Centre
Singapore 737869

Estimated Period of Repair: 2.0 days

Adjuster: OI SUN PIN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crumpled	1,129.00 FL	*1,074.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Serviceable	564.20 FL	* - FL
3	1		*REVERSE SENSOR	Not Necessary	240.00 FS	* - FS
4	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
					Sub Total (\$\$)	2,033.20
					- List Item Discount on L Items 10.00/20.00% (\$\$)	169.32
					Total Parts (\$\$)	1,863.88
						889.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REMOVING REAR BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	500.00	250.00
2	TO RESPRAY REAR BUMPER	New	500.00	300.00
Gross Labour Cost (\$\$)			1,000.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >