

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20006855/R1DA3Q2

Date: 26/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900248453

Claimant
Vehicle No : SLW7458D **Insured Vehicle No :** SMQ5183D

Date of Loss: 30/06/2020 Nature of Claim: TP Claim No: 6379283036SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW7458D	Engine No:	HIDDEN
Make & Model:	VOLKSWAGEN PASSAT B8, 1.8 TFSI (A)	Chassis No:	WVWZZZ3CZJE119179
Reg. Date:	28/02/2018 (Man. Year: 2018)	Odometer:	23419 km
Colour:	Black		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,303.02	5,823.03	2,479.99	29.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,710.00	9,110.00	6,600.00	42.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	24,013.02	14,933.03	9,079.99	37.81
+ GST 7.00/7.00% (\$\$)	1,680.91	1,045.31	635.60	37.81
Nett Amount (\$\$)	25,693.93	15,978.34	9,715.59	37.81
+ Car Rental (8.0 x S\$120.00/day + 7.00% GST) (\$\$)		1,027.20		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		17,007.54		

INSPECTION

Date of Assignment: 01/07/2020

Date Inspected: 01/07/2020 Inspected At: Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 9.0 days

Adjuster: MOHD RASUL

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID	Bent	2,284.21 FS	*2,284.21 FS
2	1		*DECKLID WEATHERSTRIP BLAC	Serviceable	305.17 FS	*- FS
3	1		*INSCRIPTION BRIGHT CHROME NAME PLATE (PASSAT)	Necessary	64.62 FS	*64.62 FS
4	1		*COVER PRIMED REAR BUMPER	Deformed	1,517.27 FS	*1,517.27 FS
5	1		*SPOILER PRIMED	Deformed	246.17 FS	*246.17 FS
6	1		*BUMPER REINFORCEMENT	Bent	526.12 FS	*526.12 FS
7	1		*ATTACHMENT STRIP BUMPER CENTRE BRACKET	Cracked	57.47 FS	*57.47 FS
8	1		*GUIDE TAIL LIGHT LOWER BRACKER LH	Serviceable	21.23 FS	*- FS
9	1		*GUIDE TAIL LIGHT LOWER BRACKER RH	Necessary	21.23 FS	*21.23 FS
10	5		*POP -RIVET	Necessary	5.45 FS	*5.45 FS
11	1		*GUIDE PIECE BUMPER SIDE BRACKET LH	Serviceable	36.59 FS	*- FS
12	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Necessary	36.59 FS	*36.59 FS
13	10		*POP-RIVET	Necessary	11.40 FS	*11.40 FS
14	1		*SET SENSOR BRACKETS	Necessary	42.59 FS	*42.59 FS
15	1		*2K-PLASTIC ADHESIVE	Necessary	75.94 FS	*75.94 FS
16	1		*BONDING AGENT FOR PLASTIC	Necessary	59.40 FS	*59.40 FS
17	1		*DECORATION MOULDING BRIGHT BUMPER LOWER CENTRE MLDG CHROM	Cut	211.12 FS	*211.12 FS
18	1		*DECORATIVE MOULDING BRIGH BUMPER LOWER MLDG CHROM LH	Serviceable	162.35 FS	*- FS
19	1		*DECORATIVE MOULDING BRIGH BUMPER LOWER MLDG CHROM RH	Cut	162.35 FS	*162.35 FS
20	1		*LED LICENCE PLACE LIGHT	Serviceable	93.80 FS	*- FS
21	1		*REFLECTOR RHS REFLECTOR INNER	Cracked	64.27 FS	*64.27 FS
22	1		*REFLECTOR RHS REFLECTOR OUTER	Cracked	64.27 FS	*64.27 FS
23	1		*END PLATE END PANEL INNER	Serviceable	949.79 FS	*- FS
24	1		*LOCK CARRIER END PANEL OUTER	Serviceable	379.75 FS	*- FS
25	1		*ZINC SPRAY	Not Necessary	62.88 FS	*- FS
26	1		*2K-BODY ADHESIVE	Not Necessary	406.76 FS	*- FS
27	1		*SEALANT CAN BE SPRAYED	Not Necessary	61.67 FS	*- FS
28	1		*SOUND ABSORBER LAMINATED FLOOR PAN INSULATOR	Necessary	41.40 FS	*41.40 FS
29	1		*UNDERBODY LINING FLOOR PAN LOWER COVER	Deformed	251.16 FS	*251.16 FS
30	1		*REAR NUMBER PLATE	Bent	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 8,303.02 5,823.03

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	6,720.00	3,360.00
2	SPRAY PAINT	New	6,400.00	4,000.00
3	TRANSFER BOOT LID MECHANISM	New	840.00	420.00
4	R&R REAR LUGGAGE TRIM	New	840.00	420.00
5	REAR WATER LEAK TEST	New	150.00	150.00
6	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
7	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
Gross Labour Cost (\$\$)			15,710.00	9,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >