



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

AXA INSURANCE PTE LTD	Ref : CC6/AXA14020008/Kpa3s2-1
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: YVONNE ANG	Date : 07-07-2020  Code : AXA2



**1. Policy Particulars :- THIRD PARTY CLAIM**

<b>Insured Veh.</b> GT 8992X	<b>Veh. Inspected</b> SDV 9535B
<b>Policy No.</b> VFX/P1002314	<b>Coverage (\$)</b> 0.00
<b>Claim No.</b> C0321240	<b>Excess (\$)</b> 0.00
<b>Assign From</b>	<b>Assign Date</b> 23/10/2014

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b> HYUNDAI MATRIX (A)	<b>c.c</b> 1599
<b>Engine No.</b> HIDDEN	<b>Year of Reg.</b> 2007
<b>Chassis No.</b> KMHPN81CR7U289494	<b>Colour</b> METALLIC GREEN
<b>Odometer</b> 195719	<b>Steering</b> IN ORDER
<b>Brakes</b> IN ORDER	<b>Modification</b> STANDARD ALLOY RIM
<b>General</b> GOOD	

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>	185/65 R19	MICHELIN	9 mm
<b>L/H Front Tyre</b>	185/65 R19	MICHELIN	9 mm
<b>R/H Rear Tyre</b>	185/65 R19	MICHELIN	9 mm
<b>L/H Rear Tyre</b>	185/65 R19	MICHELIN	9 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY.  
DAMAGES SEE DETAILS.

**5. General Information**

<b>Accident Date</b> 20/10/2014	<b>Inspection Date</b> 23/10/2014
<b>Survey held at</b> AUTOEXCEL ENGINEERING PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722	

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDV 9535B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT LH DOOR (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	FRONT LH DOOR PROTECTOR (CONSISTENT)	SCRATCHED	68.59	68.59
1	REAR LH DOOR (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	REAR LH DOOR PROTECTOR (CONSISTENT)	SCRATCHED	68.59	68.59
1	REAR LH FENDER (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	REAR LH WHEELHUB BEARING (CONSISTENT)	BENT / NECESSARY	420.00	420.00
1	REAR LH SHOCK ABSORBER (CONSISTENT)	SERVICEABLE	385.00	-
	LESS 20% DISCOUNT		-188.44	-111.44
			753.74	445.74
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR LH RIM (SN) (CONSISTENT)	DENTED	380.00	280.00
			380.00	280.00
	<b><u>LABOUR</u></b>			
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT LH DOOR, REAR LH DOOR, REAR LH FENDER AND REAR BUMPER.		700.00	360.00
	TO DO SPRAY PAINTING ON ACCIDENT AREA.		900.00	600.00
	TO REPLACE REAR UNDERCARRIAGE DAMAGE PARTS.		120.00	60.00
	TO DO WHEEL COMPUTER ALIGNMENT.		60.00	60.00
	ANTI RUST.	NOT NECESSARY	60.00	-
	REMOVE, REFIX, GARNISH, DOOR TRIM BOARD, UPHOLSTERY ETC.	NOT NECESSARY	120.00	-
	CHECKING WIRING SYSTEM.		30.00	15.00
			1,990.00	1,095.00
<b>GRAND TOTAL</b>			<b>3,123.74</b>	<b>1,820.74</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,450.00
---	--	--	----------

Report Ref No. CC6/AXA14020008/Kha3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.