

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 INV No. AC2005999

INV Date 02/09/2020

Reference CC4/LPC20006866/Kba3n2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SKQ 4218T

Insured Veh. SKU 2361D

Claim No. 19/20/20/VP05/023435

Policy No. Z19VP05023921

Accident Date 30/06/2020

Inspection Date 01/07/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

HYN



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile				
LONF	IPAC INSURANCE BHD Ref : CC4/LPC20006866/Kba3n2			6/Kba3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date: 02-09-2020 Code: LPC2			
1.		Policy Particulars	:- THIRD PARTY CLAIM		
	Insured Veh.	SKU 2361D	Veh. Inspected	SKQ 4218T	
	Policy No.	Z19VP05023921	Coverage (\$)	0.00	
	Claim No.	19/20/20/VP05/023435	Excess (\$)	0.00	
	Assign From	GERALD	Assign Date	01/07/2020	
2.		Vehicle Partic	culars & Condition		
	Make & Model	KIA FORTE K3 (A)	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	KNAFX411MF5330532	Colour	METALLIC GREY	
	Odometer	64836	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.		Conditie	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	YOKOHAMA	9 mm	
	L/H Front Tyre	205/55 R16	YOKOHAMA	9 mm	
	R/H Rear Tyre	205/55 R16	YOKOHAMA	9 mm	
	L/H Rear Tyre	205/55 R16	YOKOHAMA	9 mm	
4.		•	on of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE REA	AR AND FRONT PORTION.		
	DAMAGES SEE D	ETAILS.			
5.		General	I Information		
	Accident Date	30/06/2020	Inspection Date	01/07/2020	
	Survey held at	HUI YANG MOTOR PTE LTD			
		BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a.		Re	emarks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	b. Estimate Days of Repair				
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	6 Working Days		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 4218T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT COVER	BENT	1,150.50	885.00
2	REAR BOOT COVER HINGE @\$69.50	TO REPAIR SEE LABOUR	139.00	-
1	REAR BOOT COVER "KIA" LOGO	NECESSARY	56.00	56.00
1	REAR BOOT COVER "FORTE" EMBLEM	NECESSARY	52.00	52.00
1	REAR BOOT COVER "K3" EMBLEM	NECESSARY	45.00	45.00
1	REAR BOOT COVER "C&C" LOGO	NECESSARY	55.00	55.00
2	REAR BOOT COVER SIDE REFECTOR @\$245.00	SERVICEABLE	490.00	-
1	REAR BOOT COVER INNER LOCK	DENTED	158.00	158.00
1	REAR BOOT COVER INNER TRIM	SERVICEABLE	205.00	-
1	REAR BUMPER	BENT	898.50	668.00
2	REAR BUMPER SIDE RETAINER @\$35.00	SERVICEABLE	70.00	-
2	REAR BUMPER SIDE REFECTOR @\$95.00	O/S CRACKED	190.00	95.00
1	REAR BUMPER DIFFUSED	DENTED	355.20	347.00
1	REAR BUMPER REINFORCEMENT	CRACKED	350.00	350.00
2	REAR BUMPER REINFORCEMENT SIDE BRACKET @\$55.00	BENT	110.00	110.00
5	REAR BUMPER REINFORCEMENT TOP & LOWER BRACKET @\$25.00	SERVICEABLE	125.00	-
2	REAR TAILLAMP @\$358.00	O/S SPLIT	716.00	358.00
2	REAR TAILLAMP LOWER BRACKET @\$35.00	SERVICEABLE	70.00	-
1	REAR END PANEL	BENT	480.00	480.00
1	REAR END PANEL INNER GARNISH	BUCKLED	150.50	150.50
1	FRONT BUMPER	TO REPAIR SEE LABOUR	950.25	-
1	FRONT BUMPER NUMBER GARNISH	DENTED	85.25	85.25
1	FRONT BUMPER SPONGE	SERVICEABLE	125.50	-
1	FRONT KIA LOGO	NECESSARY	56.00	56.00
1	FRONT CENTRE GRILLE	SERVICEABLE	485.50	-
	LESS 10% DISCOUNT		-756.82	-395.08
			6,811.38	3,555.67

Report Ref No. CC4/LPC20006866/Kba3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR BOOT COVER INNER RUBBER (50%)(SN)	DENTED / DISTORTED	120.00	60.00
	LESS 10% DISCOUNT		-12.00	-
			108.00	60.00
	SPECIAL NETT ITEMS			
1	SET REAR PARKING SENSOR (SN)	SHORTED	280.00	200.00
1	SET FRONT & REAR NUMBER & CASING (SN)	DENTED	100.00	90.00
			380.00	290.00
	<u>LABOUR</u>			
	TUFFKOTE.		150.00	60.00
	WIRING.		150.00	40.00
	SPRAY PAINTING.		1,400.00	800.00
	LABOUR CHARGE.INCLUSIVE OF THE REPAIR OF REAR BOOT COVER HINGE AND FRONT BUMPER.		1,400.00	700.00
			3,100.00	1,600.00
	GRAND TOTAL		10,399.38	5,505.67
		1	<u> </u>	
	RECOMMENDED COST OF LUMP SUM REPAIRS			4,400.00

Report Ref No. CC4/LPC20006866/Kba3n2

KONG SENG CHEONG

(TO ITS PRE-ACCIDENT CONDITION)

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKQ 4218T

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKQ 4218T

RE-INSPECTION













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKQ 4218T

RE-INSPECTION







