

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20006867/KRS3Q2**Date:** 08/02/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900106740
Claimant Vehicle No :	SHD497J	Insured Vehicle No :	SML8696Y
Date of Loss:	27/06/2020	Nature of Claim:	TP
		Claim No:	6280379096SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD497J		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C003273
Reg. Date:	03/07/2017 (Man. Year: 2016)	Chassis No:	VF1ABL15AUC283466
Colour:	Metallic White/Red	Odometer:	274742 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,620.43	5,622.38	16,998.05	75.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,820.00	1,780.00	14,040.00	88.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	38,440.43	7,402.38	31,038.05	80.74
+ GST 7.00/7.00% (S\$)	2,690.83	518.17	2,172.66	80.74
Nett Amount (S\$)	41,131.26	7,920.55	33,210.71	80.74
+ Car Rental (6.0 x S\$101.27/day) (S\$)		607.62		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,535.62		
Global Sum Settlement (S\$)		8,500.00		

INSPECTION

Date of Assignment:	30/06/2020		
Date Inspected:	30/06/2020	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Cracked	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Distorted	98.10 FL	*98.10 FL
4	1		*BUMPER BRACKET SIDE RH REAR	Distorted	82.10 FL	*82.10 FL
5	1		*BUMPER RETAINER RH REAR	Distorted	59.80 FL	*59.80 FL
6	1		*BUMPER REFLECTOR RH	Cracked	16.60 FL	*16.60 FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Bent	100.90 FL	*100.90 FL
13	1		*BUMPER BLOCK LH REAR	Serviceable	75.70 FL	*- FL
14	1		*BUMPER BLOCK RH REAR	Serviceable	76.50 FL	*- FL
15	1		*BUMPER HARNESS REAR	Serviceable	301.10 FL	*- FL
16	1		*BOOT REAR	Bent	1,677.20 FL	*1,677.20 FL
17	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
18	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- FL
19	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*- FL
20	1		*BOOT REFLECTOR LAMP RH	Cracked	277.70 FL	*277.70 FL
21	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
22	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
23	1		*BOOT STRUT LH	Serviceable	145.10 FL	*- FL
24	1		*BOOT STRUT RH	Serviceable	145.10 FL	*- FL
25	1		*BOOT HINGE LH	Repair	254.20 FL	*- FL
26	1		*BOOT HINGE RH	Repair	253.80 FL	*- FL
27	1		*BOOT TRIM BOARD	Serviceable	611.00 FL	*- FL
28	1		*BOOT LOCK	Repair	246.60 FL	*- FL
29	1		*BOOT LOCK CATCH	Repair	41.70 FL	*- FL
30	2		*BOOT RUBBER PLUG	Serviceable	139.30 FL	*- FL
31	1		*BOOT SWITCH	Serviceable	113.00 FL	*- FL
32	1		*BOOT LOCK LINKAGE HOLDER	Serviceable	99.50 FL	*- FL
33	2		*LICENCE PLATE LAMP	Serviceable	26.30 FL	*- FL
34	1		*TAILLAMP RH	Mtg Cracked	401.40 FL	*401.40 FL
35	1		*TAILLAMP PANEL RH	Repair	401.40 FL	*- FL
36	1		*TAILLAMP LH	Serviceable	401.40 FL	*- FL
37	1		*TAILLAMP PANEL LH	Repair	401.40 FL	*- FL
38	1		*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	*745.80 FL
39	1		*OUTER PANEL REAR (END PANEL) TRIM	Distorted	404.56 FL	*404.56 FL
40	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	1,229.40 FL	*- FL
41	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
42	1		*SPARE WHEEL PANEL BRACKET LH L70Y	Repair	70.60 FL	*- FL
43	1		*SPARE WHEEL PANEL BRACKET RH L70Y	Repair	69.20 FL	*- FL
44	1		*SPARE TYRE BOARD	Serviceable	680.90 FL	*- FL
45	1		*EXHAUST REAR	Repair	5,263.60 FL	*- FL
46	1		*EXHAUST CAP REAR	Repair	125.40 FL	*- FL
47	1		*FENDER PANEL REAR RH	Repair	1,933.20 FL	*- FL
48	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
49	1		*WHEELARCH REAR RH	Serviceable	275.40 FL	*- FL
50	1		*SET PARKING AID	Shorted	700.00 FS	*400.00 FS
51	1		*SET REAR BUMPER CLIP	Necessary	75.00 FS	*75.00 FS
52	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	40.00 FS	*- FS
53	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	40.00 FS	*- FS
54	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	45.00 FS	*- FS
55	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	40.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	45.00 FS	*- FS
57	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	55.00 FS	*- FS
58	1		*SET BUMPER LOWER REAR CLIP	Necessary	75.00 FS	*75.00 FS
59	1		*FENDER INNER TRIM CLIP RH	Not Necessary	45.00 FS	*- FS
60	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	45.00 FS	*- FS
61	2		*END PANEL SEAM SEALANT	Not Necessary	170.00 FS	*- FS
62	1		*SET BOOT FINISHER CLIP	Not Necessary	40.00 FS	*- FS
63	1		*BOOT STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
64	1		*EXHAUST MOUNTING REAR	Serviceable	40.00 FS	*- FS
65	1		*EXHAUST BRACKET REAR	Serviceable	40.00 FS	*- FS
66	1		*BOOT STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
67	1		*BOOT TRIM BOARD CLIP	Not Necessary	45.00 FS	*- FS
68	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
69	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS
70	1		*TAILLAMP CLIP RH	Necessary	35.00 FS	*5.00 FS
71	2		*REAR WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
72	1		*WINDSCREEN MOULDING	Not Necessary	190.00 FS	*- FS
73	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	120.00 FS	*- FS
74	1		*TAILLAMP CLIP LH	Not Necessary	35.00 FS	*- FS
75	1		*REAR BUMPER PROTECTOR	Not Necessary	150.00 FS	*- FS
76	1		*SET REAR LICENCE PLATE WITH HOLDER	Serviceable	120.00 FS	*- FS
77	1		*SET END PANEL INSULATION PAD	Serviceable	200.00 FS	*- FS
78	1		*SET REAR END PANEL TRIM CLIP	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,749.92	6,178.76
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,129.49	556.38
Total Parts (\$\$)	22,620.43	5,622.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	New	170.00	0.00
2	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	New	170.00	0.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	60.00
4	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	6,000.00	700.00
5	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	New	380.00	0.00
6	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
7	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	60.00
9	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
10	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	6,000.00	880.00
11	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	New	380.00	0.00
12	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
13	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	New	170.00	0.00
14	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
15	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
16	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	20.00
17	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	60.00
18	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
Gross Labour Cost (\$\$)			15,820.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >