

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20006873/GVF3E2

Date: 06/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

207009740

Claimant Vehicle No : PC8008X

Insured Vehicle No :

SMR8851J

Date of Loss: 02/04/2020

Nature of Claim:

TP

Claim No: 6788679726SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC8008X**

Make & Model: TOYOTA HIACE, 3.0 D High-roof 14 Seater (A)

Engine No: 1KD2202355

Reg. Date: 26/06/2012 (Man. Year: 2012)

Chassis No: JTFST22P800014094

Colour: White

Odometer: 0 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size:

195 R15

Front Left Side: Bridgestone 5 mm

Rear Left Side:

Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side:

Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 01/07/2020

Date Inspected: 01/07/2020 Inspected At:

160 Sin Ming Drive #01-12 Sin Ming

Autocity

Repairer : Msm Logistics Pte Ltd- Sin Ming (HQ)

Estimated Period of Repair: 24.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Missing	0.00 F	*- F
2	1		*FRT BUMPER	Missing	0.00 F	*- F
3	1		*FRT BUMPER LOWER GRILLE	Distorted	0.00 F	*- F
4	1		*FRT BUMPER BEAM	Bent	0.00 F	*- F
5	2		*FRT BUMPER BRACKET	Cracked	0.00 F	*- F
6	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
7	1		*FRT GRILLE	Missing	0.00 F	*- F
8	1		*FRT PANEL INNER	Buckled	0.00 F	*- F
9	1		*FRT BRACE PANEL	Bent	0.00 F	*- F
10	1		*FRT PANEL GARNISH INNER	Deformed	0.00 F	*- F
11	2		*FRT CORNER PANEL	Buckled	0.00 F	*- F
12	1		*FRT LH HEADLAMP ASSY	Distorted	0.00 F	*- F
13	1		*FRT RH HEADLAMP ASSY	Distorted	0.00 F	*- F
14	1		*WIPER PANEL GARNISH	Cut	0.00 F	*- F
15	1		*FRT WINDSCREEN	Cracked	0.00 F	*- F
16	1		*FRT WINDSCREEN RUBBER	Necessary	0.00 F	*- F
17	1		*FRT WINDSCREEN SEALANT	Necessary	0.00 F	*- F
18	2		*FRT WINDSCREEN OUTER PILLAR	Repair	0.00 F	*- F
19	1		*ERP BRACKET	Necessary	0.00 F	*- F
20	1		*FRT SUPPORT PANEL	Distorted	0.00 F	*- F
21	1		*BONNET	Buckled	0.00 F	*- F
22	1		*BONNET LOCK	Bent	0.00 F	*- F
23	1		*BONNET HINGE	Bent	0.00 F	*- F
24	1		*AIR CON CONDENSER	Bent	0.00 F	*- F
25	1		*AIR CON LIQUID PIPE	* Check	0.00 F	*- F
26	1		*RADIATOR	Bent	0.00 F	*- F
27	1		*RADIATOR COOLANT	Necessary	0.00 F	*- F
28	1		*RADIATOR FAN ASSY	Distorted	0.00 F	*- F
29	1		*RADIATOR EXPANSION TANK	Cracked	0.00 F	*- F
30	1		*OIL COOLER	* Check	0.00 F	*- F
31	1		*POWER STEERING COOLER PIPE	* Check	0.00 F	*- F
32	1		*AIR DUCT	Cut	0.00 F	*- F
33	1		*AIR CLEANER ASSY	Distorted	0.00 F	*- F
34	1		*ENGINE MOUNTING	* Check	0.00 F	*- F
35	1		*FRT LH CHASSIS MEMBER	Repair	0.00 F	*- F
36	1		*FRT RH CHASSIS MEMBER	Repair	0.00 F	*- F
37	1		*AIR CON EVAPORATOR ASSY	* Check	0.00 F	*- F
38	1		*AIR CON BLOWER	* Check	0.00 F	*- F
39	1		*STEERING WHEEL AIRBAG	Activated	0.00 F	*- F
40	1		*STEERING WHEEL AIRBAG SENSOR	Activated	0.00 F	*- F
41	1		*AIRBAG CONTROL UNIT	Activated	0.00 F	*- F
42	1		*FRT RH SEAT BELT ASSY	Activated	0.00 F	*- F
43	1		*FRT LH SEAT BELT ASSY	Activated	0.00 F	*- F
44	1		*DASHBOARD ASSY	* Check	0.00 F	*- F
45	1		*GLOVE BOX COVER	* Check	0.00 F	*- F
46	1		*GLOVE BOX COMPARTMENT	* Check	0.00 F	*- F
47	1		*FRT RH WHEEL COVER	Scratched	0.00 F	*- F
48	1		*FRT RH WHEEL RIM	* Check	0.00 F	*- F
49	1		*FRT RH TYRE	Scratched	0.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*FRT LH DOOR	Bent	0.00 F	*- F
51	2		*FRT LH DOOR HINGE	Bent	0.00 F	*- F
52	1		*FRT LH DOOR WING MIRROR	Broken	0.00 F	*- F
53	1		*FRT RH DOOR	Bent	0.00 F	*- F
54	2		*FRT RH DOOR HINGE	Bent	0.00 F	*- F
55	1		*FRT RH DOOR WING MIRROR	Broken	0.00 F	*- F
56	1		*FRT RH DOOR LOCK	* Check	0.00 F	*- F
57	2		*FRT DOOR FRT PILLAR	Bent	0.00 F	*- F
58	1		*FRT DOOR REAR PILLAR	Repair	0.00 F	*- F
59	1		*FRT STEP PANEL	Repair	0.00 F	*- F
60	1		*WIPER WASHER TANK	Deformed	0.00 F	*- F
61	1		*WIRE HARNESS	* Check	0.00 F	*- F
62	1		*BODY PANEL	Repair	0.00 F	*- F
63	1		*ABS PUMP	* Check	0.00 F	*- F
64	1		*ABS PIPE	Bent	0.00 F	*- F
65	1		*FRT LH SHOCK ABSORBER	* Check	0.00 F	*- F
66	1		*FRT LH KNUCKLE ARM	* Check	0.00 F	*- F
67	1		*FRT LH KNUCKLE ARM BEARING	* Check	0.00 F	*- F
68	1		*FRT LH LOWER ARM	* Check	0.00 F	*- F
69	1		*FRT LH TIE ROD	* Check	0.00 F	*- F
70	1		*STEERING RACK & PINION	* Check	0.00 F	*- F
71	1		*STEERING CROSS MEMBER	* Check	0.00 F	*- F
72	1		*FRT SUB FRAME	* Check	0.00 F	*- F
73	1		*FRT ANTI ROLL BAR	* Check	0.00 F	*- F
74	1		*FRT ANTI ROLL BAR LINKAGE	* Check	0.00 F	*- F
75	1		*FRT RH SHOCK ABSORBER	* Check	0.00 F	*- F
76	1		*FRT RH KNUCKLE ARM	* Check	0.00 F	*- F
77	1		*FRT RH KNUCKLE ARM BEARING	* Check	0.00 F	*- F
78	1		*FRT RH LOWER ARM	* Check	0.00 F	*- F
79	1		*FRT RH TIE ROD	* Check	0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >