

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20006880/T1YF3E2

Date: 15/07/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No:	MU011947
Claimant Vehicle No : SHC7464M	Insured Vehicle No :	SLT8915K
Date of Loss: 29/06/2020	Nature of Claim:	TP Claim No: M2003248

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC7464M	Engine No:	2ZR2B89057
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 (A)	Chassis No:	JTDKB3FU203078261
Reg. Date:	09/01/2019 (Man. Year: 2018)	Odometer:	186063 km
Colour:	Yellow		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,133.92	960.60	173.32	15.29
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	720.00	550.00	170.00	23.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,864.92	1,521.60	343.32	18.41
+ GST 7.00/7.00% (S\$)	130.54	106.51	24.03	18.41
Nett Amount (S\$)	1,995.46	1,628.11	367.35	18.41

INSPECTION

Date of Assignment:	01/07/2020 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	30/06/2020 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Jul 2020)
Parts: 144	TOYOTA PRIUS HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC7464M)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER COVER	Deformed	458.60 FL	-	*458.60 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
3	1		*REAR BUMPER UNDER COVER	Deformed	552.60 FL	-	*552.60 FL
4	1		*REAR BUMPER FILLER RH	Not Necessary	148.40 FL	-	*- FL
5	1		*REAR BUMPER TOW COVER	Not Necessary	82.70 FL	-	*- FL
6	1		*REAR BUMPER REVERSE SENSOR	Not Working	135.70 F	-	*135.70 FS
7	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 F	-	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,450.00	1,218.90
- List Item Discount on L Items 25.00/25.00% (S\$)	316.08	258.30
Total Parts (S\$)	1,133.92	960.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	350.00	320.00
2	SPRAY PAINTING CHARGE	New	250.00	200.00
3	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
			Gross Labour Cost (\$\$)	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >