

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20006881/AQF3Q2

Date: 08/02/2021

REFERENCE

Insured/Claimant: RAYMOND'S MATH AND SCIENCE STUDIO Policy No: 2100431672

Date of Loss: 28/06/2020

Nature of Claim: OD

Claim No: 3193472503SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV7776C		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZD215462
Reg. Date:	30/09/2015 (Man. Year: 2015)	Chassis No:	WAUZZZ8U4GR027598
Colour:	Blue	Odometer:	140398 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$78,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/40 R19	Rear Tyre Size:	255/40 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,091.20	3,952.08	5,139.12	56.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,812.00	3,452.00	5,360.00	60.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,903.20	7,404.08	10,499.12	58.64
- Excess (\$\$)	400.00	400.00	0.00	0.00
(\$\$)	17,503.20	7,004.08	10,499.12	59.98
+ GST 7.00/7.00% (\$\$)	1,225.22	490.29	734.93	59.98
Nett Amount (\$\$)	18,728.42	7,494.37	11,234.05	59.98

INSPECTION

Date of Assignment: 01/07/2020

Date Inspected: 01/07/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	1,846.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	103.00 FS	*- FS
3	1		*HEADLIGHT MOUNTING - LH	Not Necessary	112.00 FS	*- FS
4	1		*FRONT FENDER - LH	Repair	850.00 FS	*- FS
5	1		*FRONT FENDER ATTACHMENT PARTS \$	Not Necessary	66.00 FS	*- FS
6	1		*FRONT FENDER BRACKET - LH	Not Necessary	78.00 FS	*- FS
7	1		*FRONT FENDER BRACE - LH FRONT	Not Necessary	98.00 FS	*- FS
8	1		*WHEEL HOUSING LINER - LH	Not Necessary	226.00 FS	*- FS
9	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	145.00 FS	*- FS
10	1		*FRONT WHEEL SPOILER - LH	Not Necessary	69.00 FS	*- FS
11	2		*FRONT WHEEL COVER - LH / RH	N/S Cut / O/S Necessary	994.00 FS	*795.20 FS
12	1		*FRONT DOOR - LH	Dented	2,512.00 FS	*2,009.60 FS
13	1		*FRONT DOOR OUTER SEAL - LH	Necessary	156.00 FS	*124.80 FS
14	1		*PROTECTIVE FILM	Necessary	25.00 FS	*19.28 FS
15	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	101.00 FS	*- FS
16	1		*BONDING AGENT	Not Necessary	46.00 FS	*- FS
17	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
18	1		*FRONT DOOR CATCH	Not Necessary	113.00 FS	*- FS
19	1		*FRONT DOOR COVER - LH	Necessary	420.00 FS	*336.00 FS
20	1		*FRONT ALUMINIUM RIM - LH	Cut	667.20 FS	*667.20 FS
21	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **9,091.20** **3,952.08**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	New	360.00	0.00
2	To remove and transfer lhs front doors multilock system and power window devices. Inspect for damages.	New	280.00	280.00
3	To dismantle and renew front bumper, lhs front fender and lhs front door. Re-organise crash management components. Reinstall all parts removed.	New	3,200.00	1,000.00
4	To respray front bumper, lhs front fender, lhs front door, both front wheel arch rims and door cover.	New	4,500.00	1,700.00
5	To renew lhs front rim. To carry out wheel alignment.	New	280.00	280.00
6	To carry out diagnostic check.	New	192.00	192.00
Gross Labour Cost (\$\$)			8,812.00	3,452.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >