

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20006890/ARA3Q2

Date: 03/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900254316

Claimant
Vehicle No : SMG3131U **Insured Vehicle No :** YP607U

Date of Loss: 30/06/2020 Nature of Claim: TP Claim No: 6297339620SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG3131U		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI COD S-TRONIC (A)	Engine No:	CZE846360
Reg. Date:	13/11/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V2K1003641
Colour:	Blue	Odometer:	43004 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,656.00	3,557.60	12,098.40	77.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,142.00	2,292.00	2,850.00	55.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	20,798.00	5,849.60	14,948.40	71.87
+ GST 7.00/7.00% (\$\$)	1,455.86	409.47	1,046.39	71.87
Nett Amount (\$\$)	22,253.86	6,259.07	15,994.79	71.87
+ Loss of Use (4.0 x S\$60.00/day) (\$\$)		240.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		6,501.07		

INSPECTION

Date of Assignment: 03/07/2020

Date Inspected: 03/07/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,894.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	176.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE -CENTRE	Not Necessary	151.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	505.00 FS	*- FS
5	2		*FRONT BUMPER CLOSING ELEMENT -LH/RH	Not Necessary	560.00 FS	*- FS
6	2		*FRONT BUMPER COVER TRM -LH/RH	Not Necessary	306.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cut	1,338.00 FS	*1,070.40 FS
8	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	180.00 FS	*- FS
9	1		*AIRCON STICKER	Necessary	7.00 FS	*5.60 FS
10	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*10.40 FS
11	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	681.00 FS	*- FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	178.00 FS	*- FS
13	1		*FOAM FILLER PIECE COVER	Not Necessary	115.00 FS	*- FS
14	1		*BONNET	Dented	2,988.00 FS	*2,390.40 FS
15	1		*BONNET ATTACHMENT PARTS	Not Necessary	155.00 FS	*- FS
16	2		*BONNET LID HINGE -LH/RH	Not Necessary	116.00 FS	*- FS
17	1		*BONNET CATCH HOOK	Not Necessary	84.00 FS	*- FS
18	1		*BONNET STRIKER -RH	Not Necessary	104.00 FS	*- FS
19	1		*BONNET EDGE PROTECTION	Cracked	26.00 FS	*20.80 FS
20	1		*BONNET LID LOCK	Not Necessary	202.00 FS	*- FS
21	1		*BONNET BOWDFEN CABLE -CENTRE	Not Necessary	54.00 FS	*- FS
22	1		*BONNET CATCH HOOK	Not Necessary	60.00 FS	*- FS
23	1		*LED HEADLIGHT -RH	Not Necessary	5,193.00 FS	*- FS
24	1		*LIFT CYLINDER -RH	Not Necessary	134.00 FS	*- FS
25	1		*RADIATOR AIR GUIDE -UPPER CENTRE	Not Necessary	12.00 FS	*- FS
26	1		*TEMPERATURE SENSOR BRACKET	Not Necessary	18.00 FS	*- FS
27	2		*RADIATOR AIR GUIDE -LH/RH	Not Necessary	46.00 FS	*- FS
28	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
29	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 15,656.00 3,557.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNITS AND POWER MODULES .TO CARRY OUT CALIBRATION	New	350.00	0.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND BONNET .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
3	TO RESPRAY FRONT BUMPER ,BONNET AND HINGES	New	2,500.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,142.00	2,292.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >