

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20006891/KGS3Q2

Date: 07/10/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SCG9300C	Insured Vehicle No :	SHA4605D
Date of Loss: 26/06/2020	Nature of Claim: TP	Claim No: MCT20060300

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCG9300C		
Make & Model:	MAZDA 3, 2.0 SEDAN SPORTS A/T 2WD S/R (A)	Engine No:	PE20701893
Reg. Date:	08/01/2016 (Man. Year: 2015)	Chassis No:	JM6BM4278G0323559
Colour:	Metallic Grey	Odometer:	58827 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,465.52	4,423.24	2,042.28	31.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	1,170.00	470.00	28.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,105.52	5,593.24	2,512.28	30.99
Approved Total (Overridden) (\$\$)		4,450.00		
Nett Amount (\$\$)	8,105.52	4,450.00	3,655.52	45.10
+ Loss of Use (4.0 x S\$60.00/day) (\$\$)		240.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		4,697.45		

INSPECTION

Date of Assignment:	01/07/2020	
Date Inspected:	01/07/2020 Inspected At:	King's Auto Spray Paint Pte Ltd (HQ) BLK 160 SIN MING DRIVE #05-10 SIN MING AUTOCARE Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Sep 2020)
Parts:	143	MAZDA 3 2.0 SEDAN SPORTS A/T 2WD S/R (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCG9300C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER TOP	Buckled	335.10 FL	*335.10 FL
2	1		*FRONT BUMPER LOWER GRILLE CENTER	Serviceable	153.00 FL	*- FL
3	1		*FRONT BUMPER	Buckled	1,031.70 FL	*1,031.70 FL
4	1		*FRONT BUMPER TOWING COVER	Serviceable	28.60 FL	*- FL
5	1		*FRONT BUMPER NOZZLE	Serviceable	242.40 FL	*- FL
6	1		*FRONT BUMPER NOZZLE COVER	Serviceable	85.40 FL	*- FL
7	2		*FRONT BUMPER BRACKETS	Distorted	50.00 FL	*50.00 FL
8	2		*FRONT BUMPER RETAINER SIDE	Serviceable	41.40 FL	*- FL
9	1		*FRONT BUMPER BEAM	Bent	665.10 FL	*665.10 FL
10	1		*FRONT BUMPER BEAM OUTE GARNISH	Cracked	258.40 FL	*258.40 FL
11	1		*FRONT BUMPER SPONGE	Serviceable	150.40 FL	*- FL
12	1		*FRONT BUMPER TOP PANEL	Repair	320.60 FL	*- FL
13	1		*FRONT TOP PANEL GARNISH	Serviceable	335.10 FL	*- FL
14	6		*FRONT TOP PANEL GARNISH CLIPS	Not Necessary	21.00 FL	*- FL
15	1		*FRONT SPORT LAMP	Serviceable	351.40 FL	*- FL
16	1		*FRONT SPORT LAMP COVER	Serviceable	46.40 FL	*- FL
17	1		*FRONT SPORT LAMP MLDG	Serviceable	106.70 FL	*- FL
18	1		*FRONT SPORT LAMP CHROME	Serviceable	80.00 FL	*- FL
19	1		*FRONT GRILLE CENTER	Cracked	681.60 FL	*681.60 FL
20	1		*FRONT GRILLE MLDG	O/S Cracked	373.40 FL	*186.70 FL
21	1		*FRONT GRILLE LOGO	Necessary	44.20 FL	*44.20 FL
22	1		*FRONT HEAD LAMP	Mtg Cracked	2,245.00 FL	*2,245.00 FL
23	1		*FRONT GRILLE INNER PANEL	Repair	55.00 FL	*- FL
24	1		*FRONT BONNET LOCK	Repair	330.00 FL	*- FL
25	1		*FRONT NUMBER PLATS	Scratched	40.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,071.90	5,522.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,606.38	1,099.56
Total Parts (\$\$)	6,465.52	4,423.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING	New	40.00	20.00
2	TO RENEW THE ABOVE MENTIONED PARTS KNOCKING ,CUTTING ,WELDING & STRAIGHTEN FRONT DAMAGED PARTS	New	800.00	500.00
3	SPRAY PAINTINGS	New	800.00	650.00
Gross Labour Cost (\$\$)			1,640.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >