

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006892/KDA3Q2

Date: 18/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100452775

Claimant
Vehicle No : SME8001P **Insured Vehicle No :** SGU3177K

Date of Loss: 29/06/2020 Nature of Claim: TP Claim No: 7761213007SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME8001P		
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Engine No:	2ZR0C55443
Reg. Date:	18/10/2018 (Man. Year: 2018)	Chassis No:	JTDZS3EU00J033895
Colour:	Metallic Dark Blue	Odometer:	43308 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,146.10	0.00	2,146.10	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	220.00	1,430.00	86.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,796.10	220.00	3,576.10	94.20
+ GST 7.00/7.00% (\$\$)	265.73	15.40	250.33	94.20
Nett Amount (\$\$)	4,061.83	235.40	3,826.43	94.20
+ Car Rental (2.0 x S\$120.00/day) (\$\$)		240.00		
+ Doc/Search Fee (\$\$)		29.00		
Nett Liability (\$\$)		504.40		

INSPECTION

Date of Assignment: 01/07/2020

Date Inspected: 01/07/2020 Inspected At:

YEE AUTO PTE LTD
160 SIN MING DRIVE
#02-17 SIN MING AUTOCITY
SINGAPORE 575722

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	895.20 F	*- F
2	1		*REAR BUMPER SIDE RETAINER - LH	Serviceable	65.20 F	*- F
3	1		*REAR BUMPER SIDE RETAINER - RH	Serviceable	65.20 F	*- F
4	1		*TAIL LAMP RH	Serviceable	585.50 F	*- F
5	1		*REAR BUMPER REFLECTOR - RH	Serviceable	185.00 F	*- F
6	1		*REAR BUMPER SPOILER	Serviceable	350.00 F	*- F

F=Franchise part.

Total Parts (\$)	2,146.10	0.00
-------------------------	-----------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY	New	800.00	0.00
2	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	800.00	220.00
3	TO CHECK WIRING FUNCTIONS	New	50.00	0.00
Gross Labour Cost (\$\$)			1,650.00	220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >