



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Mr Yeo Wen Hui (yao Wenhui) Blk 457 Segar Road #12-135 Singapore 670457 Contact No Mobile: 97974866	Cust No/Name	/Mr Yeo Wen Hui (yao Wenhui)
	Reg No/Reg Date	SKX5775H / 18/12/201
	Date In/Mileage	/ 0
	Chassis No	KNAHU813MG7143087
	Engine No	G4NCFH019482
	Make/Model	KIA/CARENS 2.0 A GDI EX
	Colour/Trim	9H / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	11/08/2020/ 11:53	TLC	261 / Edwin Caina	16644

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPAIR FRT BUMPER, FRT FENDER RH, FRT DOOR RH				550 1100.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, FRT FENDER RH, FRT DOOR RH				1260 1680.00
M SUNDRY Sundry				20 50.00

550 1100.00
1260 1680.00
20 50.00

1830
//

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SURVEYOR NAME: Ryan - HP 90010088

SURVEYOR SIGNATURE: Ryan

DATE: 11/08/2020 @ 11:50

REMARKS: 4 days

Ready after repair

Confirm & accepted by

	Nett	2,830.00
7% GST on	2830.00	198.10
Total Payable		3,028.10

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this