

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20006904/URA3Q2
Date: 01/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SLX7618D	Insured Vehicle No :	SMH2234H
Date of Loss:	29/06/2020	Nature of Claim:	TP
		Claim No:	5702264070SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX7618D		
Make & Model:	MERCEDES-BENZ E200K, 1.8 (A)	Engine No:	27195631056827
Reg. Date:	10/07/2008 (Man. Year: 2008)	Chassis No:	WDB2110412B324079
Colour:	Grey	Odometer:	234172 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,887.00	3,650.40	1,236.60	25.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,075.00	1,315.00	760.00	36.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,962.00	4,965.40	1,996.60	28.68
Approved Total (Overridden) (S\$)		3,950.00		

(S\$)	6,962.00	3,950.00	3,012.00	43.26
+ GST 7.00/7.00% (S\$)	487.34	276.50	210.84	43.26
Nett Amount (S\$)	7,449.34	4,226.50	3,222.84	43.26
+ Loss of Use (6.0 x S\$80.00/day) (S\$)		480.00		
(S\$)		4,706.50		
Liable Amount (50.00%) (S\$)		2,353.25		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,355.25		

INSPECTION

Date of Assignment: 02/07/2020

Date Inspected: 02/07/2020

Estimated Period of Repair: 4.0 days

Inspected At: NPH Auto Service (HQ)
Blk 9005 Tampines Steet 93, #01-246/254
Singapore 528839

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR LAMP LH	Broken	595.00 FL	*595.00 FL	
2	1		*REAR LAMP SIDE GARNISH LH	Not Necessary	34.00 FL	*- FL	
3	1		*REAR BUMPER	Distorted	1,450.00 FL	*1,450.00 FL	
4	2		*REAR BUMPER CHROME MOULDING L& R	Necessary	296.00 FL	*296.00 FL	
5	1		*REAR BUMPER CHROME MOULDING CENTER	Necessary	210.00 FL	*210.00 FL	
6	1		*REAR BUMPER PACKING SENSOR LH	Shorted	316.00 FL	*316.00 FL	
7	1		*REAR BUMPER SIDE RETAINER LH	Cracked	49.00 FL	*49.00 FL	
8	1		*REAR LAMP LOWER LAMP RETAINER LH	Cracked	24.00 FL	*24.00 FL	
9	1		*REAR BUMPER ENFORCEMENT	Bent	670.00 FL	*670.00 FL	
10	1		*REAR BUMPER SPONGE	Not fitted	255.00 FL	*- FL	
11	2		*REAR BUMPER BRACKET LOWER	Cracked	48.00 FL	*48.00 FL	
12	1		*REAR LAMP PANEL LH	Repair	245.00 FL	*- FL	
13	1		*REAR LAMP END PANEL	Repair	840.00 FL	*- FL	
14	1		*REAR EXHAUST ALUMINIUM HEAT SHIELD LH	Bent	138.00 FL	*138.00 FL	
15	1		*REAR BUMPER CENTER RETAINER	Cracked	260.00 FL	*260.00 FL	
F=Franchise part. L=ListItemDisc.							
					Sub Total (\$\$)	5,430.00	4,056.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	543.00	405.60
					Total Parts (\$\$)	4,887.00	3,650.40

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND INSTALL REAR LAMP ,REAR BUMPER ,REAR SIDE GARNISH ,BUMPER ENFORCEMENT ,CUT OUT AND RENEW REAR LAMP PANEL ,REAR ROCKER PANEL,KNOCKING REAR FENDER ,SPARE TYRE PANEL & RESTRAIGHTEN BODY AND CHASSIS	New	950.00	550.00
2	SPRAY PAINTING	New	1,000.00	680.00
3	CHECK WIRING SYSTEM	New	25.00	25.00
4	REMOVE AND INSTALL REAR BOOT CARPER	New	100.00	60.00
Gross Labour Cost (S\$)			2,075.00	1,315.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >