

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20006906/AES3Q2

Date: 06/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800045742
Claimant
Vehicle No : SJQ7824K **Insured Vehicle No :** SLZ2715D
 Date of Loss: 30/06/2020 Nature of Claim: TP Claim No: 3319395628SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJQ7824K**
 Make & Model: SUZUKI SWIFT, 1.6 (A) Engine No: M16A1467749
 Reg. Date: 27/05/2009 (Man. Year: 2009) Chassis No: JSAEZC31S00204332
 Colour: White Odometer: 198810 km
 Engine Capacity: 1586 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,644.50	8,981.67	7,662.83	46.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,930.00	4,210.00	1,720.00	29.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,574.50	13,191.67	9,382.83	41.56
Approved Total (Overridden) (S\$)		10,500.00		
Nett Amount (S\$)	22,574.50	10,500.00	12,074.50	53.49
+ Loss of Use (16.0 x S\$50.00/day) (S\$)		800.00		
		11,300.00		

INSPECTION

Date of Assignment: 01/07/2020
 Date Inspected: 01/07/2020 Inspected At: Advance Auto Garage (HQ)
 23 KAKI BUKIT AVENUE 4 #04-01
 AAS KAKI BUKIT CENTRE
 Singapore 415933
 Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE

MARKET VALUE: \$40,000

LTA REBATE: \$23,113

NETT VALUE: \$16,887

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Cracked	30.00 FS	*30.00 FS
2	1		*FRONT BUMPER	Distorted	518.70 F	*518.70 FL
3	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
4	2		*FRONT BUMPER SIDE HOLDER	Necessary	58.40 F	*58.40 FL
5	1		*FRONT BUMPER REINFORCEMENT UPPER	Bent	143.70 F	*143.70 FL
6	1		*FRONT BUMPER REINFORCEMENT COVER UPPER	Cracked	76.70 F	*76.70 FL
7	1		*FRONT BUMPER REINFORCEMENT LOWER	Not Necessary	125.70 F	*- FL
8	1		*FRONT BUMPER REINFORCEMENT COVER LOWER	Cracked	76.70 F	*76.70 FL
9	2		*FRONT BUMPER FOG LAMP	Cracked	438.40 F	*438.40 FL
10	1		*FRONT BUMPER FOG LAMP COVER	N/S Cracked	518.60 F	*259.30 FL
11	2		*FRONT BUMPER FOG LAMP COVER GARNISH	Not Necessary	90.20 F	*- FL
12	1		*FRONT BUMPER LOWER WIRE MESH	Not Necessary	150.00 FS	*- FS
13	1		*FRONT BUMPER LOWER SPOILER	Deformed	1,200.00 FS	*750.00 FS
14	1		*FRONT BUMPER TOW COVER	Necessary	24.30 F	*24.30 FL
15	1		*FRONT GRILLE	Cracked	350.00 FS	*280.00 FS
16	1		*FRONT GRILLE CLIPS	Necessary	20.00 F	*20.00 FL
17	2		*HEADLAMP	Cracked	970.60 F	*970.60 FL
18	1		*OIL COOLER	Dented	500.00 FS	*380.00 FS
19	2		*OIL COOLER LOWER ALUMINIUM SHEET	Bent	300.00 FS	*120.00 FS
20	1		*AIR CON CONDENSER	Dented	471.70 F	*471.70 FL
21	1		*RADIATOR	Not Necessary	632.40 F	*- FL
22	1		*FRONT SUPPORT PANEL	Repair	551.50 F	*- FL
23	2		*FRONT FENDER	Repair	942.00 F	*- FL
24	1		*REAR NUMBER PLATE	Cracked	30.00 FS	*30.00 FS
25	2		*REAR NUMBER PLATE LAMP	Cracked	83.60 F	*83.60 FL
26	1		*REAR BUMPER	Distorted	605.00 F	*605.00 FL
27	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
28	2		*REAR BUMPER SIDE HOLDER	Necessary	70.20 F	*70.20 FL
29	2		*REAR BUMPER WIRE MESH	Not Necessary	130.00 FS	*- FS
30	1		*REAR BUMPER LOWER SPOILER	Deformed	1,200.00 FS	*600.00 FS
31	2		*REAR BUMPER LAMP	Cracked	242.00 F	*242.00 FL
32	1		*REAR BUMPER IMPACT BRACKET	O/S Dented	94.40 F	*47.20 FL
33	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
34	1		*REAR CAMERA	Damaged	500.00 FS	*400.00 FS
35	1		*REAR END PANEL	Dented	395.60 F	*395.60 FL
36	1		*REAR END PANEL TOP GARNISH	Cracked	73.40 F	*73.40 FL
37	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 F	*20.00 FL
38	1		*REAR END PANEL AIR VENT	Not Necessary	36.00 F	*- FL
39	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
40	2		*TAILLAMP	Cracked	579.40 F	*579.40 FL
41	2		*TAILLAMP PANEL	Repair	229.00 F	*- FL
42	1		*TAILGATE	Dented	680.20 F	*680.20 FL
43	1		*TAILGATE LOCK	Jammed	149.50 F	*149.50 FL
44	1		*TAILGATE WEATHERSTRIPE	Cut	76.60 F	*76.60 FL
45	1		*TAILGATE OUTER HANDLE SWITCH	Damaged	78.60 F	*78.60 FL
46	1		*TAILGATE INNER TRIM BOARD	Cracked	172.20 F	*172.20 FL
47	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 F	*30.00 FL
48	1		*TAILGATE GLASS MOULDING	Necessary	100.20 F	*100.20 FL
49	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
50	1		*TAILGATE STICKERS	Necessary	280.00 FS	*100.00 FS
51	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	221.20 F	*- FL
52	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 F	*- FL
53	1		*SPARE TYRE PANEL	Repair	589.50 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	145.00 F	*- FL
55	1		*SPARE TYRE PANEL INSULATION PAD	Necessary	250.00 FS	*200.00 FS
56	1		*REAR EXHAUST PIPE	Not Necessary	579.30 F	*- FL
57	2		*REAR EXHAUST MOUNTING	Not Necessary	56.00 F	*- FL
58	1		*SPARE TYRE PANEL FOLDABLE BOARD	Cracked	268.00 F	*268.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,644.50	10,000.20
- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00	1,018.53
Total Parts (\$\$)	16,644.50	8,981.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,200.00	1,600.00
2	SPRAY PAINTING	New	2,200.00	1,800.00
3	WIRING	New	150.00	100.00
4	TO REMOVE UPHOLSTERY AND REAR SEAT	New	350.00	120.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE REAR CAMERA	New	100.00	50.00
7	TO REMOVE REAR VIDEO RECORDER	New	100.00	50.00
8	TO REMOVE EXHAUST PIPE	New	150.00	80.00
9	TO TRANSFER TAILGATE FITTINGS AND TAILGATE SPOILER	New	250.00	120.00
10	TO REMOVE TAILGATE GLASS	New	150.00	120.00
11	TO REMOVE CONDENSER AND RADIATOR AND TO TOP UP AIRCON GAS	New	180.00	120.00
			Gross Labour Cost (\$)	4,210.00
			5,930.00	4,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >