

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG20006909/DQF3Q2**Date:** 07/01/2021REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713MKF

**Claimant****Vehicle No :** SHA2246U**Insured Vehicle No :** SLQ9499D

Date of Loss: 30/06/2020

Nature of Claim: TP

Claim No: 625487

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHA2246U**

Make &amp; Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No: D4FDGU712998

Reg. Date: 13/12/2017 (Man. Year: 2016)

Chassis No: KMHLB41UMHU098613

Colour: Blue

Odometer: 222036 km

Engine Capacity: 1685 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Hankook 5 mm

Rear Left Side: Hankook 5 mm

Front Right Side: Hankook 5 mm

Rear Right Side: Hankook 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>	
Parts	38,697.12	18,735.40	19,961.72	51.58	
Miscellaneous Items	0.00	0.00	0.00		
Labour	7,040.00	2,750.00	4,290.00	60.94	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>45,737.12</b>	<b>21,485.40</b>	<b>24,251.72</b>	<b>53.02</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>17,000.00</b>			
	<b>(S\$)</b>	45,737.12	17,000.00	28,737.12	62.83
<b>+ GST 7.00/7.00% (S\$)</b>	3,201.60	1,190.00	2,011.60	62.83	
<b>Nett Amount (S\$)</b>	<b>48,938.72</b>	<b>18,190.00</b>	<b>30,748.72</b>	<b>62.83</b>	

INSPECTION

Date of Assignment: 02/07/2020

Date Inspected: 02/07/2020 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)  
Blk 9 Sector C, #01-42 Sin Ming  
Industrial Estate  
Singapore 575644

Estimated Period of Repair: 10.0 days

**Adjuster:** BRYAN TANI**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 07 Jan 2021)
<b>Parts:</b> 143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHA2246U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Dented	2,201.10 FL	*2,201.10 FL
2	1		*REAR DOOR RUBBER LH	Serviceable	185.40 FL	*- FL
3	1		*ROCKER PANEL OUTER GARNISH LH	Bent/Mounting Broken	732.80 FL	*341.40 FL
4	1		*ROCKER PANEL OUTER	Not Necessary	1,380.50 FL	*- FL
5	1		*ROCKER PANEL ENFORCEMENT LH	Not Necessary	969.40 FL	*- FL
6	1		*BONNET	Repair	2,265.90 FL	*- FL
7	1		*BONNET RUBBER LH	Not Necessary	35.70 FL	*- FL
8	1		*BONNET HINGE LH	Repair	126.70 FL	*- FL
9	1		*BONNET LOCK	Not Necessary	142.40 FL	*- FL
10	1		*BONNET ABSORBER (LH ONLY)	Not Necessary	61.60 FL	*- FL
11	1		*BONNET INSULATOR	Not Necessary	202.50 FL	*- FL
12	1		*BONNET SEAL	Not Necessary	31.90 FL	*- FL
13	1		*BONNET INSULATOR CLIPS	Not Necessary	15.00 FL	*- FL
14	1		*BONNET CABLE	Not Necessary	69.60 FL	*- FL
15	1		*FRONT BUMPER COVER	Bent/Cut	1,052.20 FL	*1,052.20 FL
16	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	89.60 FL	*- FL
17	1		*FRONT BUMPER BRACKET (LH/RH)	N/s Broken/O/s Not Necessary	98.40 FL	*24.60 FL
18	1		*FRONT BUMPER RETAINER MOUNTING	Not Necessary	76.20 FL	*- FL
19	1		*FRONT BUMPER GRILLE AIR DUCT LH	Not Necessary	126.20 FL	*- FL
20	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
21	1		*HEADLAMP LH	Broken	2,776.00 FL	*1,388.00 FL
22	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
23	1		*RADIATOR	Not Necessary	1,637.20 FL	*- FL
24	1		*RADIATOR GUARD LH	Not Necessary	76.50 FL	*- FL
25	1		*COOLANT	Not Necessary	45.00 FL	*- FL
26	1		*RADIATOR FAN BLADE,COWLING,MOTOR ASSY	Not Necessary	1,194.20 FL	*- FL
27	1		*FRONT FENDER LH	Buckled	566.30 FL	*566.30 FL
28	1		*FRONT FENDER APRON PANEL LH	Dented	637.00 FL	*637.00 FL
29	1		*FRONT FENDER SHIELD LH	Deformed	174.90 FL	*174.90 FL
30	1		*AIRCON CONDENSER	Not Necessary	947.80 FL	*- FL
31	1		*FRONT DOOR MIRROR SIDE GARNISH	Dislodged	225.00 FL	*225.00 FL
32	1		*FRONT DOOR MIRROR LH	Repair	670.00 FL	*- FL
33	1		*FRONT DOOR LH	Buckled	2,256.40 FL	*2,256.40 FL
34	1		*FRONT DOOR RUBBER	Serviceable	196.00 FL	*- FL
35	1		*FRONT DOOR GEAR/REGULATOR LH	Broken	776.80 FL	*776.80 FL
36	1		*FRONT DOOR POWER MOTOR	Not Necessary	442.10 FL	*- FL
37	1		*FRONT DOOR HINGE UPPER LH	Bent	113.60 FL	*36.10 FL
38	1		*FRONT DOOR HINGE LOWER LH	Bent	125.70 FL	*36.10 FL
39	1		*FRONT DOOR CHECK LH	Not Necessary	91.80 FL	*- FL
40	1		*FRONT DOOR TRIM BOARD LH	Broken	997.40 FL	*997.40 FL
41	1		*FRONT DOOR OUTER MOULDING LH	Not Necessary	153.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*FRONT WINDSCREEN MOULDING	Not Necessary	133.70 FL	*- FL
43	1		*FRONT WINDSCREEN PILLAR OUTER LH	Dented	1,535.90 FL	*1,535.90 FL
44	1		*FRONT WHEEL RIM LH	Dented	650.60 FL	*325.30 FL
45	1		*KNUCKLE ARM LH	Distorted	595.90 FL	*552.00 FL
46	1		*FRONT WHEEL BEARING HUB ASSY LH	Damaged	673.20 FL	*540.50 FL
47	1		*FRONT SUSPENSION LOWER ARM LH	Bent	1,104.00 FL	*529.30 FL
48	1		*FRONT SHOCK ABSORBER ASSY LH	Bent	684.40 FL	*342.20 FL
49	1		*FRONT SHOCK ABSORBER MOUNTING LH	Not Necessary	217.60 FL	*- FL
50	1		*STG TIE ROD LH	Bent	186.40 FL	*186.40 FL
51	1		*STG TIE END LH	Bent	125.20 FL	*125.20 FL
52	1		*STABILIZER BAR ASSY	Distorted	463.70 FL	*252.30 FL
53	1		*STABILIZER BAR LINK LH	Distorted	68.10 FL	*68.10 FL
54	1		*ABS SENSOR	Not Necessary	217.90 FL	*- FL
55	1		*FRONT DRIVE SHAFT LH	Distorted	2,061.60 FL	*1,030.80 FL
56	1		*RACK & PINION ASSY	Damaged	1,820.00 FL	*969.60 FL
57	1		*GEARBOX MOUNTING LH	Not Necessary	596.10 FL	*- FL
58	1		*ENGINE UNDER COVER	Not Necessary	334.60 FL	*- FL
59	1		*ENGINE CROSS MEMBER	Distorted	2,094.40 FL	*2,094.40 FL
60	1		*INTER COOLER	Not Necessary	1,032.50 FL	*- FL
61	1		*HOSE B TO INTER COOLER	Not Necessary	229.70 FL	*- FL
62	1		*HOSE C TO INTER COOLER INLET	Not Necessary	294.50 FL	*- FL
63	1		*WIRING-ENGINE W/FUSE BOX	Not Necessary	3,326.00 FL	*- FL
64	1		*DOOR CENTRE PILLAR OUTER LH	Dented	2,527.80 FL	*2,527.80 FL
65	1		*DOOR CENTRE PILLAR INNER	Not Necessary	1,224.20 FL	*- FL
66	1		*REAR DOOR COMFORTDELGRO & APPS STICKER LH	Necessary	80.00 FS	*80.00 FS
67	1		*REAR DOOR ADVERTISEMENT LOGO LH	Necessary	100.00 FS	*100.00 FS
68	1		*ROCKER PANEL ADVERTISEMENT LH	Necessary	120.00 FS	*120.00 FS
69	1		*FRONT FENDER ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
70	1		*FRONT DOOR COLOURED COMFORT LOGO	Necessary	75.00 FS	*75.00 FS
71	1		*FRONT DOOR ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
72	1		*FRONT WINDSCREEN SEALANT	Not Necessary	45.00 FS	*- FS
73	1		*FRONT ERP STICKER	Not Necessary	26.00 FS	*- FS
74	1		*FRONT TYRE LH	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>48,155.90</b>	<b>23,275.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>9,458.78</b>	<b>4,540.10</b>
<b>Total Parts (S\$)</b>	<b>38,697.12</b>	<b>18,735.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,800.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,600.00	1,000.00
3	WIRING CHARGE	New	160.00	30.00
4	TUFF KOTE	New	160.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
7	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
8	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
9	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
10	FOUR WHEEL ALIGNMENT	New	120.00	60.00
11	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	150.00
12	RE-SET FRT ABS SYSTEM	New	200.00	0.00
13	REMOVE/REFIX RADIATOR	New	90.00	0.00
14	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	0.00
15	REMOVE/REFIX FUSE BOX	New	120.00	0.00
16	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	120.00	0.00
17	REMOVE/REFIX ENGINE	New	600.00	0.00
18	REMOVE/REFIX DASHBOARD	New	350.00	0.00
19	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	150.00
			<b>Gross Labour Cost (\$\$)</b>	<b>7,040.00</b>
				<b>2,750.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >