

|                                             | Date      | No.        |
|---------------------------------------------|-----------|------------|
| Front Bumper Deformed.                      | 914.30    | ✓          |
| - grille crumpled                           | 842.00    | ✓          |
| - " emblem (L) Neg                          | 97.80     | ✓          |
| - " Number plate garnish behind             | 197.30    | ✓          |
| - Bumper lower grille crumpled              | 342.70    | ✓          |
| - " " Sensor - grille 263.30x2              | 526.60    | ✓          |
| - " Camera (grille) NPM                     | 1787.70   | X          |
| - " Bumper Reinforcement NPM                | 833.90    | X          |
| - " " sponge crumpled                       | 233.50    | ✓          |
| Headlamp LH crumpled.                       | 4452.80   | ✓ 2966.80. |
| Front Fog Lamp Cover crumpled               | 151.50    | ✓          |
| - " Fog Lamp LH NPM                         | 375.50    | X          |
| - " Signal Lamp LH NPM                      | 133.40    | X          |
| Front Number plate Dented                   | 50.00     | ✓          |
| - " Apron Beam Best                         | 138.20    | ✓          |
| - " Distance Sensor - Assy <sup>NPM</sup>   | 348.40    | X          |
| - " Bumper RH Air Bag Sensor <sup>NPM</sup> | 292.10    | X          |
| Front Support Panel. 985 ✓                  | 11,717.70 |            |
| crumpled                                    | Less 107. |            |
|                                             | 2343.54   |            |
|                                             | 4374.16   |            |
| spray painting                              | 600.00    | 250        |
| Panel Beating to replace parts              | 1200.00   | 800        |
| Wiring 50 30                                | 10774.16  |            |
| To perform diagnostic 200 100               |           |            |
| To remove condenser, radiator and to top up | \$8619/24 |            |
| air con gas                                 | 120.      |            |
| To remove front bumper sensor               | 120 60.   |            |
| To remove front bumper camera               | 100 50    |            |

List 7445.70

len 10%: 6701.13

Labour: 1410

total: 8111.13

1/s: 6.5K

0.5 Day

6.5K

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be submitted and is subject to final approval from insurance Company

Acknowledged

sig. date: