

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20006914/T1RA3Q2

**Date:** 18/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100507335

**Claimant**  
**Vehicle No :** SHC6418D **Insured Vehicle No :** SLN3040Z

Date of Loss: 01/07/2020 Nature of Claim: TP Claim No: 4570765715SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC6418D	Engine No:	D4FDEH313328
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414MF5588223
Reg. Date:	09/03/2015 (Man. Year: 2014)	Odometer:	514551 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,152.90	851.80	1,301.10	60.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	430.00	1,200.00	73.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,782.90</b>	<b>1,281.80</b>	<b>2,501.10</b>	<b>66.12</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,000.00</b>		
<b>(S\$)</b>	3,782.90	1,000.00	2,782.90	73.57
<b>+ GST 7.00/7.00% (S\$)</b>	264.80	70.00	194.80	73.56
<b>Nett Amount (S\$)</b>	<b>4,047.70</b>	<b>1,070.00</b>	<b>2,977.70</b>	<b>73.57</b>
<b>+ Loss of Use (2.0 x S\$50.00/day) (S\$)</b>		100.00		
<b>+ Car Rental (2.0 x S\$44.94/day) (S\$)</b>		89.88		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,261.88</b>		

### INSPECTION

Date of Assignment: 02/07/2020

Date Inspected: 06/07/2020 Inspected At:

Premier Automotive Services Pte Ltd  
(HQ)  
23 Changi South Ave 2, #01-02  
Singapore 486443

Estimated Period of Repair: 2.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	696.00 FL	*696.00 FL
2	1		*REAR BUMPER LOWER COVER	Cut	206.00 FL	*206.00 FL
3	1		*REAR BUMPER INNER SPONGE	Not Necessary	114.00 FL	*- FL
4	2		*REAR BUMPER SIDE BRACKET O/S & N/S	Not Necessary	58.00 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	607.00 FL	*- FL
6	2		*REAR BUMPER STAY O/S & N/S	Not Necessary	108.00 FL	*- FL
7	2		*REAR BUMPER REINFORCEMENT LOWER BRACKET	Not Necessary	36.00 FL	*- FL
8	2		*REAR BUMPER REINFORCEMENT UPPER BRACKET	Not Necessary	36.00 FL	*- FL
9	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
10	1		*SET REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
11	1		*SET BOOTLID STICKERS	Not Necessary	100.00 FS	*- FS
12	1		*SUNDRY	Necessary	50.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,339.00</b>	<b>942.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	186.10	90.20
<b>Total Parts (\$\$)</b>	<b>2,152.90</b>	<b>851.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	30.00
2	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS	New	180.00	0.00
3	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE END PANEL ,ETC	New	650.00	200.00
4	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER ,END PANEL ,BOOTLID LOWER GARNISH	New	600.00	200.00
5	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,630.00</b>	<b>430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >