



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG20005083/Etf3e2-1

78 SHENTON WAY #09-16

AIG BUILDING

SINGAPORE 079120

ATTN : JEFFREY NG

Date : 13-07-2020



Code : AIG

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GP 558R	<b>Veh. Inspected</b>	PA 8930T
<b>Policy No.</b>	0999993850	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	8724365484SG	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	JEFFREY NG	<b>Assign Date</b>	02/07/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA HIACE	<b>c.c</b>	2982
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
<b>Chassis No.</b>	KDH2010027250	<b>Colour</b>	SILVER
<b>Odometer</b>	215000	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195 R15C	YOKOHAMA	5 mm
<b>L/H Front Tyre</b>	195 R15C	YOKOHAMA	5 mm
<b>R/H Rear Tyre</b>	195 R15C	YOKOHAMA	5 mm
<b>L/H Rear Tyre</b>	195 R15C	YOKOHAMA	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	03/04/2020	<b>Inspection Date</b>	08/04/2020
<b>Survey held at</b>	SINCERELEAD GARAGE-2 BUROH CRESCENT #02-09 ACE @ B		
<b>Repairer</b>	-		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **12 Working Days**