

## Hsiao Tong (LKKAUTO)

---

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Monday, 15 March 2021 2:55 PM  
**To:** Tan, Bennie-WZ  
**Subject:** AIG REF: 4681470446SG // LKK REF: CC6/AIG20006918/Apa3 [ACCIDENT INVOLVING GBD 288S(OI) AND SMS 2835R(TP) ON 30/06/2020]

Hi Bennie,

We refer to the above matter and your enquiry dated 16/12/2020.

Surveyor recommended repair cost at L/sum basis as third party vehicle is a Honda Vezel which is quite common on the road and 2<sup>nd</sup> hand parts are available in market.

As for the In-Car Camera, the impact caused the rear camera damaged. Kindly refer to the photo No.14 in Merimen. There is a wire(connection for the rear camera) hang in the middle of the rear windscreen area. Furthermore, we have uploaded a copy of rear video footage submitted by third party to show that no video had been recorded after the accident impact.

Kindly let us have your mandate after review the matter. Thanks.



<< Back

## View Received Message

This mail is associated with :

**\*SMS2835R (4681470446SG)**  
**[GBD288S]**

TP  
HU JIANING  
Jun 30 2020 1:00PM  
[SCT HOLDINGS ELECTRICAL PTE LTD]  
MG Solution Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 16/12/2020 10:02 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Maintained - SMS2835R - Claim Handler: Tan, Bennie-WZ

Maintained:Pls advise on the recommendation to this part: IN-CAR CAMERA as well as lump sum repair instead of part by part.

Best Regards,

**Hsiao Tong, Chew (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | Email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | Fax: 6741 4108

HQ : Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)