

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006923/KPA3Q2

Date: 29/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800008075
Claimant		
Vehicle No : SJN6555J	Insured Vehicle No :	SLV9912B
Date of Loss: 06/06/2020	Nature of Claim: TP	Claim No: 1383940754SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN6555J		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Engine No:	3ZZ4860871
Reg. Date:	24/02/2009 (Man. Year: 2009)	Chassis No:	MR053ZEE106139982
Colour:	Metallic Silver	Odometer:	156008 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 7 mm	Rear Left Side:	Nexen 7 mm
Front Right Side:	Nexen 7 mm	Rear Right Side:	Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,306.70	383.10	1,923.60	83.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	1,000.00	780.00	43.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,086.70	1,383.10	2,703.60	66.16
Approved Total (Overridden) (\$\$)		1,100.00		
Nett Amount (\$\$)	4,086.70	1,100.00	2,986.70	73.08
+ Loss of Use (3.0 x S\$60.00/day) (\$\$)		180.00		
+ Doc/Search Fee (\$\$)		43.94		
+ Legal Costs/Disbursements (\$\$)		350.00		
Nett Liability (\$\$)		1,673.94		

INSPECTION

Date of Assignment:	02/07/2020	
Date Inspected:	07/07/2020 Inspected At:	Poon Siang Seow (HQ)
		160 Sin Ming Drive, #05-13 Sin Ming
		AutoCity
		Singapore 575722
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Distorted	634.90 F	*456.80 FL
2	2		*REAR BUMPER RETAINER	Serviceable	97.80 F	* - FL
3	1		*REAR WHEEL RIM	Serviceable	550.00 F	* - FL
4	1		*REAR DOOR PROTECTOR	Necessary	54.00 F	*54.00 FL
5	1		*REAR FENDE	Repair	850.00 F	* - FL
6	1		*W/S MOULDING	Not Necessary	120.00 F	* - FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,306.70	510.80
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	127.70
Total Parts (\$\$)	2,306.70	383.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RUST PROOFING	New	80.00	0.00
2	PANEL BEATING	New	900.00	400.00
3	SPRAY PAINTING	New	800.00	600.00
Gross Labour Cost (S\$)			1,780.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >