Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20006924/T1YF3E2

Date: 19/08/2020

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMHCSNA00000361900

Claimant Vehicle

SKU244Y

Insured Vehicle No:

Claim:

SMQ7798S

Date of Loss:

No:

Nature of 26/06/2020

TP

Claim No:

Engine No:

SNM20D202311/C02/THAMYL

G4KJFA647128

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKU244Y

Make & Model: KIA SORENTO, 2.4 EX (A)

Reg. Date: 29/06/2015 (Man. Year: 2015) Chassis No: KNAPH813MF5083634 Odometer: 40767 km

Colour: Silver

Engine Capacity: 2359 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable): Yes Footbrake (Serviceable): General Condition: Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

235/60 R18 Front Tyre Size: 235/60 R18 Rear Tyre Size: Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm Rear Right Side: Falken 6 mm Front Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,330.11	696.69	633.42	47.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,335.00	895.00	440.00	32.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,665.11	1,591.69	1,073.42	40.28
+ GST 7.00/7.00% (S\$)	186.56	111.42	75.14	40.28
Nett Amount (S\$)	2,851.67	1,703.11	1,148.56	40.28

INSPECTION

Date of Assignment: 17/08/2020

Date Inspected: 03/07/2020 Inspected At: Ethoz Group Ltd (HQ)

30 Bukit Batok Crescent Singapore 658075

Estimated Period of Repair: 4.0 days

Manager: YVONNE WONG YIN CHENG Adjuster: MOHD TAUFIKH BIN HAMID

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen ... 19/8/2020

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference					
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Aug 2020)			
Parts:	M1-SUV	KIA SORENTO 2.4 EX (A) (Catalogue:Merimen Singapore 1.0)			
Labour:	Repairer's	(Price-denominated Standard List)			
Print Code:	Print Code: (Unsubmitted, no print-code for SKU244Y)				
Validity:	dity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page				
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.					

Recommended Parts

*REAR BUMPER *REAR BUMPER CLIP *REAR BUMPER SIDE RET. *TAIL LAMP RH (OUTER) *TAIL LAMP CLIP	Deformed Necessary AINER RH Necessary Not Necessary	696.00 FL 49.00 FL 29.10 FL 687.00 FL	*29.10 FL
*REAR BUMPER SIDE RET. *TAIL LAMP RH (OUTER)	AINER RH Necessary	29.10 FL	
*TAIL LAMP RH (OUTER)	,		*29.10 FL
· · · · · · · · · · · · · · · · · · ·	Not Necessary	687 00 FI	
*TAIL LAMP CLIP		007.001 L	*- FL
	Not Necessary	16.80 FL	*- FL
*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
rt. L=ListItemDisc.			
	Sub Total (S\$)	1,477.90	774.10
- List Item	Discount on L Items 10.00/10.00% (S\$)_	147.79	77.41
	Total Parts (S\$)	1,330.11	696.69
r	(NPA) t. L=ListItemDisc.	(NPA) t. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 10.00/10.00% (S\$)	(NPA) t. L=ListItemDisc. Sub Total (\$\$) 1,477.90 - List Item Discount on L Items 10.00/10.00% (\$\$) 147.79

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR TO CARRY OUT REAR REPAIR	New	600.00	400.00
2	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	35.00	35.00
3	TO SPRAY PAINTING ON REAR AFFECTED AREA	New	600.00	400.00
4	SPRAY RUST PROOF ON AFFECTED AREA	New	40.00	30.00
5	TO REMOVE & REINSTALL REVERSE SENSOR	New	60.00	30.00
	Gross Labour Cost (S\$)		1,335.00	895.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.