

Your Ref : SNM20D202304/C01/TANKL

Date: 20<sup>th</sup> July 2020

Our Ref : CS/CTI20006925/Evf3e2

**M/s China Taiping Insurance (S) Pte Ltd**

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SDX 68G  
ACCIDENT ON 30/06/2020**

Instruction was received to inspect the vehicle Reg. No. SDX 68G. The inspection was conducted on 03/07/2020 at the premises of M/s Jin Auto Services Pte Ltd, Blk 14 Defu Lane 10, #01-410/412, Singapore 539195.

The following vehicle information was recorded:

Registration Number	: SDX 68G
Make/Model	: Jaguar XJ 2.0 TSS SWB SR
Year of Registration	: 2014
Body Colour	: Beige
Chassis Number	: SAJAC12M2EPV65898
Engine Capacity	: 1999 cc

The vehicle sustained damages at the front portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 120,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 92,729.00 )
Nett Liability	<u>S\$ 27,271.00</u> =====

Vehicle Inspected By:



CHEN TSUE YEE  
Automotive Assessor



K.K.LAU  
MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.