

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI20006925/EVF3E2

**Date:** 20/07/2020

### REFERENCE

Insured/Claimant: CHUA CHENG CHOO Policy No: DMPCSN1936211900

Date of Loss: 30/06/2020

Nature of Claim: OD

Claim No: SNM20D202304/C01/TANKL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDX68G**

Make & Model: JAGUAR XJ, 2.0 TSS (A)

Engine No: 281113165816204PT

Reg. Date: 19/05/2014 (Man. Year: 2013)

Chassis No: SAJAC12M2EPV65898

Colour: Beige

Odometer: 96243 km

Engine Capacity: 1999 cc

Market Value/New Car Price: S\$120,000.00

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/45 R19

Rear Tyre Size: 245/45 R19

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 02/07/2020 Present Location:

Jin Auto Services Pte Ltd (Defu)

Date Inspected: 03/07/2020 Inspected At:

Jin Auto Services Pte Ltd (Defu)  
Blk 14 Defu Lane 10, #01-410/412  
Singapore 539195

Estimated Period of Repair: 0.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :       \$120,000.00  
OMV :               \$70,375.00  
PARF Rebate (1) :     \$64,138.00  
Quota Premium Paid :   \$73,810.00  
COE Rebate (2) :     \$28,591.00  
Total Rebate (1) + (2) = : \$92,729.00

The total amount incurred will be Market Value \$120,000.00 minus Total Rebate \$92,729.00 = \$27,271.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 19 Jul 2020)

**Parts:** 143      JAGUAR XJ 2.0 TSS (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SDX68G)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**