

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20006926/KYF3Q2

Date: 29/10/2020

REFERENCE

Insured/Claimant: SHUN WAI MUN Policy No: DMPCSNW00047952000

Date of Loss: 29/06/2020 Nature of Claim: OD Claim No: SNM20D202306/C01/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ6794Z		
Make & Model:	PEUGEOT 3008 ALLURE, 1.6 E-THP EAT6 (A)	Engine No:	10FJCC2387408
Reg. Date:	15/05/2018 (Man. Year: 2017)	Chassis No:	VF3M45GZWHS318791
Colour:	Metallic Brown	Odometer:	68898 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$108,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	69,275.35	31,185.41	38,089.94	54.98
Miscellaneous Items	3,630.00	3,390.00	240.00	6.61
Labour	10,750.00	6,320.00	4,430.00	41.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	83,655.35	40,895.41	42,759.94	51.11
+ GST 7.00/7.00% (S\$)	5,855.88	2,862.68	2,993.20	51.11
Nett Amount (S\$)	89,511.23	43,758.09	45,753.14	51.11

INSPECTION

Date of Assignment:	02/07/2020	Present Location:	Goldbell Engineering Pte Ltd (Tuas)
Date Inspected:	03/07/2020	Inspected At:	Goldbell Engineering Pte Ltd (Tuas) 10 Tuas Ave 18 Singapore 638894

Estimated Period of Repair: 14.0 days

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Oct 2020)
Parts:	M1-SUV	PEUGEOT 3008 ALLURE 1.6 E-THP EAT6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ6794Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	2,395.37 F	*950.00 F
2	1		*BONNET HINGE LH	Repair	164.61 F	*- F
3	1		*BONNET HINGE RH	Repair	164.61 F	*- F
4	1		*BONNET INSULATOR	Cracked	530.26 F	*155.00 F
5	1		*FRONT GRILL	Serviceable	837.31 F	*- F
6	1		*FRONT GRILL CHROME MOULDING	Serviceable	497.86 F	*- F
7	1		*FRONT EMBLEM	Serviceable	188.02 F	*- F
8	1		*FRONT BUMPER	Bent / Cracked	2,000.12 F	*850.00 F
9	1		*FRONT BUMPER RETAINER LH	Cracked	102.77 F	*85.00 F
10	1		*FRONT BUMPER SIDE BRACKET LH	Repair	121.68 F	*- F
11	1		*FRONT BUMPER LOWER CORNER COVER LH	Cracked	535.06 F	*195.00 F
12	1		*FRONT BUMPER SPONGE	Serviceable	464.07 F	*- F
13	1		*FRONT BUMPER REINFORCEMENT	Repair	850.18 F	*- F
14	1		*FRONT SUPPORT PANEL	Repair	1,068.73 F	*- F
15	1		*LH HEADLAMP	Broken	1,969.12 F	*1,100.00 F
16	1		*LH HEADLAMP LOWER BRACKET	Repair	292.02 F	*- F
17	1		*LH FRONT FOGLAMP	Cracked	550.72 F	*180.00 F
18	1		*LH FRONT FOGLAMP COVER	Dented	447.33 F	*85.00 F
19	1		*LH FRONT FOGLAMP CHROME MOULDING	Serviceable	327.52 F	*- F
20	1		*LH FRONT FENDER	Bent	927.52 F	*255.00 F
21	1		*LH FRONT FENDER INNER PANEL	Repair	724.32 F	*- F
22	1		*LH FRONT FENDER LOGO	Necessary	118.27 F	*118.27 F
23	1		*LH FRONT FENDER INNER SHIELD	Torn	464.07 F	*115.00 F
24	1		*LH FRONT FENDER ARCH GARNISH	Distorted / Cracked	497.86 F	*200.00 F
25	1		*LH FRONT DOOR	Repair	2,601.37 F	*- F
26	1		*LH FRONT DOOR PROTECTOR	Serviceable	910.47 F	*- F
27	1		*LH CHASSIS	Repair	3,800.00 F	*- F
28	1		*LH FRONT WHEEL HOUSE	Repair	620.00 F	*- F
29	1		*RESONATOR BOX	Serviceable	498.02 F	*- F
30	1		*CONDENSOR	Serviceable	1,961.22 F	*- F
31	1		*RADIATOR	Serviceable	2,148.92 F	*- F
32	1		*RADIATOR FAN COWLING	Serviceable	753.92 F	*- F
33	1		*RADIATOR FAN MOTOR	Serviceable	457.72 F	*- F
34	1		*RADIATOR FAN BLADE	Serviceable	309.23 F	*- F
35	1		*LH SIDE ROCKER PANEL	Repair	1,068.57 F	*- F
36	1		*IMPACT SENSOR LH	Necessary	302.72 F	*350.00 F
37	1		*IMPACT SENSOR RH	Necessary	302.72 F	*350.00 F
38	1		*RH FRONT AIRBAG	Burst	2,717.46 F	*2,717.46 F
39	1		*RH FRONT AIRBAG CLOCK SPRING	Necessary	600.47 F	*680.00 F
40	1		*LH FRONT AIRBAG	Burst	3,097.37 F	*3,097.37 F
41	1		*FRONT DASHBOARD	Torn	2,763.96 F	*6,200.00 F
42	1		*AIRBAG CONTROL UNIT	Necessary	2,937.72 F	*940.00 F
43	1		*FRONT SEAT BELT LH	Jammed	927.52 F	*950.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*FRONT SEAT BELT RH	Jammed	927.52 F	*950.00 F
45	1		*FRONT SEAT BELT BUCKLE LH	Jammed	770.51 F	*480.00 F
46	1		*FRONT SEAT BELT BUCKLE RH	Jammed	770.51 F	*480.00 F
47	1		*LH ABS SENSOR	Necessary	309.38 F	*85.00 F
48	1		*LH FRONT ABSORBER	Bent	752.22 F	*145.00 F
49	1		*LH FRONT KNUCKLE ARM	Bent	706.18 F	*490.00 F
50	1		*LH FRONT LOWER ARM	Bent	675.34 F	*180.00 F
51	1		*LH FRONT WHEEL HUB	Serviceable	654.26 F	*- F
52	1		*LH FRONT WHEEL HUB BEARING	Not Necessary	396.18 F	*- F
53	1		*LH FRONT TIE ROD	Serviceable	304.27 F	*- F
54	1		*LH FRONT TIE ROD END	Serviceable	302.72 F	*- F
55	1		*LH FRONT STABILIER LINGKAGE	Serviceable	308.76 F	*- F
56	1		*LH FRONT DRIVE SHAFT	Repair	1,864.81 F	*- F
57	1		*FRONT CROSSMEMBER	Serviceable	2,114.67 F	*- F
58	1		*STEERING RACK AND PINION	Repair	3,077.22 F	*- F
59	1		*FRONT SENSOR HARNESS	Serviceable	606.21 F	*- F
<u>Supplementary #1</u>						
60	1		*REAR SEAT BELT LH	Jammed	1,071.00 F	*1,071.00 F
61	1		*REAR SEAT BELT RH	Jammed	1,071.00 F	*1,071.00 F
62	1		*REAR SEAT BELT CENTER	Serviceable	913.50 F	*- F
63	1		*REAR SEAT BELT BUCKLE LH	Jammed	493.50 F	*493.50 F
64	1		*REAR SEAT BELT BUCKLE RH	Jammed	546.00 F	*546.00 F
65	1		*FUSE BOX	Cracked	393.75 F	*393.75 F
66	1		*FUSE BOX COVER	Dented	278.25 F	*278.25 F
<u>Supplementary #2</u>						
67	1		*SUBFRAME	Bent	3,517.50 F	*3,517.50 F
<u>Supplementary #3</u>						
68	1		*GEAR CONTROL UNIT	Necessary	981.31 F	*981.31 F
69	1		*LH SIDE MIRROR ASSY	Cracked	450.00 F	*450.00 F
					Total Parts (S\$)	69,275.35 31,185.41

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	BONNET INSULATOR CLIPS (NECESSARY)	50.00	50.00
2	1	COOLANT (NOT NECESSARY)	50.00	0.00
3	1	FRONT BUMPER CLIPS (NECESSARY)	50.00	50.00
4	1	FRONT BUMPER SENSOR (SET) (MISSING)	600.00	600.00
5	1	FRONT GRILLE CLIPS (NOT NECESSARY)	30.00	0.00
6	1	FRONT LOWER BUMPER SENSOR WITH HOLDER AND SEAL (SET) (SHORTED)	1,020.00	1,020.00
7	1	FRONT NUMBER PLATE (SERVICEABLE)	50.00	0.00
8	1	LH FRONT FENDER ARCH GARNISH CLIPS (NECESSARY)	50.00	50.00
9	1	LH FRONT FENDER INNER SHEILD CLIPS (NECESSARY)	30.00	30.00
10	1	LH FRONT LIM (DENTED)	1,050.00	1,050.00
11	1	LH FRONT TYRE (CUT) (80%)	550.00	440.00
12	1	TOWING	100.00	100.00
Sub Total (S\$)			3,630.00	3,390.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, REFIX & REPAIR AFFECTED DAMAGED PARTS. INCLUDING KNOCK OUT, WELD AND STRAIGHTEN ON THE AFFECTED PARTS	New	4,800.00	3,000.00
2	TO REMOVE AND REFIT LH FRONT UNDERCARRIAGE AND CROSSMEMBER }	New	350.00	300.00
3	TO REMOVE AND REFIT FRONT UNDERCARRIAGE }	New	150.00	0.00
4	TO ROTATE AND BALANCING LH FRONT WHEEL	New	100.00	20.00
5	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	200.00	20.00
6	TO REMOVE AND REFIT FRONT SENSOR	New	120.00	60.00
7	TO RESET AIRBAG WARNING LIGHT	New	350.00	200.00
8	TO REMOVE AND REFIT RH FRONT AIRBAG }	New	350.00	200.00
9	TO REMOVE AND REFIT LH FRONT AIRBAG }	New	450.00	0.00
10	TO REMOVE AND REFIT FRONT DASHBOARD	New	350.00	300.00
11	TO REMOVE AND REFIT FRONT SEATS BELT AND BUCKLE	New	350.00	120.00
12	TO REMOVE AND REFIT AIRCON CONDENSOR	New	150.00	0.00
13	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	New	2,500.00	1,750.00
14	TO REMOVE AND RESET ABS WARNING LIGHT	New	150.00	100.00
15	TO REPAIR AND STRAIGHTEN FRONT FRAME CHASSIS	New	380.00	250.00
Gross Labour Cost (\$\$)			10,750.00	6,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >