

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 03 Jul 2020

Preliminary Advice

Vehicle No	: SLZ6794Z	Accident Date	: 29/06/2020
Make	: PEUGEOT 3008 ALLURE	Policy No.	: DMPCSNW00047952000
Assignment Date	: 02/07/2020	Excess	: S\$0.00
Date of Inspection	: 03/07/2020	Est. Duration of Repair	: 14
Inspection At	: GOLDBELL ENGINEERING PTE LTD (TUAS) 10 TUAS AVE 18 SINGAPORE 638894		

Point of Impact / General Description of Damages

The vehicle is sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	73,939.54
Revised Amount	:S\$	36,058.35
Check Items (Estimated)	:S\$	20,918.99
Total	:S\$	56,977.34

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	158,000.00
Pre-Accident Value	:S\$	108,000.00
COE / PARF Rebate	:S\$	54,251.00
Salvage Value	:S\$	
Margin for Repair (New for old value)	:S\$	103,749.00
Margin for Repair (Pre-accident value)	:S\$	53,749.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :