

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20006928/AVF3E2
Date: 09/03/2021

REFERENCE

Insured/Claimant: SUNG KANG (SONG GANG) Policy No: 1800073873
Date of Loss: 29/06/2020 Nature of Claim: OD Claim No: 8931595365SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKJ689E**
Make & Model: AUDI A5, 2.0 SPORTBACK (A) Engine No: CVK064263
Reg. Date: 10/07/2018 (Man. Year: 2018) Chassis No: WAUZZZF51JA112867
Colour: Black Odometer: 29402 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$140,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,382.00	12,693.36	7,688.64	37.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,172.00	3,872.00	4,300.00	52.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,554.00	16,565.36	11,988.64	41.99
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	27,754.00	15,765.36	11,988.64	43.20
+ GST 7.00/7.00% (S\$)	1,942.78	1,103.58	839.20	43.20
Nett Amount (S\$)	29,696.78	16,868.94	12,827.84	43.20

INSPECTION

Date of Assignment: 03/07/2020
Date Inspected: 02/07/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,142.00 FS	*1,800.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	383.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	34.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTRE	Not Necessary	185.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	215.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Not Necessary	504.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE-LH	Not Necessary	59.00 FS	*- FS
8	1		*RADIATOR GRILLE	Not Necessary	2,190.00 FS	*- FS
9	2		*SULTRASOUND SENSOR SUPPORT-LH/RH	Not Necessary	98.00 FS	*- FS
10	1		*RADIATOR GRILLE COVER-UPPER	Not Necessary	178.00 FS	*- FS
11	1		*FRONT BUMPER AIR GUIDE-LH	Cut	446.00 FS	*374.40 FS
12	1		*FRONT BUMPER CARRIER	Bent	757.00 FS	*635.60 FS
13	1		*FRONT BUMPER GUIDE SECTION-LH	Not Necessary	34.00 FS	*- FS
14	1		*FRONT BUMPER FOAM FILLER PIECE	Deformed	117.00 FS	*98.40 FS
15	1		*FRONT BUMPER COVER	Not Necessary	120.00 FS	*- FS
16	1		*CAUTION SIGN STICKER	Not Necessary	13.00 FS	*- FS
17	1		*AIRCON STICKER	Not Necessary	7.00 FS	*- FS
18	1		*LOCK CARRIER BRACKET	Cracked	129.00 FS	*108.40 FS
19	2		*LOCK CARRIER BRACKET SUPPORT-LH/RH	Not Necessary	54.00 FS	*- FS
20	1		*FRONT PARKING AID SENSOR-FRONT OUTER (NPA)	Not Necessary	0.00 FS	*- FS
21	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
22	1		*HORN-LH HIGH TONE	Not Necessary	119.00 FS	*- FS
23	1		*SPRING SHACKLE-LH	Not Necessary	27.00 FS	*- FS
24	1		*WHEEL SPOILER	Not Necessary	69.00 FS	*- FS
25	1		*WHEEL SPOILER TRIM-LH	Not Necessary	36.00 FS	*- FS
26	1		*BONNET	Dented	2,682.00 FS	*2,253.60 FS
27	1		*BONNET ATTACHMENT PARTS	Not Necessary	116.00 FS	*- FS
28	1		*BONNET IMPACT PROTECTION-LH/RH/CENTRE (3PCS)	Necessary	78.00 FS	*64.88 FS
29	1		*BONNET STRIKER-LH	Not Necessary	47.00 FS	*- FS
30	1		*BONNET LID LOCK	Not Necessary	202.00 FS	*- FS
31	1		*BONNET BOWDEN CABLE-CENTRE	Not Necessary	54.00 FS	*- FS
32	1		*LED HEADLIGHT	Cut	7,438.00 FS	*6,249.60 FS
33	1		*LIFT CYLINDER-LH	Not Necessary	187.00 FS	*- FS
34	1		*RADIATOR AIR GUIDE-LH	Not Necessary	30.00 FS	*- FS
35	1		*RADIATOR AIR GUIDE-LH	Not Necessary	15.00 FS	*- FS
36	1		*RADIATOR AIR GUIDE-UPPER	Not Necessary	15.00 FS	*- FS
37	1		*TEMPERATURE SENSOR BRACKET	Cracked	18.00 FS	*14.40 FS
38	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
39	1		*SUNDRIES	Necessary	300.00 FS	*17.60 FS
40	1		*FRONT FENDER LHS	Buckled	997.00 FS	*838.40 FS
41	1		*FRONT FENDER TOP LEDGE COVER INNER LHS	Necessary	34.00 FS	*27.92 FS
42	1		*FRONT FENDER TOP LEDGE COVER OUTER LHS	Necessary	15.00 FS	*12.16 FS
43	1		*FRONT FENDER EMBLEM TRIM LHS	Necessary	150.00 FS	*125.60 FS
44	1		*BRACKET FOR LIFT CYLINDER LHS	Cracked	14.00 FS	*11.60 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **20,382.00** **12,693.36**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER/REINSTALL FRONT BUMPER WIRE HARNESS FOR FRONT PARKING AID SYSTEM.	New	280.00	280.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND LHS HEADLIGHT.TO REPAIR LHS FRONT FENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	New	3,200.00	1,250.00
3	TO RESPRAY FRONT BUMPER,LHS FRONT FENDER AND BONNET.	New	3,500.00	1,650.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
5	TO RENEW LHS FRONT FENDER.	New	1,000.00	500.00
			Gross Labour Cost (\$)	8,172.00
				3,872.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >