

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20006929/ARA3Q2
Date: 15/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100431672
Claimant Vehicle No :	SMD4848U	Insured Vehicle No :	SKV7776C
Date of Loss:	28/06/2020	Nature of Claim:	TP
		Claim No:	3193472503SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD4848U	Engine No:	27091031876607
Make & Model:	MERCEDES-BENZ GLA180 URBAN (R18 LED), 1.6 (A)	Chassis No:	WDC1569422J627873
Reg. Date:	27/09/2019 (Man. Year: 2019)	Odometer:	23158 km
Colour:	Grey		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,665.00	1,512.00	153.00	9.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	780.00	720.00	48.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,165.00	2,292.00	873.00	27.58
Approved Total (Overridden) (S\$)		1,800.00		

(S\$)	3,165.00	1,800.00	1,365.00	43.13
+ GST 7.00/7.00% (S\$)	221.55	126.00	95.55	43.13
Nett Amount (S\$)	3,386.55	1,926.00	1,460.55	43.13
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
(S\$)		2,246.00		
Liable Amount (50.00%) (S\$)		1,123.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,125.00		

INSPECTION

Date of Assignment: 02/07/2020

Date Inspected: 02/07/2020

Inspected At: Success United Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
Singapore 417921

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR RH	Dented	1,850.00 FL	*1,680.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$)	1,850.00
					- List Item Discount on L Items 10.00/10.00% (\$)	185.00
					Total Parts (\$)	1,665.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPLACE & TRANSFER DOOR COMPONENTS	New	200.00	80.00
2	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORK & WHERE CONSISTENT TO THE ACCIDENT	New	500.00	300.00
3	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	800.00	400.00
Gross Labour Cost (\$\$)			1,500.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >