



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LIAN HAP XING KEE EDIBILE OIL TRADING PTE LTD 12 CHIN BEE CRESCENT SINGAPORE 619896 Contact No Mobile: 96772536	Cust No/Name LCV07723/ LIAN HAP XING KEE EDIBILE OIL Reg No/Reg Date SMG4842U / 21/12/201 Date In/Mileage / 0 Chassis No KNAF1416MK5024511 Engine No G4FGJH713226 Make/Model KIA/CERATO 1.6 A L S116 Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	01/07/2020/ 13:04	QUE	261 / Edwin Caina	16972

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER REPAIR RR END PNL & RHR FENDER				1100 2200.00
E PNT98000 RESPRAY RR BUMPER, RHR FENDER & RR END PNL				1260.00
E PNT88000 REMOVE & REFIT RR FLR BAORD, TRIM & CARPET TO FACILITATE REPAIR				275.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				30 50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				50 80.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR				80 100.00
M SUNDRY SUPPLY REVERSE SENSOR				220.00
M SUNDRY Sundries				20 50.00
M COVER-RR BUMPER de				651.00 00.00 651.00
M COVER-RR BUMPER LWR de				241.00 00.00 241.00
M COVER-RR BUMPER FOG LAMP, RH de				19.00 00.00 19.00
M LAMP ASSY-SIDE T/SIGNAL, RH de				181.00 00.00 181.00
M EXTN WIRING ASSY-BWS de				207.00 00.00 207.00
M BEAM-RR BUMPER de				318.00 00.00 318.00
M STAY-RR BUMPER RH de				65.00 00.00 65.00
M COVER-RR BUMPER UNDER, RH de				33.00 00.00 33.00
M BRACKET-ASSY RR BPR SIDE UPR, RH de				31.00 00.00 31.00
M LAMP ASSY-REAR COMB OUTSIDE, RH de				274.00 00.00 274.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Rose - Hp 90010068

Confirm & accepted by

SURVEYOR SIGNATURE: [Signature]DATE: 01/07/2020 @ 1020REMARKS: 5 days

Authorized signatory and company stamp

Nett 6,455.00
7% GST on 6455.00 451.85
Total Payable 6,906.85

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.