

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/FWD20006944/KSF3Q2

**Date:** 12/11/2020

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00017315  
**Claimant**  
**Vehicle No :** SLV4215M **Insured Vehicle No :** SKZ2207R  
**Date of Loss:** 02/07/2020 **Nature of Claim:** TP **Claim No:** 1202000018813

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV4215M**  
 Make & Model: TOYOTA PRIUS HYBRID, 1.8 E (A) Engine No: 2ZR8151392  
 Reg. Date: 28/12/2017 (Man. Year: 2017) Chassis No: ZVW516053283  
 Colour: Metallic Silver Odometer: 325830 km  
 Engine Capacity: 1797 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15  
 Front Left Side: Davanti 8 mm Rear Left Side: Davanti 8 mm  
 Front Right Side: Davanti 8 mm Rear Right Side: Davanti 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,296.79	3,133.70	4,163.09	57.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,660.00	1,360.00	2,300.00	62.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,956.79</b>	<b>4,493.70</b>	<b>6,463.09</b>	<b>58.99</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,600.00</b>		
<b>(S\$)</b>	10,956.79	3,600.00	7,356.79	67.14
<b>+ GST 7.00/7.00% (S\$)</b>	766.98	252.00	514.98	67.14
<b>Nett Amount (S\$)</b>	<b>11,723.77</b>	<b>3,852.00</b>	<b>7,871.77</b>	<b>67.14</b>

### INSPECTION

Date of Assignment: 03/07/2020

Date Inspected: 06/07/2020 Inspected At:

H C Auto Pte Ltd (HQ)  
 160 Sin Ming Drive, #05-09 Sin Ming  
 Auto City  
 Singapore 575722

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 11 Nov 2020)
<b>Parts:</b>	144	TOYOTA PRIUS HYBRID 1.8 E (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLV4215M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Buckled	1,211.40 FL	*1,147.80 FL
2	1		*TAIL GATE TOYOTA LOGO	Necessary	60.30 FL	*60.30 FL
3	1		*TAIL GATE PRIUS EMBLEM	Necessary	65.60 FL	*65.60 FL
4	1		*TAIL GATE HYBRID SYNERGY DRIVE EMBLEM	Necessary	51.90 FL	*51.90 FL
5	1		*TAIL GATE INNER LOCK	Repair	472.45 FL	*- FL
6	1		*TAIL GATE INNER LOCK CATCH	Repair	48.90 FL	*- FL
7	1		*TAIL GATE GARNISH	Cracked	960.00 FL	*925.60 FL
8	1		*TAIL GATE INNER TRIM	Serviceable	568.00 FL	*- FL
9	1		*REAR WEATHER-STRIP	Serviceable	353.40 FL	*- FL
10	1		*O/S TAIL LAMP TOP	Serviceable	501.30 FL	*- FL
11	1		*O/S TAIL LAMP BOTTOM	Serviceable	486.20 FL	*- FL
12	1		*REAR BUMPER TOP	Buckled	1,358.50 FL	*458.60 FL
13	1		*REAR BUMPER BOTTOM	Dented	946.20 FL	*576.30 FL
14	1		*REAR BUMPER SIDE COVER	O/s Mtg Cracked	376.00 FL	*123.70 FL
15	1		*O/S REAR BUMPER LOWER COVER (SIDE)	Serviceable	112.00 FL	*- FL
16	1		*N/S REAR BUMPER LOWER COVER (SIDE)	Serviceable	115.00 FL	*- FL
17	1		*REAR BUMPER LOWER COVER (CENTER)	Mtg Cracked	183.00 FL	*183.00 FL
18	2		*REAR BUMPER SIDE RETAINER	Serviceable	189.60 FL	*- FL
19	2		*REAR BUMPER BRACKET	Repair	174.20 FL	*- FL
20	1		*REAR BUMPER TOW COVER	Serviceable	67.90 FL	*- FL
21	1		*REAR BUMPER REINFORCEMENT	Bent	507.20 FL	*398.80 FL
22	1		*REAR NO PLATE	Serviceable	100.00 FS	*- FS
23	2		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	120.00 FS	*60.00 FS
24	2		*REAR WINDSCREEN GLASS GUM	Necessary	120.00 FS	*80.00 FS
25	1		*SET REAR REVERSE SENSOR	Serviceable	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>9,499.05</b>	<b>4,131.60</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	<b>2,202.26</b>	<b>997.90</b>
<b>Total Parts (\$)</b>	<b>7,296.79</b>	<b>3,133.70</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR CHARGES	New	1,600.00	500.00
2	TO PUTTY AND SPRAY PAINTING	New	1,400.00	600.00
3	RE-SEAL ANTI RUST	New	200.00	0.00
4	TO CHECK,REPAIR WIRING	New	120.00	20.00
5	TO TRANSFER TAIL GATE	New	120.00	60.00
6	TO REMOVE AND REFIX REAR BOTH WINDSCREEN GLASS	New	220.00	180.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,660.00</b>	<b>1,360.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >