



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2008190
INV Date 08/12/2020
Reference CC4/FCI20006946/Apa3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SLQ 4759L
Insured Veh. SHD 3008T
Claim No. D20002644MFSH
Policy No. D-20094922MFSH
Accident Date 02/07/2020
Inspection Date 07/07/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20006946/Apa3q2

36 ROBINSON ROAD
#16-01 CITY HOUSES SINGAPORE 068877

Date : 08-12-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3008T	Veh. Inspected	SLQ 4759L
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20002644MFSH	Excess (\$)	0.00
Assign From	RACHEL WU	Assign Date	03/07/2020

2. Vehicle Particulars & Condition

Make & Model	KIA CERATO K3	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KNAFX411MH5721032	Colour	GREY
Odometer	58046	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	NEXEN	6 mm
L/H Front Tyre	205/55 R16	NEXEN	6 mm
R/H Rear Tyre	205/55 R16	NEXEN	6 mm
L/H Rear Tyre	205/55 R16	NEXEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	02/07/2020	Inspection Date	07/07/2020
Survey held at	CYCLE & CARRIAGE.FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 4759L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SET REVERSE SENSOR (SN)	DAMAGED	280.00	280.00
1	C&C LOGO (SN)	NECESSARY	50.00	50.00
1	COVER -REAR BUMPER (SN)	DISTORTED	688.00	688.00
1	COVER -REAR BUMPER (SN)	DISTORTED	347.00	347.00
1	LH REFLECTOR REFLEX (SN)	CUT	99.00	99.00
10	CLIP -BUMPER (SN)	NECESSARY	20.00	20.00
1	RH SIDE BRACKET -RE (SN)	NOT NECESSARY	29.00	-
1	LH SIDE BRACKET -RE (SN)	NECESSARY	29.00	29.00
1	COVER -RR BPR UNDER (SN)	NOT NECESSARY	42.00	-
1	BEAM -REAR BUMPER (SN)	NOT NECESSARY	318.00	-
2	BRACKET -REAR BEAM (SN)	NOT NECESSARY	10.00	-
1	BRACKET -REAR BEAM (SN)	NOT NECESSARY	5.00	-
1	LH BRACKET -REAR BE (SN)	NOT NECESSARY	3.00	-
1	RH BRACKET -REAR BE (SN)	NOT NECESSARY	3.00	-
1	LH STAY -REAR BUMPE (SN)	NOT NECESSARY	120.00	-
1	RH STAY -REAR BUMPE (SN)	NOT NECESSARY	120.00	-
1	PANEL ASSY -BACK (SN)	TO REPAIR SEE LABOUR	274.00	-
1	TRUNK LID PANEL ASSY (SN)	TO REPAIR SEE LABOUR	1,570.00	-
1	WEATHERSTRIP -TRUNK (SN)	NOT NECESSARY	100.00	-
1	LATCH ASSY -TRUNK (SN)	NOT NECESSARY	112.00	-
1	KIA SUB LOGO ASSY (SN)	NECESSARY	37.00	37.00
1	EMBLEM -CERATO (SN)	NECESSARY	35.00	35.00
1	EMBLEM K3 (SN)	NECESSARY	15.00	15.00
1	LH INSIDE LAMP ASSY (SN)	NOT NECESSARY	710.00	-
1	LH LAMP ASSY -REAR (SN)	NOT NECESSARY	788.00	-
			5,804.00	1,600.00
	<u>LABOUR</u>			
	TO REPLACE REAR REVERSE CAMERA LENS .	NOT NECESSARY	350.00	-
	DIAGNOSTIC /SCANNING .		250.00	250.00

Report Ref No. CC4/FCI20006946/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS.		100.00	80.00
	TO TRANSFER TRUNK LID COMPONENT & MECHANISM PARTS.	NOT NECESSARY	600.00	-
	TO REMOVE AND REINSTALL TRIMMING AND CAPERTING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS.		600.00	300.00
	TO REPLACE TRUNK LID PNL,REAR BUMPER ,REAR REINFORCEMENT ,ETC.REPAIR LHR OTR QTR PNL.CUT & RE-WELD REAR END PANEL		3,600.00	1,200.00
	STRAIGHTEN ,PEFORM ,ALIGN ON REAR ACCIDENT AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF PANEL ASSY -BACK AND TRUNK LID PANEL ASSY .			
	TO APPLY SEALANT KIT ON NEW PANEL.	NOT NECESSARY	300.00	-
	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS.		2,100.00	1,680.00
			7,900.00	3,510.00
GRAND TOTAL			13,704.00	5,110.00
RECOMMENDED COST OF REPAIRS				5,110.00

Report Ref No. CC4/FCI20006946/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLQ 4759L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLQ 4759L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

