

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20006958/GTF3E2

Date: 17/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900129453
Claimant Vehicle No : SMG5180P	Insured Vehicle No :	SMM9841H
Date of Loss: 25/06/2020	Nature of Claim:	TP Claim No: 8455543957SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG5180P	
Make & Model:	PORSCHE 911 CARRERA, 3.4 PDK (991 Series) (A)	Engine No: D03180
Reg. Date:	30/11/2012 (Man. Year: 2012)	Chassis No: WP0ZZZ99ZDS100956
Colour:	Blue	Odometer: 90627 km
Engine Capacity:	3436 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35Z R20	Rear Tyre Size:	245/35Z R20
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	03/07/2020	
Date Inspected:	14/07/2020 Inspected At:	Sze Kang Automobile Spraying Services (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #03-17 Singapore 568047
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRT NUMBER PLATE	Cracked	0.00 F	*- F	
2	1		*FRT NUMBER PLATE BASE	Cracked	0.00 F	*- F	
3	1		*FRT BUMPER	* Check	0.00 F	*- F	
4	1		*FRT BUMPER TOW COVER	* Check	0.00 F	*- F	
5	2		*FRT BUMPER SIDE RETAINER	Deformed	0.00 F	*- F	
6	1		*FRT BUMPER SENSOR	Damaged	0.00 F	*- F	
7	1		*FRT BUMPER LAMP	* Check	0.00 F	*- F	
8	1		*FRT RH HEADLAMP ASSY	* Check	0.00 F	*- F	
					Total Parts (\$\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >