

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/LCR18001078/ADA3Q2-1

**Date:** 27/07/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995060

**Claimant**  
**Vehicle No :** SGD4011M **Insured Vehicle No :** SLE4731D

Date of Loss: 09/01/2018 Nature of Claim: TP Claim No: 8309126652SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGD4011M</b>		
Make & Model:	NISSAN LATIO, 1.5 L (A)	Engine No:	HR15248443A
Reg. Date:	23/07/2008 (Man. Year: 2007)	Chassis No:	JN1BAAC11Z0009031
Colour:	Champagne	Odometer:	136595 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,114.92	0.00	1,114.92	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	500.00	630.00	55.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>2,244.92</b>	<b>500.00</b>	<b>1,744.92</b>	<b>77.73</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	157.14	35.00	122.14	77.73
<b>Nett Amount (\$\$)</b>	<b>2,402.06</b>	<b>535.00</b>	<b>1,867.06</b>	<b>77.73</b>
<b>+ Loss of Use (3.0 x S\$70.00/day) (\$\$)</b>		210.00		
<b>+ Doc/Search Fee (\$\$)</b>		8.00		
<b>Nett Liability (\$\$)</b>		<b>753.00</b>		

### INSPECTION

Date of Assignment: 17/01/2018

Date Inspected: 23/01/2018 Inspected At:

Precise Auto Service (HQ)  
No 1 Kaki Bukit Ave 6, #02-34/36  
Singapore 417883

Estimated Period of Repair: 2.0 days

**Adjuster:** ADRIAN LING

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR ASSY -RH	Repair	1,143.80 FN	* - FN
2	1		*REAR DOOR FRAME BLACK STICKER	Not Necessary	95.00 FN	* - FN

F=Franchise part. N=NettItemDisc.

<b>Sub Total (S\$)</b>	<b>1,238.80</b>	<b>0.00</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (S\$)</b>	123.88	0.00
<b>Total Parts (S\$)</b>	<b>1,114.92</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RESPRAY AFFECTED AREAS	New	500.00	400.00
2	TO REMOVE & REFIT REAR RH DOOR MECHANISM	New	180.00	0.00
3	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR FRONT RH DOOR & ALIGNED ALL PARTS	New	450.00	100.00
<b>Gross Labour Cost (S\$)</b>			<b>1,130.00</b>	<b>500.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**