

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD20005170/QSF3E2-1
Date: 21/07/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00015373-01
Claimant Vehicle No : SKV7585L **Insured Vehicle No :** SKX3033D
 Date of Loss: 11/04/2020 Nature of Claim: TP Claim No: 1202000016328

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKV7585L**
 Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4022033
 Reg. Date: 30/09/2015 (Man. Year: 2015) Chassis No: RU11102032
 Colour: Black Odometer: 176457 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,596.20	3,467.65	6,128.55	63.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,540.00	1,540.00	2,000.00	56.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,136.20	5,007.65	8,128.55	61.88
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	13,136.20	4,000.00	9,136.20	69.55

INSPECTION

Date of Assignment: 13/04/2020
 Date Inspected: 14/04/2020 Inspected At: Hong Motor Service (HQ)
 Blk 5035 Ang Mo Kio Industrial Park 2, (off Ave 3) #01-365 Singapore 569538
 Singapore 569538
 Estimated Period of Repair: 4.0 days

Adjuster: OI SUN PIN

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Jul 2020)
Parts: M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKV7585L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,436.00 F	*1,100.00 FL
2	1		*TAILGATE OUTER GARNISH	Serviceable	285.00 F	*- FL
3	1		*TAILGATE LOGO	Serviceable	87.00 F	*- FL
4	1		*TAILGATE EMBLEM VEZEL	Necessary	86.20 F	*86.20 FL
5	1		*TAILGATE REFLECTOR	N/S Cracked	790.00 F	*395.00 FL
6	1		*TAILGATE INNER LOCK	Jammed	145.00 F	*145.00 FL
7	1		*TAILGATE LOCK SENSOR	Serviceable	185.00 F	*- FL
8	1		*TAILGATE TRIMBOARD	Crumpled	325.00 F	*325.00 FL
9	1		*TAILGATE WEATHERTRIP	Crumpled	165.00 F	*165.00 FL
10	2		*TAILGATE HYDRAULIC DAMPER	Serviceable	250.00 F	*- FL
11	2		*REAR W/SCREEN MOULDING SIDE	Necessary	164.00 F	*80.00 FL
12	1		*REAR W/SCREEN MOULDING TOP	Necessary	104.00 F	*40.00 FL
13	1		*REAR W/SCREEN MOULDING BOTTOM	Necessary	104.00 F	*40.00 FL
14	1		*SMART BUZZER	Shorted	195.00 F	*195.00 FL
15	1		*TAILLAMP	N/S Scratched / O/S Serviceable	1,178.00 F	*450.00 FL
16	1		*REAR BUMPER	Dented	980.00 F	*850.00 FL
17	1		*REAR BUMPER SIDE RETAINER	Broken (1Pc Only)	144.00 F	*72.00 FL
18	1		*REAR BUMPER REFLECTOR	Cracked (1Pc Only)	254.00 F	*127.00 FL
19	2		*REAR BUMPER SIDE GARNISH	Repair	420.00 F	*- FL
20	1		*REAR END PANEL	Repair	650.00 F	*- FL
21	1		*REAR END PANEL TOP GARNISH	Serviceable	184.00 F	*- FL
22	1		*SUNDRIES	Serviceable	50.00 FS	*- FS
23	2		*SET TAILGATE REFLECTOR CLIPS	Necessary	50.00 FS	*20.00 FS
24	2		*TAILGATE REFLECTOR SEAL	Necessary	60.00 FS	*30.00 FS
25	1		*SET TAILGATE OUTER GARNISH CLIPS	Serviceable	40.00 FS	*- FS
26	1		*TAILGATE SEALANT	Necessary	100.00 FS	*30.00 FS
27	1		*SET TAILGATE TRIMBOARD CLIPS	Necessary	40.00 FS	*30.00 FS
28	1		*SET TAILGATE WINDSCREEN CLIPS	Serviceable	45.00 FS	*- FS
29	1		*TAILGATE WINDSCREEN PRIMER AND CLEANER	Serviceable	100.00 FS	*- FS
30	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
31	1		*TAILGATE WINDSCREEN INNER SEAL	Serviceable	100.00 FS	*- FS
32	1		*TAILGATE SEALANT	Repeated	100.00 FS	*- FS
33	2		*SET TAILLAMP CLIPS	Necessary	50.00 FS	*20.00 FS
34	1		*TAILLAMP SEAL	Necessary (1Pc Only)	60.00 FS	*15.00 FS
35	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
36	2		*SET REAR BUMPER SIDE GARNISH CLIP	Serviceable	50.00 FS	*- FS
37	2		*SET REAR FENDER ARCH GARNISH CLIP	Serviceable	60.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
38	1		*REAR END PANEL SEALANT	Serviceable	100.00 FS	*- FS	
39	1		*REVERSE SENSOR WITH MODULE	Shorted	300.00 FS	*200.00 FS	
					Sub Total (\$)	9,596.20	4,485.20
					- List Item Discount on L Items 0.00/25.00% (\$)	0.00	1,017.55
					Total Parts (\$)	9,596.20	3,467.65

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	1,500.00	600.00
2	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS	New	80.00	30.00
3	TO REMOVE AND REFIT INTERIOR UPHOLSTERY TO FACILITATE THE REPAIR	New	200.00	50.00
4	TO REMOVE AND REFIT TAILGATE COMPONENT TO REPLACE TAILGATE, CHECK AND RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE	New	100.00	60.00
5	TO REMOVE AND REFIT TAILGATE WINDSCREEN TO FACILITATE THE REPAIR	New	180.00	120.00
6	TO MEASURE, DRILL HOLES ON REPLACED REAR BUMPER, POSITION AND INSTALL REVERSE SENSOR, CHECK AND TEST ON THE DISTANCE AND FUNCTIONS	New	80.00	30.00
7	TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION	New	200.00	50.00
8	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY TAILGATE, REAR BUMPER, REAR BUMPER SIDE GARNISH, REAR END PANEL AND OTHER AFFECTED AREA / PANEL	New	1,200.00	600.00
Gross Labour Cost (S\$)			3,540.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >