

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/III20007000/UGS3Q2

**Date:** 24/09/2020

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MPC0002331_01
<b>Claimant Vehicle No :</b>	FBE5013E	<b>Insured Vehicle No :</b>	SKN266X
Date of Loss:	20/06/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0001153

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBE5013E	Engine No:	5PV031625
Make & Model:	YAMAHA RXZ, 133cc (M)	Chassis No:	PMY5PV100A0031625
Reg. Date:	06/05/2010 (Man. Year: 2010)	Odometer:	90227 km
Colour:	Yellow		
Engine Capacity:	133 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	80-90-18	Rear Tyre Size:	80-90-18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,592.70	2,068.00	524.70	20.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	520.00	335.00	185.00	35.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,112.70</b>	<b>2,403.00</b>	<b>709.70</b>	<b>22.80</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,900.00</b>		
<b>Nett Amount (S\$)</b>	<b>3,112.70</b>	<b>1,900.00</b>	<b>1,212.70</b>	<b>38.96</b>
<b>+ Loss of Use (7.0 x S\$20.00/day) (S\$)</b>		140.00		
<b>Nett Liability (S\$)</b>		<b>2,040.00</b>		

### INSPECTION

Date of Assignment:	06/07/2020	
Date Inspected:	06/07/2020 Inspected At:	Erofia Motor Trading Pte Ltd (KAKI BUKIT)
		1 KAKI BUKIT AVE 6 #02-62
		Singapore 417883
Estimated Period of Repair:	5.0 days	

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 01 Sep 2020)	
<b>Parts:</b>	N/A	YAMAHA RXZ 133cc (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBE5013E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Broken	65.00 FL	*65.00 FL
2	2		*FORK INNER TUBES	Bent / Twisted	210.00 FL	*210.00 FL
3	2		*FORK OUTER TUBES	Twisted	220.00 FL	*220.00 FL
4	1		*FORK UNDER BRACKET	Bent	145.00 FL	*145.00 FL
5	1		*FRONT SPORT RIM	Bent	250.00 FL	*250.00 FL
6	1		*FRONT RIM SHAFT	Bent	38.00 FL	*38.00 FL
7	1		*TOP COWLING	Broken	85.00 FL	*85.00 FL
8	1		*WINDSHIELD	Broken	32.00 FL	*32.00 FL
9	1		*LAMP ASSY	Bent	50.00 FL	*50.00 FL
10	1		*HEADLAMP	Broken	70.00 FL	*70.00 FL
11	2		*FRONT SIGNALS	Broken	80.00 FL	*80.00 FL
12	1		*HANDLE -BAR-L/H	Bent	68.00 FL	*68.00 FL
13	1		*HANDLE -BAR END	Scratched	18.00 FL	*18.00 FL
14	1		*CLUTCH LEVER	Scratched	25.00 FL	*25.00 FL
15	1		*METER ASSY	Distorted	480.00 FL	*480.00 FL
16	1		*FRONT FOOTREST -L/H	Cut	32.00 FL	*32.00 FL
17	1		*FRONT FOOTREST BRACKET -L/H	Serviceable	55.00 FL	*- FL
18	1		*GEAR PEDAL	Bent	32.00 FL	*32.00 FL
19	1		*REAR FOOTREST -L/H	Serviceable	28.00 FL	*- FL
20	1		*REAR TAILBOARD -L/H	Repair	70.00 FL	*- FL
21	1		*MIRROR ASSY	Cut	40.00 FL	*40.00 FL
22	1		*FORK TOP HOLDER	Bent	90.00 FL	*90.00 FL
23	1		*KEY LOCK ASSY	Not Necessary	160.00 FL	*- FL
24	1		*SET NUMBER PLATE	Bent	28.00 FS	*10.00 FS
25	2		*FORK OILS	Necessary	30.00 FS	*30.00 FS
26	2		*FORK OIL SEALS	Necessary	56.00 FS	*56.00 FS
27	1		*SET STEERING CONE	Necessary	75.00 FS	*75.00 FS
28	1		*E.R.P IU	Not Necessary	175.00 FS	*- FS
29	1		*FRONT TYRE (50%)	Punctured	100.00 FS	*50.00 FS
30	1		*HORN	Dented	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,827.00</b>	<b>2,271.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	234.30	203.00
<b>Total Parts (\$\$)</b>	<b>2,592.70</b>	<b>2,068.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	60.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	380.00	300.00
<b>Gross Labour Cost (\$\$)</b>			<b>520.00</b>	<b>335.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >