

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007002/KDA3Q2

Date: 22/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100329245
Claimant		
Vehicle No : SMH4248E	Insured Vehicle No :	SJN926L
Date of Loss: 03/07/2020	Nature of Claim: TP	Claim No: 0879162008SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH4248E		
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Engine No:	2ZRV401360
Reg. Date:	05/05/2017 (Man. Year: 2017)	Chassis No:	NMTKZ3BX60R005144
Colour:	Metallic Blue	Odometer:	136554 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Dunlop 2 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 2 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,165.74	4,429.19	1,736.55	28.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,495.00	1,640.00	855.00	34.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,660.74	6,069.19	2,591.55	29.92
Approved Total (Overridden) (S\$)		4,850.00		
(S\$)	8,660.74	4,850.00	3,810.74	44.00
+ GST 7.00/7.00% (S\$)	606.25	339.50	266.75	44.00
Nett Amount (S\$)	9,266.99	5,189.50	4,077.49	44.00
+ Car Rental (6.0 x S\$120.00/day) (S\$)		720.00		
Nett Liability (S\$)		5,909.50		

INSPECTION

Date of Assignment: 06/07/2020

Date Inspected: 06/07/2020 Inspected At:

Kum Chew Motor Workshop (160 Sin Ming)
(HQ)
160 Sin Ming Drive, #05-08 Sin Ming
Autocity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Mtg Cracked	382.98 FL	*382.98 FL
2	12		*REAR BUMPER CLIPS	Necessary	69.60 FL	*69.60 FL
3	1		*REAR BUMPER RETAINER	Serviceable	107.71 FL	*- FL
4	1		*REAR BUMPER BRACKET -RH	Repair	45.60 FL	*- FL
5	1		*REAR FENDER -RH	Repair	731.04 FL	*- FL
6	1		*REAR FENDER DUST COVER -R/H	Serviceable	93.09 FL	*- FL
7	8		*REAR FENDER DUST COVER CLIPS	Not Necessary	46.40 FL	*- FL
8	1		*REAR FENDER GARNISH -RH	Dented / Cut	261.25 FL	*261.25 FL
9	7		*REAR FENDER GARNISH CLIPS-RH	Necessary	40.60 FL	*40.60 FL
10	1		*REAR DOOR -RH	Bent / Warped	1,168.25 FL	*1,168.25 FL
11	1		*REAR DOOR FRAME STICKER -R/H	Necessary	67.40 FL	*67.40 FL
12	1		*REAR DOOR GARNISH -R/H	Missing	183.95 FL	*183.95 FL
13	12		*REAR DOOR GARNISH CLIPS-R/H	Necessary	69.60 FL	*69.60 FL
14	1		*ROCKER GARNISH -RH	Cracked	508.95 FL	*508.95 FL
15	1		*ROCKER GARNISH BRACKET-RH	Serviceable	47.30 FL	*- FL
16	16		*ROCKER GARNISH CLIPS -R/H	Necessary	92.80 FL	*92.80 FL
17	1		*REAR LOWER SUPPORT ARM -R/H	Distorted	204.22 FL	*204.22 FL
18	1		*REAR LOWER ARM -RH	Bent	315.77 FL	*315.77 FL
19	1		*REAR KNUCKLE ARM -RH	Bent	695.33 FL	*602.50 FL
20	1		*REAR KNUCKLE ARM BEARING-RH	Necessary	681.30 FL	*581.10 FL
21	1		*REAR SUSPENSION -R/H	Bent	190.74 FL	*190.74 FL
22	1		*REAR UPPER ARM-R/H	Distorted	301.03 FL	*301.03 FL
23	1		*REAR TRAILING ARM -R/H	Bent	331.52 FL	*331.52 FL
24	1		*REAR TRAILING ARM BRACKET-R/H	Serviceable	181.40 FL	*- FL
25	1		*REAR TRAILING ARM BRACKET TOP COVER-R/H	Serviceable	241.75 FL	*- FL
26	1		*REAR STABILIZER BAR LINK -RH	Serviceable	148.08 FL	*- FL
27	1		*REAR SPORT RIM -RH	Dented	480.00 FS	*400.00 FS
28	1		*REAR TYRE -R/H	Serviceable	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,967.66	5,772.26
- List Item Discount on L Items 25.00/25.00% (\$)	1,801.92	1,343.07
Total Parts (\$)	6,165.74	4,429.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGE	New	150.00	150.00
2	TO PULL ,KNOCK ON ACCIDENT PORTION & CHARGE ABOVE PART	New	580.00	500.00
3	TO SPRAY & PAINT ON ACCIDENT PORTION	New	850.00	600.00
4	TO DISMANTLE & REPLACE UNDERCARRIAGE	New	450.00	200.00
5	TO COMPUTER WHEEL ALIGNMENT	New	150.00	60.00
6	TO DISMANTLE ,REFIX TYRE & BALANCING	New	35.00	20.00
7	TO ANTI-RUST AFFECTED AREAS	New	80.00	30.00
8	TO CHECK WIRING FUNCTIONS	New	50.00	20.00
9	TO DISMANTLE /REMOVE REAR R/H DOOR ,REFIX DOOR GLASS DOOR GEAR MOTOR AND DOOR MECHANISM	New	150.00	60.00
Gross Labour Cost (\$\$)			2,495.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >