

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jan 2020 Edit Reg		06 Jul 2020 00:00 Edit Adj Rpt	S\$6,500.00 Edit Estimates	S\$6,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Tan Yew Chuan Eber , ID: S7045812H									
Main Claimant: SOH KOK CHONG									
Vehicle Reg. No.: SJL3587Y		Date of Loss: 31/12/2019 13:00 - :59 [133 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 1202000000112		Policy/Cover Note No.: PNPV2019-00011815 (Third Party Only) Coverage: 05/08/2019 - 04/08/2020							
Vehicle Reg. No. (Insured): SLW3184U		Policy No. (Claimant): Excess:							
Repairer: Topmax Auto Body Shop (HQ) Blk 3007 Ubi Road 1 #01-410, 408701 Ubi - Tel: 90622722									
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 08/07/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
FWD_SG (06/07/2020): PAPER SURVEY									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJL3587Y (1202000000112)**

[SLW3184U]

TP

SOH KOK CHONG

Dec 31 2019 1:00PM

[Tan Yew Chuan Eber]

Topmax Auto Body Shop

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Photos/Images					
			3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/01/20 18:26	General View		Load JPG	
2	13/01/20 18:26	General View		Load JPG	
3	13/01/20 18:26	General View		Load JPG	
4	13/01/20 18:26	General View		Load JPG	
5	13/01/20 18:26	General View		Load JPG	
6	13/01/20 18:26	General View		Load JPG	
7	13/01/20 18:26	General View		Load JPG	
8	13/01/20 18:26	General View		Load JPG	
9	13/01/20 18:26	General View		Load JPG	
10	13/01/20 18:26	General View		Load JPG	
11	13/01/20 18:26	General View		Load JPG	
12	13/01/20 18:26	General View		Load JPG	
13	13/01/20 18:26	General View		Load JPG	
14	13/01/20 18:26	General View		Load JPG	
15	13/01/20 18:26	General View		Load JPG	
16	13/01/20 18:26	General View		Load JPG	
17	13/01/20 18:26	General View		Load JPG	
18	13/01/20 18:26	General View		Load JPG	
19	13/01/20 18:26	General View		Load JPG	
20	13/01/20 18:26	General View		Load JPG	
21	13/01/20 18:46	After Repair Photo		Load JPG	
22	13/01/20 18:46	After Repair Photo		Load JPG	
23	13/01/20 18:46	After Repair Photo		Load JPG	
24	13/01/20 18:46	After Repair Photo		Load JPG	
25	13/01/20 18:46	After Repair Photo		Load JPG	
26	13/01/20 18:46	After Repair Photo		Load JPG	
27	13/01/20 18:46	After Repair Photo		Load JPG	
28	13/01/20 18:46	After Repair Photo		Load JPG	
29	13/01/20 18:46	After Repair Photo		Load JPG	
30	13/01/20 18:46	After Repair Photo		Load JPG	
31	13/01/20 18:46	After Repair Photo		Load JPG	
32	13/01/20 18:46	After Repair Photo		Load JPG	
33	13/01/20 18:46	After Repair Photo		Load JPG	
34	13/01/20 18:46	After Repair Photo		Load JPG	
35	13/01/20 18:46	After Repair Photo		Load JPG	
Documentation					
			1 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/07/20 08:22	PRS INVOICE		Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	03/01/20 12:08	PRI - RS SOLOMON LLC		Load PDF	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
2	03/01/20 12:08	SLW3184U OI GIA		Load PDF	
3	03/01/20 12:08	SJL3587Y TP GIA		Load PDF	
4	06/07/20 14:07	TP SJL3587Y_SURVEY REPORT PART1		Load PDF	
5	06/07/20 14:07	TP SJL3587Y_SURVEY REPORT PART2		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/FWD20000136/T1YF3S2-1**Date:** 23/07/2020REFERENCE

Handling Insurer:	FWD Singapore Pte. Ltd.	Policy No:	PNPV2019-00011815
Claimant Vehicle No :	SJL3587Y	Insured Vehicle No :	SLW3184U
Date of Loss:	31/12/2019	Nature of Claim:	TP
		Claim No:	1202000000112

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL3587Y	Engine No:	L13A4094785
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61085483
Reg. Date:	25/11/2008 (Man. Year: 2008)	Odometer:	174684 km
Colour:	White		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,626.56	5,234.88	2,391.68	31.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,360.00	2,870.00	1,490.00	34.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,986.56	8,104.88	3,881.68	32.38
Approved Total (Overridden) (S\$)		6,500.00		
Nett Amount (S\$)	11,986.56	6,500.00	5,486.56	45.77

INSPECTION

Date of Assignment:	06/07/2020		
Date Inspected:	02/01/2020	Inspected At:	Topmax Auto Body Shop (HQ) Blk 3007 Ubi Road 1 #01-410 Singapore 408701
Estimated Period of Repair:	8.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jul 2020)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL3587Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN GLASS MOULING	Necessary	79.50 FL	*79.50 FL
2	1		*REAR TAILGATE	Bent	966.00 FL	*796.60 FL
3	1		*REAR TAILGATE INNER TRIM BOARD	Deformed	254.50 FL	*254.50 FL
4	1		*REAR TAILGATE LOCK	Bent	183.50 FL	*183.50 FL
5	1		*REAR TAILGATE RUBBER	Necessary	154.10 FL	*154.10 FL
6	2		*REAR TAILLAMPS	Cracked	1,052.20 FL	*793.60 FL
7	1		*REAR END PANEL	Bent	553.40 FL	*492.90 FL
8	1		*REAR END PANEL INNER GARNISH	Deformed	213.40 FL	*213.40 FL
9	1		*REAR BUMPER	Deformed	660.90 FL	*555.30 FL
10	2		*REAR BUMPER SIDE RETAINERS	Necessary	61.00 FL	*61.00 FL
11	1		*REAR BUMPER TOW HOOK COVER	Deformed	38.50 FL	*38.50 FL
12	1		*REAR FLOOR PANEL	Buckled	965.00 FL	*637.40 FL
13	1		*REAR FLOOR BOARD	Deformed	280.40 FL	*280.40 FL
14	1		*REAR SPARE TYRE TOOL SPONGE TRAY	Deformed	289.50 FL	*289.50 FL
15	1		*REAR EXHAUST SILENCER	Repair	580.70 FL	*- FL
16	2		*REAR EXHAUST MOUNTINGS	Repair	57.00 FL	*- FL
17	1		*REAR EXHAUST HEAT SHIELD	Bent	105.90 FL	*105.90 FL
18	1		*REAR O/S FENDER	Repair	891.50 FL	*- FL
19	2		*REAR FENDER INNER TRIM BOARDS	Deformed	671.20 FL	*570.00 FL
20	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*50.00 FS
21	1		*REAR TAILGATE INNER TRIM SOUND INSULATOR	Necessary	250.00 FS	*200.00 FS
22	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
23	1		*SET REAR REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
24	1		*REAR FLOOR PANEL SOUND INSULATOR	Necessary	450.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,238.20	6,336.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,611.64	1,101.22

Total Parts (\$\$)	7,626.56	5,234.88
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIT, REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING.	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES, INNER TRIM TO ASSIST REPAIR.	New	150.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR.	New	120.00	30.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY TO ASSIST REPAIR.	New	80.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	New	180.00	120.00
6	TO REMOVE, REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS.	New	150.00	80.00
7	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.	New	200.00	90.00
8	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIR INCLUDING CUT AND WELD; RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	1,800.00	1,200.00
9	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.	New	1,600.00	1,200.00
Gross Labour Cost (\$\$)			4,360.00	2,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >