

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20007017/APA3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800028854
Claimant		
Vehicle No : SMQ2585Y	Insured Vehicle No :	SLX2044S
Date of Loss: 23/06/2020	Nature of Claim: TP	Claim No: 7932045926SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ2585Y		
Make & Model:	HYUNDAI SANTA FE, 2.4 (A)	Engine No:	G4KJKA449735
Reg. Date:	05/11/2019 (Man. Year: 2019)	Chassis No:	KMHS381DSL239290
Colour:	Black	Odometer:	4428 km
Engine Capacity:	2359 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R19	Rear Tyre Size:	235/55R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,334.64	2,674.64	6,660.00	71.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,020.00	930.00	3,090.00	76.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,354.64	3,604.64	9,750.00	73.01
Approved Total (Overridden) (S\$)		2,850.00		
(S\$)	13,354.64	2,850.00	10,504.64	78.66
+ GST 7.00/7.00% (S\$)	934.82	199.50	735.32	78.66
Nett Amount (S\$)	14,289.46	3,049.50	11,239.96	78.66
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		3,378.50		
Global Sum Settlement (S\$)		3,370.00		

INSPECTION

Date of Assignment:	07/07/2020	
Date Inspected:	07/07/2020 Inspected At:	Cas Garage Pte Ltd (HQ)
		No.1, Kaki Bukit Ave 6, #02-22
		Autobay
		Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	2,327.00 FL	*- FL
2	1		*TAILGATE OUTER GARNISH	Not Necessary	298.70 FL	*- FL
3	1		*TAILGATE LOGO	Necessary	102.50 FL	*102.50 FL
4	1		*TAILGATE SANTA EE EMBLEM	Necessary	98.70 FL	*98.70 FL
5	1		*TAILGATE HTRAC EMBLEM	Necessary	89.50 FL	*89.50 FL
6	2		*TAILGATE LAMPS	Not Necessary	970.40 FL	*- FL
7	1		*TAILGATE WEATHERSTRIP	Not Necessary	265.80 FL	*- FL
8	1		*TAILGATE INNER TRIM	Not Necessary	402.80 FL	*- FL
9	2		*TAILAMPS	Not Necessary	1,165.20 FL	*- FL
10	1		*REAR END PANEL	Repair	795.20 FL	*- FL
11	1		*REAR END PANEL TOP GARNISH	Not Necessary	245.30 FL	*- FL
12	1		*REAR BUMPER UPPER	Deformed	502.20 FL	*502.20 FL
13	1		*REAR BUMPER LOWER	Deformed	592.10 FL	*592.10 FL
14	1		*REAR BUMPER REINFORCEMENT	Cracked	345.70 FL	*345.70 FL
15	1		*REAR BUMPER LOWER SKID PLATE	Deformed	235.80 FL	*235.80 FL
16	2		*REAR BUMPER SIDE RETAINERS	Necessary	185.00 FL	*185.00 FL
17	1		*REAR BUMPER SIDE CHROME GARNISH	N/S Cut	411.60 FL	*205.80 FL
18	1		*REAR BUMPER LOWER CENTRE MOLDING	Torn	98.70 FL	*98.70 FL
19	1		*REAR BUMPER TOWING COVER	Not Necessary	58.20 FL	*- FL
20	1		*REAR BUMPER REFLECTORS	N/S Cracked	757.20 FL	*378.60 FL
21	4		*REAR REVERSE SENSOR	Damaged (2 PCS ONLY)	942.40 FL	*471.20 FL
22	1		*REAR EXHAUST TIP GARNISH	Not Necessary	165.80 FL	*- FL
23	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
24	2		*END PANEL SEALANTS	Not Necessary	80.00 FS	*- FS
25	2		*WINDSCREEN SEALANTS	Not Necessary	80.00 FS	*- FS
26	1		*SET REAR REVERSE SENSORS	Repair	250.00 FS	*- FS
27	1		*SET REAR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 11,545.80 3,335.80
- List Item Discount on L Items 20.00/20.00% (\$\$) 2,211.16 661.16

Total Parts (\$\$) 9,334.64 2,674.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS ,REPLACED ,BEAT ,WELD ,REALIGN AND ALIGNE ALL PARTS	New	1,800.00	400.00
2	TO RESPRAY AFFECTED AREAS	New	1,600.00	400.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	50.00
4	TO REMOVE AND REPLACE SENSORS AND DISTANCE SETTLING	New	150.00	50.00
5	TO CONDUCT WIRING CHECK ON REAR TAILAMPS	New	120.00	30.00
6	TO REMOVE/REFIT INTERIOR UPHOLSTERY	New	150.00	0.00
Gross Labour Cost (\$\$)			4,020.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >