Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007019/UPA3Q2

Date: 14/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993961

Claimant Vehicle No: FBP6615D Insured Vehicle No: GBC1836J

Date of Loss: 29/06/2020 Nature of Claim: TP Claim No: 6895523372SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBP6615D

Make & Model: YAMAHA NMAX155, 155cc Engine No: G3H6E0013747

Reg. Date: 17/05/2019 (Man. Year: 2019) Chassis No: MH3SG431000011017

Colour: White Odometer: 15575 km

Engine Capacity: 155 cc
Market Value/New Car
N/A

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110-70 -13 Rear Tyre Size: 130-70-13
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,157.80	1,793.00	2,364.80	56.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	511.00	250.00	261.00	51.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,668.80	2,043.00	2,625.80	56.24
Approved Total (Overridden) (S\$)		1,600.00		
Nett Amount (S\$)	4,668.80	1,600.00	3,068.80	65.73
+ Loss of Use (5.0 x S\$20.00/day) (S		100.00		
Ne	tt Liability (S\$)	1,700.00		

INSPECTION

Date of Assignment: 06/07/2020

Date Inspected: 06/07/2020 Inspected At: Erofia Motor Trading Pte Ltd (KAKI

Global Sum Settlement (S\$)

BUKIT)

1,700.00

1 KAKI BUKIT AVE 6 #02-62

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT FORK ASSY	Serviceable	780.00 FL	*- FL	
2	1		*FRONT SPORT RIM	Not Necessary	350.00 FL	*- FL	
3	1		*FRONT BRAKE DISC	Not Necessary	180.00 FL	*- FL	
4	1		*FRONT RIM SHAFT	Not Necessary	52.00 FL	*- FL	
5	1		*HEADLAMP	Not Necessary	450.00 FL	*- FL	
6	1		*SET SIDE MIRROR	Cut	120.00 FL	*120.00 FL	
7	1		*HANDLE -BAR	Serviceable	125.00 FL	*- FL	
8	1		*SET HANDLE -BAR BALANCER	Not Necessary	80.00 FL	*- FL	
9	2		*FRONT SIGNALS	Not Necessary	170.00 FL	*- FL	
10	1		*SET FAIRING COVER	Cut	950.00 FL	*950.00 FL	
11	1		*DROVE BELT COVER	Cut	180.00 FL	*180.00 FL	
12	1		*AIR FILTER BOX COVER	Cut	150.00 FL	*150.00 FL	
13	1		*MAIN STAND	Repair	145.00 FL	*- FL	
14	1		*SIDE STAND	Repair	95.00 FL	*- FL	
15	1		*RIDER FOOT STEP -L/H	Serviceable	85.00 FL	*- FL	
16	1		*REAR FENDER	Deformed	110.00 FL	*110.00 FL	
17	1		*REAR LAMP	Scratched	160.00 FL	*160.00 FL	
18	1		*SET NUMBER PLATE	Rear Bent	28.00 FS	*10.00 FS	
19	2		*FORK OILS	Not Necessary	30.00 FS	*-FS	
20	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*-FS	
21	1		*REAR BOX BRACKET	Bent	120.00 FS	*120.00 FS	
22	1		*REAR BOX	Cut	160.00 FS	*160.00 FS	
F=Fra	anchise	part. S=SpcN	ett. L=ListItemDisc.				
			Land House Brown and Carlot	Sub Total (S\$)	4,576.00	1,960.00	
	- List Item Discount on L Items 10.00/10.00% (S\$)			418.20	167.00		
				Total Parts (S\$)	4,157.80	1,793.00	
	Report was unsubmitted during this print-out.						

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=g... 14/4/2021

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PROVIDE TOWING SERVICE	New	50.00	0.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	381.00	250.00
	Gross Labour Cost (S\$)		511.00	250.00
	Report was unsubmitted durin	na this print-out		

< END OF ESTIMATES >