



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 5676E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR LH (CONSISTENT)	TO REPAIR SEE LABOUR	2,847.60	-
1	FRONT DOOR LOCK ASSY (CONSISTENT)	NOT DAMAGED	328.40	-
1	FRONT DOOR LOCK STRIKER (CONSISTENT)	NOT DAMAGED	84.20	-
1	FRONT DOOR OUTER HANDLE W/SENSOR (CONSISTENT)	NOT DAMAGED	641.30	-
1	FRONT DOOR WEATHERSTRIP (CONSISTENT)	NOT DAMAGED	241.30	-
1	SIDE MIRROR ASSY LH (CONSISTENT)	CUT	2,361.60	1,589.00
	LESS 10% DISCOUNT		-650.44	-158.90
			5,853.96	1,430.10
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (CONSISTENT)(SN)	NOT NECESSARY	80.00	-
1	FRONT DOOR SEALANT (CONSISTENT)(SN)	NOT NECESSARY	80.00	-
1	FRONT DOOR TRIMBOARD CLIPS (CONSISTENT)(SN)	NECESSARY	50.00	30.00
			210.00	30.00
<u>LABOUR</u>				
	R&R FRONT DOOR COMPONENT.		150.00	80.00
	UPHOLSTERY.	NOT NECESSARY	200.00	-
	CHECK WIRING.		100.00	60.00
	PANEL BEAT.INCLUSIVE OF THE REPAIR OF FRONT DOOR LH.		800.00	400.00
	SPRAY PAINT.		800.00	400.00
	RUST PROOFING.	NOT NECESSARY	100.00	-
			2,150.00	940.00
GRAND TOTAL			8,213.96	2,400.10

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00
---	--	--	-----------------

Report Ref No. CC4/ASM20007025/Bps3q2

LIM TEOW GUAN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.