

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI20007026/KTF3E2

Date: 21/07/2020

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MH001900

**Claimant Vehicle No :** SHC5980C

**Insured Vehicle No :** SLJ7174R

Date of Loss: 02/07/2020

Nature of Claim: TP Claim No: M2003297

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5980C**

Make &amp; Model: RENAULT LATITUDE, 2.0 L (A)

Engine No: M9R8839C002651

Reg. Date: 23/03/2015 (Man. Year: 2015)

Chassis No: VF1ABL15AUC281511

Colour: Metallic White/Red

Odometer: 801487 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Giti 9 mm

Rear Left Side: Sailun 9 mm

Front Right Side: Giti 9 mm

Rear Right Side: Sailun 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	37,394.51	8,093.72	29,300.79	78.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,390.00	2,830.00	14,560.00	83.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>54,784.51</b>	<b>10,923.72</b>	<b>43,860.79</b>	<b>80.06</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,750.00</b>		
<b>(S\$)</b>	54,784.51	8,750.00	46,034.51	84.03
<b>+ GST 7.00/7.00% (S\$)</b>	3,834.92	612.50	3,222.42	84.03
<b>Nett Amount (S\$)</b>	<b>58,619.43</b>	<b>9,362.50</b>	<b>49,256.93</b>	<b>84.03</b>

### INSPECTION

Date of Assignment: 07/07/2020

Date Inspected: 06/07/2020 Inspected At:

Trans-Cab Auto Services Pte Ltd - Amk (HQ)

No 2 Ang Mo Kio St 63

Singapore 569111

Estimated Period of Repair: 8.0 days

---

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jul 2020)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC5980C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BUMPER COVER REAR	Bent	561.70 FL	-	*561.70 FL
2	1		*BUMPER LOWER REAR	Cracked	411.90 FL	-	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	-	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Distorted	82.10 FL	-	*82.10 FL
5	1		*BUMPER RETAINER RH REAR	Distorted	59.80 FL	-	*59.80 FL
6	1		*BUMPER REFLECTOR RH	Broken	16.60 FL	-	*16.60 FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	-	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	-	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	-	*- FL
10	1		*BUMPER BEAM REAR	Bent	547.80 FL	-	*547.80 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	-	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	100.90 FL	-	*- FL
13	1		*BUMPER BLOCK RH REAR	Serviceable	76.50 FL	-	*- FL
14	1		*BUMPER HARNESS REAR	Serviceable	301.10 FL	-	*- FL
15	1		*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	-	*745.80 FL
16	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	-	*- FL
17	1		*TAILLAMP RH	Cracked	401.40 FL	-	*401.40 FL
18	1		*TAILLAMP PANEL RH	Bent	401.40 FL	-	*401.40 FL
19	1		*TAILLAMP LH	Serviceable	401.40 FL	-	*- FL
20	1		*TAILLAMP PANEL LH	Repair	401.40 FL	-	*- FL
21	1		*BOOT REAR	Bent	1,677.20 FL	-	*1,677.20 FL
22	1		*BOOT FINISHER	Serviceable	344.70 FL	-	*- FL
23	1		*BOOT WEATHERSTRIP (\$178.20) (50%)	Distorted / Dented	160.38 FS	-	*89.10 FS
24	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	-	*- FL
25	1		*BOOT REFLECTOR LAMP RH	Cracked	277.70 FL	-	*277.70 FL
26	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	-	*82.40 FL
27	1		*BOOT BADGE	Necessary	95.80 FL	-	*95.80 FL
28	1		*BOOT STRUT LH	Serviceable	145.10 FL	-	*- FL
29	1		*BOOT INNER TRIM BOARD	Serviceable	611.00 FL	-	*- FL
30	1		*BOOT STRUT RH	Serviceable	145.10 FL	-	*- FL
31	1		*BOOT HINGE LH	Repair	254.20 FL	-	*- FL
32	1		*BOOT HINGE RH	Repair	253.80 FL	-	*- FL
33	1		*BOOT LOCK	Repair	246.60 FL	-	*- FL
34	2		*BOOT RUBBER PLUG	Serviceable	139.30 FL	-	*- FL
35	1		*EXHAUST REAR	Repair	5,263.60 FL	-	*- FL
36	1		*EXHAUST CAP REAR	Serviceable	125.40 FL	-	*- FL
37	1		*REAR RH FENDER PANEL	Buckled	1,933.20 FL	-	*1,933.20 FL
38	1		*WHEELARCH REAR RH	Serviceable	275.40 FL	-	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
39	1		*FENDER PANEL INNER TRIM REAR RH	Deformed	671.45 FL	-	*671.45 FL
40	1		*TRUNK CARPET	Serviceable	961.00 FL	-	*- FL
41	1		*TRUNK CARPET EXTENSION	Serviceable	412.80 FL	-	*- FL
42	1		*TRUNK CARPET SUPPORT	Serviceable	409.80 FL	-	*- FL
43	1		*SPARE WHEEL PANEL	Repair	1,229.40 FL	-	*- FL
44	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	-	*- FL
45	1		*SPARE TYRE BOARD	Serviceable	680.90 FL	-	*- FL
46	1		*SPARE WHEEL PANEL BRACKET RH	Repair	70.60 FL	-	*- FL
47	1		*CHASSIS PANEL REAR RH	Repair	2,192.40 FL	-	*- FL
48	1		*FENDER PANEL INNER REAR RH L70Y	Repair	1,241.60 FL	-	*- FL
49	1		*FENDER INNER BOARD RH L70Y	Serviceable	561.40 FL	-	*- FL
50	1		*FENDER WHEEL HOUSING PANEL REAR RH	Repair	4,682.09 FL	-	*- FL
51	1		*KNUCKLE ARM REAR RH L70Y	Serviceable	472.10 FL	-	*- FL
52	1		*LOWER ARM REAR RH L70Y	Serviceable	543.50 FL	-	*- FL
53	1		*AXLE SPRING ARM RH	Serviceable	220.60 FL	-	*- FL
54	1		*ABSORBER REAR RH	Serviceable	217.30 FL	-	*- FL
55	1		*KNUCKLE HUB + BEARING REAR RH	Serviceable	272.30 FL	-	*- FL
56	1		*SUBFRAME ARM REAR RH	Serviceable	198.33 FL	-	*- FL
57	1		*RODE - LONG REAR RH	Serviceable	120.16 FL	-	*- FL
58	1		*REAR AXLE	Serviceable	3,469.00 FL	-	*- FL
59	1		*SET PARKING AID	Shorted	700.00 FS	-	*400.00 FS
60	1		*SET REAR BUMPER CLIP	Necessary	75.00 FS	-	*75.00 FS
61	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	40.00 FS	-	*- FS
62	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	40.00 FS	-	*- FS
63	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	45.00 FS	-	*- FS
64	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	40.00 FS	-	*- FS
65	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	45.00 FS	-	*- FS
66	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	60.00 FS	-	*- FS
67	1		*SET BUMPER LOWER REAR CLIP	Necessary	75.00 FS	-	*75.00 FS
68	1		*BOOT STICKER TRANS-CAB	Necessary	80.00 FS	-	*30.00 FS
69	1		*BOOT STICKER 6555-3333	Necessary	80.00 FS	-	*30.00 FS
70	1		*SET BOOT FINISHER CLIP	Not Necessary	40.00 FS	-	*- FS
71	1		*TAILLAMP CLIP LH	Not Necessary	35.00 FS	-	*- FS
72	1		*TAILLAMP CLIP RH	Necessary	35.00 FS	-	*5.00 FS
73	1		*REAR BUMPER PROTECTOR	Not Necessary	150.00 FS	-	*- FS
74	1		*REAR LICENCE PLATE WITH HOLDER	Not Necessary	120.00 FS	-	*- FS
75	1		*EXHAUST MOUNTING REAR	Serviceable	45.00 FS	-	*- FS
76	1		*EXHAUST BRACKET REAR	Serviceable	45.00 FS	-	*- FS
77	1		*FENDER INNER TRIM CLIP RH	Not Necessary	45.00 FS	-	*- FS
78	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	50.00 FS	-	*- FS
79	2		*REAR WINDSCREEN SEALANT	Not Necessary	160.00 FS	-	*- FS
80	1		*WINDSCREEN MOULDING	Necessary	190.00 FS	-	*190.00 FS
81	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	130.00 FS	-	*30.00 FS
82	2		*SEAM SEALANT	Not Necessary	180.00 FS	-	*- FS
83	1		*REAR RENAULT TYRE	Not Necessary	330.00 FS	-	*- FS
84	1		*REAR RENAULT TYRE RIM	Not Necessary	380.00 FS	-	*- FS
85	1		*RENAULT TYRE RIM COVER	Not Necessary	65.00 FS	-	*- FS
86	1		*SPARE TYRE	Serviceable	330.00 FS	-	*- FS
87	1		*SPARE TYRE RIM	Serviceable	380.00 FS	-	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
88	1		*SET END PANEL TRIM CLIP	Not Necessary	45.00 FS	-	*- FS
89	1		*SET END PANEL INSULATION PAD / COVER	Not Necessary	200.00 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>41,061.08</b>	<b>8,890.35</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	3,666.57	796.63
<b>Total Parts (\$)</b>	<b>37,394.51</b>	<b>8,093.72</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
2	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	220.00	60.00
3	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
4	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
5	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
6	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	6,000.00	1,200.00
7	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	120.00
8	TO REPAIR AND REALIGN REAR EXHAUST PIPE (Repeated)	New	170.00	0.00
9	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
10	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
11	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
12	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
13	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	90.00
14	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
15	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	1,100.00
16	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	120.00
17	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	0.00
18	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
19	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
20	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING	New	380.00	0.00
21	TO DISMANTLE AND REFIT REAR AXLE ASSY, REMOVE AND RENEWAL OF PARTS, FINAL CHECKING AND TESTING	New	380.00	0.00
22	TO CHECK ABS AND BRAKE EFFICIENCY, FINAL CHECKING AND TESTING	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>17,390.00</b>	<b>2,830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >