

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20007027/ADA3Q2

**Date:** 26/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900094263

**Claimant**  
**Vehicle No :** SDS7388M **Insured Vehicle No :** SKT442Y

Date of Loss: 05/07/2020 Nature of Claim: TP Claim No: 5970827535SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDS7388M		
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Engine No:	CVN040770
Reg. Date:	14/08/2017 (Man. Year: 2017)	Chassis No:	WAUZZZF42HA178460
Colour:	Blue	Odometer:	31779 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,797.00	2,018.40	1,778.60	46.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,502.00	1,602.00	900.00	35.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>6,299.00</b>	<b>3,620.40</b>	<b>2,678.60</b>	<b>42.52</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	440.93	253.43	187.50	42.52
<b>Nett Amount (\$\$)</b>	<b>6,739.93</b>	<b>3,873.83</b>	<b>2,866.10</b>	<b>42.52</b>
<b>+ Car Rental (3.0 x S\$100.00/day) (\$\$)</b>		300.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>4,175.83</b>		

### INSPECTION

Date of Assignment: 08/07/2020

Date Inspected: 08/07/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,079.00 FS	*1,663.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	69.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Necessary	210.00 FS	*168.00 FS
4	1		*REAR BUMPER SPOILER	Deformed	234.00 FS	*187.20 FS
5	2		*REAR LIGHT REFLECTOR - LH / RH	Not Necessary	78.00 FS	*- FS
6	1		*REAR BUMPER CARRIER	Not Necessary	845.00 FS	*- FS
7	2		*REAR BUMPER CARRIER SEAL	Not Necessary	26.00 FS	*- FS
8	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	42.00 FS	*- FS
9	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
10	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
11	2		*REAR PARKING AID SENSOR - INNER / OUTER (NPA)	Not Necessary	0.00 F	*- F
					<b>Total Parts (S\$)</b>	<b>3,797.00      2,018.40</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,502.00</b>	<b>1,602.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >