

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG19013011/R1DS3Q2

**Date:** 28/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994139

**Claimant**  
**Vehicle No :** SLZ3780H **Insured Vehicle No :** SLV2359U

Date of Loss: 22/07/2019 Nature of Claim: TP Claim No: 2840763111SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ3780H	Engine No:	F153H712B38B15A
Make & Model:	BMW X1, 1.5 SDRIVE 18i (A)	Chassis No:	WBAJG12060EG21698
Reg. Date:	30/04/2018 (Man. Year: 2018)	Odometer:	34670 km
Colour:	Black		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	923.80	923.80	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,951.00	5,730.00	1,221.00	17.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>7,874.80</b>	<b>6,653.80</b>	<b>1,221.00</b>	<b>15.51</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	551.24	465.77	85.47	15.51
<b>Nett Amount (\$\$)</b>	<b>8,426.04</b>	<b>7,119.57</b>	<b>1,306.47</b>	<b>15.51</b>
<b>+ Loss of Use (5.0 x S\$80.00/day) (\$\$)</b>		400.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>7,527.02</b>		

### INSPECTION

Date of Assignment: 06/07/2020

Date Inspected: 06/07/2020 Inspected At:

Performance Motors Limited  
(Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*FRT LH SIDE PANEL	Bent	664.00 FS	*664.00 FS
3	1		*FRT LH WHEEL ARCH TRIM	Scratched	151.80 FS	*151.80 FS
4	20		*EXPANDING RIVER BLACK	Necessary	28.00 FS	*28.00 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (S\$)</b>					<b>923.80</b>	<b>923.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REPLACE LEFT FRONT FENDER AND REMOVE AND INSTALL FRONT BUMPER ,RIGHT FRONT DOOR AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT	New	3,400.00	2,550.00
2	PAINTING FRONT BUMPER ,LEFT FRONT FENDER ,LEFT FRONT DOOR	New	3,256.00	2,930.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS	New	177.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,951.00</b>	<b>5,730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >