

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20007038/DQF3Q2

Date: 01/02/2021

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No: MS011794
Claimant	
Vehicle No : SHD6757U	Insured Vehicle No : GBK61S
Date of Loss: 03/07/2020	Nature of Claim: TP Claim No: M2003329

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD6757U	Engine No: D4FDEU495790
Make & Model: HYUNDAI I40, 1.7 L (A)	Chassis No: KMHLB41UMFU068141
Reg. Date: 23/04/2015 (Man. Year: 2015)	Odometer: 583498 km
Colour: Blue	
Engine Capacity: 1685 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16	Rear Tyre Size: 205/60R16
Front Left Side: Hankook 5 mm	Rear Left Side: Hankook 5 mm
Front Right Side: Hankook 5 mm	Rear Right Side: Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,485.32	7,199.88	20,285.44	73.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,460.00	1,530.00	4,930.00	76.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,945.32	8,729.88	25,215.44	74.28
Approved Total (Overridden) (S\$)		6,900.00		
(S\$)	33,945.32	6,900.00	27,045.32	79.67
+ GST 7.00/7.00% (S\$)	2,376.17	483.00	1,893.17	79.67
Nett Amount (S\$)	36,321.49	7,383.00	28,938.49	79.67

INSPECTION

Date of Assignment:	07/07/2020	
Date Inspected:	07/07/2020 Inspected At:	Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate Singapore 575644
Estimated Period of Repair:	7.0 days	

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Feb 2021)
Parts:	143	HYUNDAI I40 1.7 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD6757U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*ROCKER PANEL OUTER GARNISH LH	Not Necessary	732.80 FL	-	*- FL
2	1		*BONNET	Bent	2,265.90 FL	-	*2,265.90 FL
3	1		*BONNET RUBBER LH	Not Necessary	35.70 FL	-	*- FL
4	1		*BONNET RUBBER RH	Not Necessary	35.70 FL	-	*- FL
5	2		*BONNET HINGE LH/RH	Not Necessary	253.40 FL	-	*- FL
6	1		*BONNET LOCK	Not Necessary	142.40 FL	-	*- FL
7	1		*BONNET ABSORBER (LH ONLY)	Not Necessary	61.60 FL	-	*- FL
8	1		*BONNET INSULATOR	Not Necessary	202.50 FL	-	*- FL
9	1		*BONNET SEAL	Not Necessary	31.90 FL	-	*- FL
10	1		*BONNET INSULATOR CLIPS	Not Necessary	15.00 FL	-	*- FL
11	1		*RADIATOR GRILLE H EMBLEM	Not Necessary	129.50 FL	-	*- FL
12	1		*RADIATOR GRILLE	Not Necessary	1,480.00 FL	-	*- FL
13	1		*FRONT BUMPER COVER	Cut/Mounting Broken	1,052.20 FL	-	*1,052.20 FL
14	1		*FRONT BUMPER GRILLE LH	Cut	149.20 FL	-	*149.20 FL
15	2		*FRONT BUMPER BRACKET TOP LH/RH	Not Necessary	89.60 FL	-	*- FL
16	2		*FRONT BUMPER BRACKET LH/RH	Serviceable	98.40 FL	-	*- FL
17	1		*FRONT BUMPER RETAINER MOUNTING	Not Necessary	76.20 FL	-	*- FL
18	1		*FRONT BUMPER GRILLE AIR DUCT LH	Not Necessary	126.20 FL	-	*- FL
19	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	-	*907.40 FL
20	1		*HEADLAMP LH	Mounting Broken	2,776.00 FL	-	*1,388.00 FL
21	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	-	*- FL
22	1		*RADIATOR	Not Necessary	1,637.20 FL	-	*- FL
23	1		*RADIATOR GUARD LH	Not Necessary	76.50 FL	-	*- FL
24	1		*COOLANT	Not Necessary	45.00 FL	-	*- FL
25	1		*RADIATOR FAN BLADE,COWLING,MOTOR ASSY	Not Necessary	1,194.20 FL	-	*- FL
26	1		*FRONT FENDER LH	Not Necessary	566.30 FL	-	*- FL
27	1		*FRONT FENDER APRON PANEL LH	Dented	637.00 FL	-	*637.00 FL
28	1		*FRONT FENDER SHIELD LH	Serviceable	174.90 FL	-	*- FL
29	1		*AIRCON CONDENSER	Not Necessary	947.80 FL	-	*- FL
30	1		*FRONT DOOR MIRROR SIDE GARNISH	Not Necessary	225.00 FL	-	*- FL
31	1		*FRONT DOOR MIRROR LH	Not Necessary	670.00 FL	-	*- FL
32	1		*FRONT DOOR LH	Dented	2,256.40 FL	-	*2,256.40 FL
33	1		*FRONT DOOR RUBBER	Not Necessary	196.00 FL	-	*- FL
34	1		*FRONT DOOR HINGE UPPER LH	Not Necessary	113.60 FL	-	*- FL
35	1		*FRONT DOOR HINGE LOWER LH	Not Necessary	125.70 FL	-	*- FL
36	1		*FRONT DOOR CHECK LH	Not Necessary	91.80 FL	-	*- FL
37	1		*FRONT WHEEL RIM LH	Not Necessary	650.60 FL	-	*- FL
38	1		*KNUCKLE ARM LH	Not Necessary	595.90 FL	-	*- FL
39	1			Not Necessary	673.20 FL	-	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
			*FRONT WHEEL BEARING HUB ASSY LH				
40	1		*FRONT SUSPENSION LOWER ARM LH	Not Necessary	1,104.00 FL	-	*- FL
41	1		*FRONT SHOCK ABSORBER ASSY LH	Not Necessary	684.40 FL	-	*- FL
42	1		*FRONT SHOCK ABSORBER MOUNTING LH	Not Necessary	217.60 FL	-	*- FL
43	1		*STG TIE ROD LH	Not Necessary	186.40 FL	-	*- FL
44	1		*STG TIE END LH	Not Necessary	125.20 FL	-	*- FL
45	1		*STABILIZER BAR ASSY	Not Necessary	463.70 FL	-	*- FL
46	1		*STABILIZER BAR LINK LH	Not Necessary	68.10 FL	-	*- FL
47	1		*ABS SENSOR	Not Necessary	217.90 FL	-	*- FL
48	1		*FRONT DRIVE SHAFT LH	Not Necessary	2,061.60 FL	-	*- FL
49	1		*RACK & PINION ASSY	Not Necessary	1,820.00 FL	-	*- FL
50	1		*INTER COOLER	Not Necessary	1,032.50 FL	-	*- FL
51	1		*HOSE B TO INTER COOLER	Not Necessary	229.70 FL	-	*- FL
52	1		*HOSE C TO INTER COOLER INLET	Not Necessary	294.50 FL	-	*- FL
53	1		*WIRING-ENGINE W/FUSE BOX	Not Necessary	3,326.00 FL	-	*- FL
54	1		*ROCKER PANEL ADVERTISEMENT LH	Serviceable	120.00 FS	-	*- FS
55	1		*FRONT FENDER ADVERTISEMENT LOGO	Necessary	100.00 FS	-	*100.00 FS
56	1		*FRONT DOOR COLOURED COMFORT LOGO	Necessary	75.00 FS	-	*75.00 FS
57	1		*FRONT DOOR ADVERTISEMENT LOGO	Necessary	100.00 FS	-	*100.00 FS
58	1		*FRONT TYRE (LH)	Serviceable	216.00 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 34,203.90 8,931.10
- List Item Discount on L Items 20.00/20.00% (\$\$) 6,718.58 1,731.22

Total Parts (\$\$) 27,485.32 7,199.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,600.00	700.00
2	SPRAY PAINTING CHARGE	New	1,400.00	700.00
3	WIRING CHARGE	New	160.00	30.00
4	TUFF KOTE	New	160.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
7	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
8	FOUR WHEEL ALIGNMENT	New	120.00	0.00
9	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	0.00
10	RE-SET FRT ABS SYSTEM	New	200.00	0.00
11	REMOVE/REFIX RADIATOR	New	90.00	0.00
12	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	0.00
13	REMOVE/REFIX FUSE BOX	New	120.00	0.00
14	REMOVE/REFIX ENGINE	New	600.00	0.00
15	REMOVE/REFIX DASHBOARD	New	350.00	0.00
16	FRONT CHASSIS ALIGNMENT CHARGE	New	220.00	0.00
17	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (\$\$)			6,460.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >