

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20007041/DSF3E2
Date: 04/01/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29141713MKF
Claimant Vehicle No : SHC2375U **Insured Vehicle No :** SLK1295J
Date of Loss: 04/07/2020 Nature of Claim: TP Claim No: 625671

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC2375U**
Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEKU409555
Reg. Date: 19/12/2019 (Man. Year: 2019) Chassis No: KMHC851CVLU190055
Colour: Blue Odometer: 58925 km
Engine Capacity: 1580 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,545.31	11,236.92	13,308.39	54.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,660.00	1,920.00	3,740.00	66.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	30,205.31	13,156.92	17,048.39	56.44
+ GST 7.00/7.00% (S\$)	2,114.37	920.98	1,193.39	56.44
Nett Amount (S\$)	32,319.68	14,077.90	18,241.78	56.44

INSPECTION

Date of Assignment: 07/07/2020
Date Inspected: 07/07/2020 Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ)
Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
Singapore 575644
Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2021)
Parts: 192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC2375U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	2,253.80 FL	*- FL
2	1		*BONNET HINGE RH	Not Necessary	118.70 FL	*- FL
3	1		*BONNET INSULATOR CLIPS	Not Necessary	15.00 FL	*- FL
4	1		*RADIATOR GRILLE NEW MODEL	Not Necessary	1,568.60 FL	*- FL
5	1		*FLAP ASSY ACTIVE AIR UPPER,RH	Not Necessary	824.60 FL	*- FL
6	1		*FRONT BUMPER COVER	Torn	418.30 FL	*418.30 FL
7	1		*FRONT BUMPER MOULDING CENTRE UPPER	Cut	368.50 FL	*368.50 FL
8	1		*FRONT BUMPER BRACKET TOP RH	Not Necessary	35.00 FL	*- FL
9	1		*FRONT BUMPER BRACKET RH	Serviceable	28.00 FL	*- FL
10	1		*FRONT BUMPER RETAINER MOUNTING RH	Serviceable	65.30 FL	*- FL
11	10		*FRONT BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
12	1		*FRONT BUMPER GRILLE RH	Dislodged	186.90 FL	*186.90 FL
13	1		*FRONT BUMPER AIR DUCT RH	Not Necessary	153.80 FL	*- FL
14	1		*DAY LIGHT,RH	Mounting Broken	642.50 FL	*642.50 FL
15	1		*DAY LIGHT WIRE,RH	Not Necessary	585.50 FL	*- FL
16	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	949.30 FL	*949.30 FL
17	1		*HEADLAMP RH	Mounting Broken	3,987.30 FL	*1,198.80 FL
18	1		*RADIATOR INVERTER	Not Necessary	884.80 FL	*- FL
19	1		*RADIATOR	Not Necessary	710.50 FL	*- FL
20	1		*COOLANT	Not Necessary	45.00 FL	*- FL
21	1		*RADIATOR FAN BLOWER MOTOR ASSY	Not Necessary	1,226.60 FL	*- FL
22	1		*RADIATOR AIR GUARD RH	Not Necessary	76.40 FL	*- FL
23	1		*FRT PILLAR UPPER COVER-OUTER RH	Not Necessary	89.60 FL	*- FL
24	1		*FRONT FENDER RH	Buckled	490.70 FL	*490.70 FL
25	1		*FRONT FENDER APRON PANEL RH	Not Necessary	756.20 FL	*- FL
26	1		*FRONT FENDER APRON PANEL UPPER RH	Not Necessary	229.60 FL	*- FL
27	1		*FRONT FENDER SHIELD RH	Deformed	164.70 FL	*164.70 FL
28	1		*AIRCON CONDENSER	Not Necessary	663.60 FL	*- FL
29	1		*FRT DOOR RH	Bent/Dented	1,797.20 FL	*1,797.20 FL
30	1		*FRT DOOR RUBBER	Not Necessary	250.00 FL	*- FL
31	1		*FRONT DOOR HINGE UPPER RH	Not Necessary	165.76 FL	*- FL
32	1		*FRONT DOOR HINGE LOWER RH	Not Necessary	153.70 FL	*- FL
33	1		*FRONT DOOR CHECK RH	Not Necessary	72.98 FL	*- FL
34	1		*SPEAKER	Not Necessary	256.10 FL	*- FL
35	1		*FRONT WHEEL RIM RH	Distorted	1,124.20 FL	*1,124.20 FL
36	1		*FRONT WHEEL HUB CAP AND HUB ASSY RH	Cut	678.50 FL	*678.50 FL
37	1		*FRONT SHOCK ABSORBER (ASSY)(RH)	Bent	372.50 FL	*372.50 FL
38	1		*FRONT SHOCK ABSORBER MOUNTING (RH)	Not Necessary	206.90 FL	*- FL
39	1		*FRONT DRIVE SHAFT RH	Distorted	1,136.70 FL	*1,136.70 FL
40	1		*FRONT DRIVE SHAFT EXTENSION RH	Not Necessary	1,125.80 FL	*- FL
41	1		*RACK & PINION ASSY	Damaged	1,087.40 FL	*1,087.40 FL
42	1		*STG TIE ROD	Distorted	125.60 FL	*125.60 FL
43	1		*STG TIE END	Distorted	94.70 FL	*94.70 FL
44	1		*STABILIZER BAR	Not Necessary	326.80 FL	*- FL
45	1		*STABILIZER BAR LINK	Not Necessary	92.10 FL	*- FL
46	1		*FRONT SUSPENSION LOWER ARM RH	Distorted	596.80 FL	*596.80 FL
47	1		*KNUCKLE ARM RH	Distorted	663.60 FL	*663.60 FL
48	1		*ABS SENSOR	Not Necessary	290.00 FL	*- FL
49	1		*BRAKE HOSE RH	Not Necessary	234.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*INVERTER COOLANT	Not Necessary	65.00 FL	*- FL
51	1		*ENGINE CROSSMEMBER	Distorted	1,803.90 FL	*1,803.90 FL
52	1		*EMBLEM-BLUE DRIVE RH	Necessary	26.60 F	*26.60 FN
53	1		*FRONT DOOR COMFORT LOGO RH	Necessary	75.00 FS	*75.00 FS
54	1		*FRONT TYRE RH	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$)	30,602.24	14,027.40
- List Item Discount on L Items 20.00/20.00% (\$)	6,056.93	2,785.16
- Nett Item Discount on N Items 0.00/20.00% (\$)	0.00	5.32
Total Parts (\$)	24,545.31	11,236.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	700.00
2	SPRAY PAINTING CHARGE	New	1,200.00	700.00
3	WIRING CHARGE	New	120.00	30.00
4	TUFF KOTE	New	120.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
7	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
8	FOUR WHEEL ALIGNMENT	New	120.00	60.00
9	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	150.00
10	RE-SET FRT ABS SYSTEM	New	200.00	0.00
11	REMOVE/REFIX RADIATOR	New	90.00	0.00
12	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	0.00
13	REMOVE/REFIX ENGINE	New	600.00	0.00
14	FRONT CHASSIS ALIGNMENT CHARGE	New	220.00	0.00
15	REMOVE/REFIX STEERING RACK/WHEEL/DR SHAFT	New	150.00	0.00
16	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	180.00
			Gross Labour Cost (\$\$)	5,660.00
				1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >