

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Jul 2020 Edit Reg		07 Jul 2020 00:00 Edit Adj Rpt	S\$11,000.00 Edit Estimates	S\$11,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LEE ENG HIOCK, ID: S2667861G								
Main Claimant:	NATIONAL CAR RENTALS PTE LTD								
Vehicle Reg. No.:	SKQ3306D	Date of Loss:	03/07/2020 00:00 - :59 [67 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1131366343SG	Policy/Cover Note No.:	1900101585 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJQ641S	Policy No. (Claimant):							
		Excess:							
Repairer:	S Three Automotive Recovery Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate, #01-64/66 Sector C, 575643 Sin Ming - Tel: 62841542 / 62841575								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 16/07/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS ☐ View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKQ3306D (1131366343SG)**
[SJQ641S]
TP
NATIONAL CAR RENTALS PTE LTD
Jul 3 2020 12:00AM
[LEE ENG HIOCK]
S Three Automotive Recovery Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser		
Photos/Images			3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/07/20 16:30	Reinspection Photo		Load JPG	
2	08/07/20 16:30	Reinspection Photo		Load JPG	
3	08/07/20 16:30	Reinspection Photo		Load JPG	
4	08/07/20 16:30	Reinspection Photo		Load JPG	
5	08/07/20 16:30	Reinspection Photo		Load JPG	
6	08/07/20 16:30	Reinspection Photo		Load JPG	
7	08/07/20 16:30	Reinspection Photo		Load JPG	
8	08/07/20 16:30	Reinspection Photo		Load JPG	
9	08/07/20 16:30	Reinspection Photo		Load JPG	
10	08/07/20 16:30	Reinspection Photo		Load JPG	
11	08/07/20 16:30	Reinspection Photo		Load JPG	
12	08/07/20 16:30	Reinspection Photo		Load JPG	
13	08/07/20 16:30	Reinspection Photo		Load JPG	
14	08/07/20 16:30	Reinspection Photo		Load JPG	
15	08/07/20 16:30	Reinspection Photo		Load JPG	
16	08/07/20 16:30	Reinspection Photo		Load JPG	
17	08/07/20 16:30	Reinspection Photo		Load JPG	
18	08/07/20 16:30	Reinspection Photo		Load JPG	
19	08/07/20 16:30	Reinspection Photo		Load JPG	
20	08/07/20 16:30	Reinspection Photo		Load JPG	
21	08/07/20 16:30	Reinspection Photo		Load JPG	
22	08/07/20 16:30	Reinspection Photo		Load JPG	
23	27/08/20 18:05	General View		Load JPG	
24	27/08/20 18:05	General View		Load JPG	
25	27/08/20 18:05	General View		Load JPG	
26	27/08/20 18:05	General View		Load JPG	
27	27/08/20 18:05	General View		Load JPG	
28	27/08/20 18:05	General View		Load JPG	
29	27/08/20 18:05	General View		Load JPG	
30	27/08/20 18:05	General View		Load JPG	
31	27/08/20 18:05	General View		Load JPG	
32	27/08/20 18:05	General View		Load JPG	
33	27/08/20 18:05	General View		Load JPG	
34	27/08/20 18:05	General View		Load JPG	
35	27/08/20 18:05	General View		Load JPG	
36	27/08/20 18:05	General View		Load JPG	
37	27/08/20 18:05	General View		Load JPG	
38	27/08/20 18:05	General View		Load JPG	
39	27/08/20 18:05	General View		Load JPG	
40	27/08/20 18:05	General View		Load JPG	

Photos/Images

3 per page

☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
41	27/08/20 18:05	General View		Load JPG	☒
42	27/08/20 18:06	General View		Load JPG	☒
43	27/08/20 18:06	General View		Load JPG	☒
44	27/08/20 18:06	General View		Load JPG	☒
45	27/08/20 18:06	General View		Load JPG	☒
46	27/08/20 18:06	General View		Load JPG	☒
47	27/08/20 18:06	General View		Load JPG	☒
48	27/08/20 18:06	General View		Load JPG	☒
49	27/08/20 18:06	General View		Load JPG	☒
50	27/08/20 18:06	General View		Load JPG	☒
51	27/08/20 18:06	General View		Load JPG	☒
52	27/08/20 18:06	General View		Load JPG	☒
53	27/08/20 18:06	General View		Load JPG	☒
54	27/08/20 18:06	General View		Load JPG	☒
55	27/08/20 18:06	General View		Load JPG	☒
56	27/08/20 18:06	General View		Load JPG	☒
57	27/08/20 18:06	General View		Load JPG	☒
58	27/08/20 18:06	General View		Load JPG	☒
59	27/08/20 18:06	General View		Load JPG	☒
60	27/08/20 18:06	General View		Load JPG	☒

Documentation

1 per page

☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/07/20 17:38	ACKNOWLEDGEMENT EMAIL TO AIG DD07072020		Load PDF	
2	07/07/20 17:38	EMAIL FROM AIG DD07072020		Load PDF	
3	08/07/20 12:00	TP GIA REPORT		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	15/07/20 08:57	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20007050/KKS3S2**Date:** 03/09/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900101585
Claimant Vehicle No :	SKQ3306D	Insured Vehicle No :	SJQ641S
Date of Loss:	03/07/2020	Nature of Claim:	TP
		Claim No:	1131366343SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ3306D	Engine No:	PE20535360
Make & Model:	MAZDA CX-5 5-DOOR WAGON, 2.0 L SP.6EAT (A)	Chassis No:	JM6KE1071F0262278
Reg. Date:	21/11/2014 (Man. Year: 2014)	Odometer:	73814 km
Colour:	Metallic Grey		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/65 R17	Rear Tyre Size:	225/65 R17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,702.08	14,511.72	10,190.36	41.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,010.00	2,810.00	5,200.00	64.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,712.08	17,321.72	15,390.36	47.05
Approved Total (Overridden) (S\$)		11,000.00		
Nett Amount (S\$)	32,712.08	11,000.00	21,712.08	66.37

INSPECTION

Date of Assignment:	07/07/2020	S Three Automotive Recovery Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate, #01-64/66 Sector C Singapore 575643
Date Inspected:	07/07/2020 Inspected At:	
Estimated Period of Repair:	9.0 days	

Adjuster: KENNETH KONG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	975.00 FL	*975.00 FL
2	1		*FRONT BUMPER FOG LAMP RH	Serviceable	352.00 FL	*- FL
3	1		*FRONT BUMPER FOG LAMP LH	Serviceable	352.00 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP COVER RH	Serviceable	82.40 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP COVER LH	Serviceable	82.40 FL	*- FL
6	1		*FRONT BUMPER RETAINER RH	Distorted	60.00 FL	*60.00 FL
7	1		*FRONT BUMPER RETAINER LH	Distorted	60.00 FL	*60.00 FL
8	1		*FRONT BUMPER BRACKET RH	Repair	60.00 FL	*- FL
9	1		*FRONT BUMPER BRACKET LH	Repair	60.00 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Bent	584.80 FL	*524.40 FL
11	1		*FRONT BUMPER SPONGE	Cracked	94.30 FL	*94.30 FL
12	1		*FRONT BONNET	Bent	1,170.00 FL	*1,170.00 FL
13	1		*FRONT BONNET LOCK	Repair	224.00 FL	*- FL
14	1		*FRONT BONNET SEAL INNER	Necessary	78.00 FL	*78.00 FL
15	1		*FRONT BONNET SEAL OUTER	Necessary	28.00 FL	*28.00 FL
16	1		*FRONT BONNET RUBBER	Serviceable	108.00 FL	*- FL
17	1		*FRONT BONNET HINGE RH	Repair	48.00 FL	*- FL
18	1		*FRONT BONNET HINGE LH	Repair	48.00 FL	*- FL
19	1		*FRONT GRILLE	Mtg Cracked	682.80 FL	*682.80 FL
20	1		*FRONT GRILLE CHROME	Cracked	288.80 FL	*288.80 FL
21	1		*FRONT GRILLE LOGO	Necessary	68.00 FL	*68.00 FL
22	1		*FRONT FENDER PROTECTOR RH	Serviceable	178.00 FL	*- FL
23	1		*FRONT FENDER PROTECTION LH	Serviceable	178.00 FL	*- FL
24	1		*FRONT HEADLAMP RH	Mtg Cracked	995.00 FL	*995.00 FL
25	1		*FRONT HEADLAMP LH	Mtg Cracked	995.00 FL	*995.00 FL
26	1		*REAR BUMPER	Buckled	1,281.00 FL	*1,218.00 FL
27	1		*REAR BUMPER TOWING LH	Missing	96.00 FL	*96.00 FL
28	1		*REAR BUMPER TOWING RH	Missing	96.00 FL	*96.00 FL
29	1		*REAR BUMPER LOWER REFLECTOR LH	Cracked	186.00 FL	*186.00 FL
30	1		*REAR BUMPER LOWER REFLECTOR RH	Serviceable	186.00 FL	*- FL
31	1		*REAR BUMPER REINFORCEMENT	Bent	543.00 FL	*543.00 FL
32	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Repair	80.00 FL	*- FL
33	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Repair	80.00 FL	*- FL
34	1		*REAR BUMPER BRACKET LH	Repair	116.00 FL	*- FL
35	1		*REAR BUMPER BRACKET RH	Repair	116.00 FL	*- FL
36	1		*REAR BUMPER LOWER COVER LH	Serviceable	220.00 FL	*- FL
37	1		*REAR BUMPER LOWER COVER RH	Serviceable	220.00 FL	*- FL
38	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	108.00 FL	*- FL
39	1		*REAR BUMPER SIDE RETAINER LH	Distorted	108.00 FL	*108.00 FL
40	1		*REAR FENDER PROTECTOR	Distorted	375.00 FL	*375.00 FL
41	1		*REAR FENDER PROTECTOR RH	Serviceable	375.00 FL	*- FL
42	1		*REAR END PANEL	Bent	519.00 FL	*476.10 FL
43	1		*REAR END PANEL INNER TRIM	Serviceable	134.00 FL	*- FL
44	1		*TAILGATE	Bent	1,448.00 FL	*1,448.00 FL
45	1		*TAILGATE CATCH	Repair	45.60 FL	*- FL
46	1		*TAILGATE INNER HANDLE	Missing	105.00 FL	*105.00 FL
47	1		*TAILGATE OUTER HANDLE	Serviceable	105.00 FL	*- FL
48	1		*TAILGATE RUBBER BEADING	Serviceable	285.60 FL	*- FL
49	1		*TAILGATE INNER TRIM	Mtg Cracked	750.00 FL	*750.00 FL
50	1		*TAILGATE LAMP LH	Serviceable	495.00 FL	*- FL
51	1		*TAILGATE LAMP RH	Serviceable	495.00 FL	*- FL
52	1		*TAILGATE LOCK	Dented	250.80 FL	*250.80 FL
53	1		*TAILGATE EMBLEM CX5	Necessary	42.00 FL	*42.00 FL
54	1		*TAILGATE EMBLEM SKYACITY	Necessary	72.60 FL	*72.60 FL
55	1		*TAILGATE LOGO	Necessary	43.60 FL	*43.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*TAILGATE DAMPER LH	Serviceable	244.00 FL	*- FL
57	1		*TAILGATE DAMPER RH	Serviceable	244.00 FL	*- FL
58	1		*TAILLAMP LH	Serviceable	520.00 FL	*- FL
59	1		*TAILLAMP RH	Serviceable	520.00 FL	*- FL
60	1		*REAR NO PLATE LAMP	Serviceable	42.00 FL	*- FL
61	1		*REAR EXHAUST MUFFLER	Bent	1,551.00 FL	*1,551.00 FL
62	2		*REAR EXHAUST CHROME	Dented	640.00 FL	*640.00 FL
63	1		*REAR EXHAUST CENTRE	Repair	1,780.00 FL	*- FL
64	1		*REAR EXHAUST HEAT SHIELD	Repair	269.90 FL	*- FL
65	4		*REAR EXHAUST PIPE MOUNTING	Distorted	280.00 FL	*280.00 FL
66	4		*REVERSE SENSOR	Cracked 2pcs Only	1,120.00 FL	*560.00 FL
67	1		*REAR AXLE	Bent	2,898.00 FL	*2,898.00 FL
68	1		*RADIATOR	Serviceable	1,012.00 FL	*- FL
69	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
70	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
71	1		*FRONT BONNET INSULATOR CLIPS	Not Necessary	80.00 FS	*- FS
72	1		*FRONT GRILLE TOP COVER CLIPS	Not Necessary	80.00 FS	*- FS
73	1		*FRONT NO PLATE	Bent	50.00 FS	*45.00 FS
74	1		*REAR NO PLATE	Serviceable	50.00 FS	*- FS
75	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*80.00 FS
76	1		*REAR FENDER PROTECTOR CLIPS	Necessary	100.00 FS	*100.00 FS
77	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*30.00 FS
78	1		*REAR EXHAUST MUFFLER MOULDING	Serviceable	100.00 FS	*- FS
79	1		*REVERSE CAMERA	Serviceable	680.00 FS	*- FS
80	1		*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
81	1		*AIR CON CONDENSER	Serviceable	1,077.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	30,507.60	18,063.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,805.52	3,551.68
Total Parts (\$\$)	24,702.08	14,511.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREA - FRONT.	New	1,400.00	500.00
2	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREA - REAR	New	1,600.00	700.00
3	SPRAY PAINTING ON ACCIDENT AREA - FRONT.	New	1,400.00	400.00
4	SPRAY PAINTING ACCIDENT AREA - REAR.	New	1,400.00	800.00
5	RESPRAY TUFF KOTE ON AFFECTED AREA - FRONT.	New	180.00	30.00
6	RESPRAY TUFF KOTE ON AFFECTED AREA - REAR.	New	180.00	60.00
7	CHECK HEADLAMP WIRING SYSTEM.	New	180.00	20.00
8	CONDUCT FULL WHEEL ALIGNMENT.	New	120.00	60.00
9	BALANCING TYRES.	New	80.00	0.00
10	DIAGNOSE, PROGRAME AND RESET ENGINE LIGHT SYSTEM.	New	380.00	0.00
11	R&R AIR CON CONDENSER & TOP UP AIR CON GAS R134.	New	180.00	0.00
12	R&R BOOT INNER TRIM & CARPET TO REPAIR.	New	120.00	60.00
13	CHECK TAILLAMP WIRING SYSTEM.	New	180.00	20.00
14	R&R EXHAUST MUFFLER PIPE.	New	280.00	100.00
15	R&R REVERSE SENSOR & CAMERA SYSTEM.	New	180.00	60.00
16	R&R TAILGATE COMPARTMENT AND RESET SYSTEM.	New	150.00	0.00
Gross Labour Cost (\$\$)			8,010.00	2,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >